

HAZARDOUS MATERIALS ASSESSMENT

WRANGELL MEDICAL CENTER EVALUATION

WRANGELL, ALASKA

Surveyed
September 15, 17, 18, 2020

Report Date
February 9, 2021

EHS, ALASKA, INC.
ENGINEERING, HEALTH & SAFETY CONSULTANTS
11901 BUSINESS BLVD., SUITE 208
EAGLE RIVER, ALASKA 99577-7701

**HAZARDOUS MATERIALS ASSESSMENT
WRANGELL MEDICAL CENTER EVALUATION**

WRANGELL, ALASKA

TABLE OF CONTENTS

	PAGE NO.
OVERVIEW	3
A. GENERALIZED REQUIREMENTS FOR HAZARDOUS MATERIALS	3
B. BUILDING DESCRIPTION	4
C. SAMPLING AND ANALYSIS	5
1. Asbestos-Containing Materials	5
2. Lead-Containing Materials	6
D. SURVEY RESULTS	6
1. Asbestos-Containing Materials	6
2. Asbestos in Dusts	19
3. Lead-Containing Materials	19
4. PCB-Containing Materials	20
5. Mercury-Containing Materials	20
6. Other Hazardous Materials	21
E. REGULATORY CONSTRAINTS	21
1. Asbestos-Containing Materials	21
2. Dusts with Asbestos	22
3. Lead-Containing Materials	22
4. PCB-Containing Materials	23
5. Mercury-Containing Materials	23
6. Other Hazardous Materials	23
F. RECOMMENDATIONS	24
1. Asbestos-Containing Materials	24
2. Dusts with Asbestos	24
3. Lead-Containing Materials	25
4. PCB-Containing Materials	25
5. Mercury-Containing Materials	25
6. Other Hazardous Materials	25
G. LIMITATIONS	25
1. Accuracy of Information	26
2. Site Conditions	26
3. Changing Regulatory Constraints	26
APPENDICES	
Appendix A	Asbestos Bulk Field Survey Data Sheets and Lab Reports
Appendix B	Lead Analyzer Test Results
Appendix C	Drawings of Sample Locations

HAZARDOUS MATERIALS ASSESSMENT WRANGELL MEDICAL CENTER EVALUATION

WRANGELL, ALASKA

OVERVIEW

The Wrangell Medical Center, located in Wrangell, Alaska, was surveyed for the presence of asbestos-containing materials (ACM), and other potentially hazardous materials as a part of the design services for the Wrangell Medical Center Evaluation Project for the Wrangell Facilities Department. The survey also provided a “good faith” inspection for hazardous materials that may be disturbed during renovation, construction, or demolition. The proposed work will likely include the disturbance, demolition, removal and disposal of lead-containing paints and/or lead-containing materials that is incidental to the renovation, remodeling or demolition project. Mr. Brandon W. Hill, and Mr. Robert A. French, P.E. of EHS-Alaska, Inc. (EHS-Alaska) conducted the inspections in September 2020. It will be the contractor’s responsibility to take this baseline data, and to conduct hazardous materials removal in compliance with all regulatory requirements.

A. GENERALIZED REQUIREMENTS FOR HAZARDOUS MATERIALS

Potentially hazardous materials have been identified in Wrangell Medical Center that will affect both ongoing maintenance operations, as well as possible future renovations or demolition. Those materials include asbestos, lead, polychlorinated bi-phenyls (PCBs), mercury, and radioactive materials. Not all materials were tested for potentially hazardous components, other potentially hazardous materials, including those exterior to the building, such as contamination from underground fuel tanks may be present, but are not part of this report.

Buildings or portions of buildings that were constructed prior to 1978 which are residences, or contain day care facilities, kindergarten classes or other activities frequently visited by children under 6 years of age are classified as *child occupied facilities*. All work classified as “renovations” or disturbing more than 6 square feet of lead-based painted surfaces per room for interior activities or more than 20 square feet for exterior activities in child occupied facilities must comply with the requirements of 40 CFR 745. Portions of this building may be classified as a *child occupied facility* if children under 6 years of age spend long lengths of time in the facility, and it is the Owner’s responsibility to ensure the requirements of 40 CFR 745 are met. See lead testing results for locations of lead-based paints present in the project areas.

Only the materials that will be directly affected or disturbed are subject to OSHA and EPA regulations. It will be the Owner’s responsibility to take this baseline data to coordinate and fully develop a hazardous materials removal design that will identify the presence, locations and quantities of asbestos and/or other hazardous materials that will be affected by future projects. The removal and disposal of potentially hazardous materials are highly regulated, and it is anticipated that removal and disposal of asbestos, lead and chemical hazards will be conducted by a subcontractor to the general contractor who is qualified for such removal. It is anticipated that the general contractor and other trades will be able to conduct their work using engineering controls and work practices to control worker exposure and to keep airborne contaminants out of occupied areas of the building.

Settled and concealed dusts in areas not subject to routine cleaning are present throughout the building, including the roof, and inside and on top of architectural, mechanical, electrical, and structural elements, and those dusts are assumed to contain regulated air contaminants. This should not be read to imply that there is an existing hazard to building occupants (normal occupants of the building as opposed to construction workers working in the affected areas). However, depending on the specific work items involved and on the means and methods employed when working in the affected areas, construction workers could be exposed to regulated air contaminants from those dusts in excess of the OSHA Permissible Exposure Limits (PELs).

The settled and concealed dusts were examined by an EPA Certified Building Inspector but were not sampled. The inspector determined that the dusts are not "asbestos debris" from an asbestos-containing building material (ACBM). Based on similar sampling from similar buildings, the inspector also determined that the dusts are unlikely to contain more than one percent (1%) asbestos by weight, and therefore are not an asbestos-containing material (ACM). Reference 40 CFR 763.83.

NOTE: Asbestos-containing debris was noted from damaged pipe insulation, damaged joint compound of the gypsum wall board, and damaged roofing materials in the attic areas, and above the suspended ceiling system in the 1964 and 1974 eras, and it is likely that the dusts in these areas may contain more than one percent (1%) asbestos by weight, and therefore would be classified as an asbestos-containing material (ACM). Reference 40 CFR 763.83. The dirt floor of the crawl space under the 1974 portion of the building was also contaminated by debris from damaged pipe insulation, and the soil is considered to be contaminated.

"Awareness training" (typically 2 hours) and possibly respiratory protection will be required for all Contractor Personnel who will be disturbing the dusts. The extent of the training and protective measures will depend upon the airborne concentrations measured during air monitoring of the contractors work force, which depends on the means and methods employed to control the dusts. The air monitoring may be discontinued following a "negative exposure assessment" showing that worker exposures are below the OSHA permissible exposure limits for the type of work and means and methods employed. Previous air monitoring from similar jobs with similar conditions may be used as historical data to establish a "negative exposure assessment".

B. BUILDING DESCRIPTION

The Wrangell Medical Center was originally constructed in many different phases with many different renovations through the years. It is important to understand the boundaries and materials of each era of construction, as many materials have been removed or covered over by subsequent renovations.

The single story original portion was built in 1967 and includes much of the service functions of the building, as well as Operating rooms, etc. The original portion had a dirt floored crawl space with concrete foundation walls that were supported on what appeared to be driven steel piles. The original building was mainly of wood framed construction, with a slightly pitched, built-up roofing (beneath the metal roof) that contained asbestos.

The two story 1974 era consists of the current long-term care wing, with a lower level that mainly had storage, laundry, mortuary, and other service functions. The lower level had a slab-on grade foundation with truss joist framing supporting the main floor and a slightly sloped plywood roof deck with built-up roofing (beneath the metal roof) that contained asbestos.

A large addition and renovation was constructed in 1988 that was mostly of a modular construction that wrapped around the original core of the building. The "as-built" drawings from that construction are inconsistent, and appear to have a fair amount of errors, or undocumented changes. The 1988 work included renovations to areas of the original construction and 1974 wing. The 1988 renovation included installing a pitched metal roof over the entire building. The existing roofs were mostly left in place, with a large attic structure over the top of the existing structures, which also included an existing shallow attic over the original portion of the building. The 1988 addition also included an Exterior Insulation Finish Systems (EIFS) around the entire building. The 1988 addition had a dirt floored crawl space with concrete perimeter foundation walls and glue-laminated beams, supported by creosote piles, in a similar fashion to the original construction.

There was a maintenance/storage addition that was constructed sometime between 1992 and 1995, with the dates not being entirely clear. The 1992 addition was a pre-engineered metal building supported on concrete pads supported by piers, with a metal skirting around the perimeter of the building.

There were a couple of "infill" or "addition" rooms that were installed at an unknown date.

A Magnetic Resonance Imaging (MRI) instrument was located in a moveable trailer to the north of the main building. The MRI trailer was on lease, and was not inspected as part of this project.

The Building is built on a site that slopes down to the south, and is reported to be built on “muskeg” which has resulted in soil settling in several locations, most notable at the perimeter of the original construction and at the 1992 addition.

Interior portions of the building typically consisted of the following:

- Floor finishes: vinyl composition floor tiles, carpeting, sheet vinyl, ceramic mosaic floor tiles, laminate floors, and bare concrete. Most of the older portions had more than one layer of flooring present, and had wood substrates with multiple layers of plywood or particle board subflooring.
- Wall finishes: gypsum wall board, decorative ceramic wall tiles, and fiber reinforced plastic wall panels. It appeared that many walls in the older portions would have concealed materials beneath the current finish.
- Ceiling finishes: gypsum wall board, lay-in ceiling tiles, glued-on ceiling tiles, and exposed structure. The ceiling systems in the older portions often had concealed materials.

Heating and ventilation at the building is provided by various air handling systems, with hydronic heating, and oil fired boilers.

C. SAMPLING AND ANALYSIS

1. Asbestos-Containing Materials

The survey included sampling of suspect ACM materials that had not been sampled in prior asbestos surveys, or samples of materials where previous sampling had been inconsistent. The design has relied heavily on previous sampling conducted in the building, especially in areas that were closed to this survey due to COVID-19 restrictions. Refer to the previous asbestos survey report, available for review in the Wrangell Medical Center offices, for information on previous sampling which is not included in this report. Additional testing of materials pertinent to the project, including asbestos and lead was conducted and is included in this report.

The samples were analyzed for the presence of asbestos by polarized light microscopy (PLM), the method of analysis recommended by the U.S. Environmental Protection Agency (EPA) to determine the composition of suspected asbestos-containing materials (EPA method 600/M4-82-020). Only materials containing more than 1% total asbestos were classified as “asbestos-containing” based on EPA and the Occupational Safety and Health Administration (OSHA) criteria. Samples that were analyzed to have less than 10% asbestos were “point-counted” by the laboratory for more accuracy. Samples that are listed as having a “Trace by Point Count” had asbestos fibers found in the material, but the fibers were not present at the counting grids. Table 1 in Part D below contains a summary list of the asbestos bulk samples and the applicable results.

The Bulk Asbestos samples were analyzed for asbestos content by International Asbestos Testing Laboratories (IATL), Mt. Laurel, New Jersey a National Voluntary Laboratory Accreditation Program (NVLAP) accredited laboratory.

EPA regulations under 40 CFR 763 requires the use of Polarized Light Microscopy (PLM) to determine whether or not a material contains asbestos. While PLM analysis does a good job for most materials, it does have some limitations, both in the size of the fibers that are visible under a standard optical microscope, and because the organic matrix that the fibers are bound within can obscure the fibers. At the discretion of the building inspector and the client, some types of samples may be analyzed or re-analyzed by what is called TEM NOB, or Transmission Electron Microscopy for Non-Friable Organically Bound materials, for “asbestos in bulk building materials by TEM Gravimetry”. TEM NOB is the definitive method for determining if asbestos is present, but TEM NOB use is not required by the EPA. TEM NOB analysis was not done for this project.

Field survey data sheets and laboratory reports of the bulk samples are included in Appendix A. Drawings showing sample locations are included as Appendix C.

2. Lead-Containing Materials

Nearly all surfaces in the building were coated with paint and most surfaces had been repainted. EHS-Alaska tested representative paints throughout the affected areas of the building using an Heuresis Pb200i X-Ray Fluorescence (XRF) lead paint analyzer (Serial # 1770 with software version 4.0-21). The lead testing conducted was not a Lead-Based Paint Inspection or Screening as defined by HUD or EPA regulations, but was done to test surfaces that may be representative of those likely to be affected by this project. If surfaces and materials other than those tested are identified, it is presumed that additional testing may be appropriate. Refer to the Lead Analyzer Test Results Table in Appendix B that identifies the surfaces tested, and the results. All surfaces affected by this project may not have been tested and therefore additional sampling may be required to refute the presence of lead-based paints in child occupied facilities regulated by 40 CFR 745. The Lead Test Locations are shown in Appendix C.

EPA and the Department of Housing and Urban Development (HUD) have defined lead-based paint as any paint or other surface coating that contains lead equal to or in excess of 1.0 milligram per square centimeter (mg/cm²) or 0.5 percent by weight. XRF results are classified as positive (lead is present at 1.0 mg/cm² or greater), negative (less than 1.0 mg/cm² of lead was present) or inconclusive (the XRF could not make a conclusive positive or negative determination). Tests that were invalid due to operator error are shown as void tests.

A Performance Characteristic Sheet (PCS) for the Heuresis Pb200i is available upon request. This PCS data provides supplemental information to be used in conjunction with Chapter 7 of the "HUD Guidelines". Performance parameters provided in the PCS are applicable when operating the instrument using the manufacturer's instructions and the procedures described in Chapter 7 of the "HUD Guidelines". The instrument was operated in accordance with manufacturer's instructions and Chapter 7 of the HUD Guidelines. No substrate correction is required for this instrument. There is no inconclusive classification for this instrument when using the 1.0 mg/cm² threshold.

D. SURVEY RESULTS

1. Asbestos-Containing Materials

The following Table 1A lists the samples taken in September 2020, and the results of the laboratory analysis. Asbestos field survey data sheets and laboratory reports are included as Appendix A. Refer to Appendix C for sample locations.

TABLE 1A

SAMPLE NUMBER	MATERIAL	LOCATION	ASBESTOS CONTENT
WMS0920-A01	White, Chalky "Hard Fitting" insulation	Attic Fan room in 1967 Era. On white pipe above fan unit near Hatch. Photo B72	3.2% chrysotile, 2.2% crocidolite, 1% amosite
WMS0920-A02	White, Chalky "Hard Fitting" insulation	Attic Fan room in 1967 Era. On loose yellow painted insulation in plastic box near Hatch. Photo B73	3.4% chrysotile, 2.4% crocidolite, 1.2% amosite
WMS0920-A03	White, Chalky "Hard Fitting" insulation	Attic Fan room in 1967 Era. Broken elbow near fan-coil. Photo B74	30% chrysotile, 6% amosite

HAZARDOUS MATERIALS ASSESSMENT

SAMPLE NUMBER	MATERIAL	LOCATION	ASBESTOS CONTENT
WMS0920-A04	Gray sticky sealant in HVAC Unit	Attic Fan room in 1967 Era. Filter bank chamber downstream of the Heat Recovery Wheel. Photo R575	3.4% chrysotile
WMS0920-A05	Joint compound at Ceiling	Attic Fan room in 1967 Era. Ceiling above Fan Unit Photo B75	1.6% chrysotile
WMS0920-A06	GCT-1; 12x12 Ceiling tiles with dark brown mastic	Attic Fan room in 1967 Era. Loose, stored tiles "in case they are needed". Photo B76	None Detected, both layers
WMS0920-A07	GCT-1; 12x12 Ceiling tiles with dark brown mastic	Attic Fan room in 1967 Era. Loose, stored tiles "in case they are needed". Photo B77	None Detected, both layers
WMS0920-A08	Gray sticky sealant in HVAC Unit	Attic Fan room in 1967 Era. Filter bank chamber downstream of the Heat Recovery Wheel. No photo	3.2% chrysotile
WMS0920-A09	Gray sticky sealant at ductwork	Attic Fan room in 1967 Era. At shiny ducts of Kitchen Exhaust Fan. Photo B78	3.4% chrysotile
WMS0920-A10	Gray sticky sealant in HVAC Unit	Attic Fan room in 1967 Era. Filter bank chamber for Fan 10016. Photos R601, 602	3.4% chrysotile
WMS0920-A11	Dark Brown mastic for TJI Wood joists. Ignore wood layer!	Attic, Joists of the 1988 roof structure. Near peak of the roof above the 1967 era. Photo B88	None Detected
WMS0920-A12	Dark Brown mastic for TJI Wood joists. Ignore wood layer!	Attic, Joists of the 1988 roof structure. Near peak of the roof above the 1967 era. Photo B89	None Detected
WMS0920-A13	Joint Compound	Attic. On exterior "wall" of the 1967 fan rom, but likely installed in 1988. Photo B90	None Detected
WMS0920-A14	Tar Paper under 1988 metal Roof	Attic, at hole for Boiler stack through the 1988 roof. Photo R 639	None Detected
WMS0920-A15	Brown hard insulation of "Van Packer" boiler stack	Attic. Appears to be original 1967 stack. Photo R 640 & 41	40% chrysotile
WMS0920-A16	White fabric and Black Tar sealant	Attic above PT. Remnant of temporary roof over 1988 modular buildings. At Duct penetration. Photo B91	3.4% chrysotile
WMS0920-A17	White fabric and Black Tar sealant	Attic above PT. Remnant of temporary roof over 1988 modular buildings. At Duct penetration. Photo R655 & 656	None Detected
WMS0920-A18	GCT 12x12 Ceiling tiles with dark brown mastic. "PyROTECT on back.	Attic above PT. Loose, stored tiles "in case they are needed". Photo B95	None Detected, both layers

SAMPLE NUMBER	MATERIAL	LOCATION	ASBESTOS CONTENT
WMS0920-A19	GCT 12x12 Ceiling tiles with dark brown mastic. "PyROTECT on back.	Attic above PT. Loose, stored tiles "in case they are needed". Photo B97	None Detected, both layers
WMS0920-A20	Black tarry coating inside old Pace Exhaust Fan	Attic above boiler room. Fan appears to be abandoned. Photo R633 & 638	5.2% chrysotile
WMS0920-A21	Cream Window Frame Sealant, between frame and (missing) siding (21" x 5'-6")	Attic above PT. Loose stored windows. Likely to be from the 1974 Dayroom. Photo R670	4.1% chrysotile
WMS0920-A22	Cream Window Frame Sealant, between frame and (missing) siding (21" x 5'-6")	Attic above PT. Loose stored windows. Likely to be from the 1974 Dayroom. Photo R670	3.8% chrysotile
WMS0920-A23	Lighter yellow-white window glazing compound at edge of glass (21" x 5'-6")	Attic above PT. Loose stored windows. Likely to be from the 1974 Dayroom. Photo R671 & 2	1.3% chrysotile
WMS0920-A24	Gray sticky window glazing compound at edge of glass (21" x 5'-6")	Attic above PT. Loose stored windows. Likely to be from the 1974 Dayroom. Photo R671 & 2	2.4% chrysotile
WMS0920-A25	Cream, hard window glazing compound at edge of glass (10" x 7'-8")	Attic above PT. Loose stored glass. Photo R676 & 7	4.2% chrysotile
WMS0920-A26	White sealant at round adjustable duct.	Attic above PT. Loose stored duct. Photo R678	None Detected
WMS0920-A27	White sealant at round adjustable duct.	Attic above Reception Area. Active Duct. Photo B100	None Detected
WMS0920-A28	Chalky white hard fitting insulation	Attic above Surgery Area. Debris on Ceiling. Photo B101	15% chrysotile, 5% amosite
WMS0920-A29	Tarry craft paper from behind cedar shingle siding	Attic. Former exterior wall of 1974 era. Photo B102	None Detected
WMS0920-A30	Red duct sealant	Attic above 1967 era. Loose duct in attic space. Photo R734	4.4% chrysotile
WMC920-A31	Gray-green mastic of Stainless Corner Guard	Attic near 1974 era. Loose stored corner guard. Photo B103	None Detected
WMC920-A32	Built-up Roofing of 1974 era flat roof, with brown perlite board insulation	Attic of 1974 era. Under loose fiberglass at exhaust duct penetration through old roof into attic. Photo B104	20% chrysotile in BUR, None Detected in perlite
WMC920-A33	Tarry vapor barrier and tar and fesco board	Attic of 1974 era. Bottom of roof assembly at exhaust duct penetration through old roof into attic. Photo R745 & 746	None Detected, both layers

HAZARDOUS MATERIALS ASSESSMENT

SAMPLE NUMBER	MATERIAL	LOCATION	ASBESTOS CONTENT
WMC920-A34	Probably hot mop and fesco board	Attic of 1974 era. Middle layer of fesco board insulation at exhaust duct penetration through old roof into attic. Photo R747	None Detected, both layers
WMC920-A35	Built-up Roofing of 1974 era flat roof with brown perlite board insulation	Attic of 1974 era. Under loose fiberglass at supply duct penetration through old roof into attic. Photo R749	20% chrysotile in 3 of the BUR layers , None Detected in perlite
WMC920-A36	Tarry vapor barrier and tar and fesco board	Attic of 1974 era. Bottom of roof assembly at supply duct penetration through old roof into attic. Photo R750	None Detected
WMC920-A37	ATCO Roof patch tar	Attic near 1974 era. Loose 5 gal. can of Part # 1823. Photo R733	6.2% chrysotile
WMC920-A38	Tar paper under T&G Siding	Attic at "exterior" side of original 1967 Fan Room. Photo R762	None Detected
WMC920-A39	Tar paper and GWB sheathing under T&G Siding	Attic at "exterior" side of original 1967 Fan Room. Photo R763 & 4	None Detected all three layers
WMC920-A40	White silicone sealant at roofing	Metal Roof under valley flashing canopy near main entrance. Photo R782 & 783	None Detected
WMC920-A41	Gray rubbery roof sealant	Metal Roof sealant under edge flashing, near main entrance. Photo R782 & 783	None Detected
WMC920-A42	Clear silicone sealant at fascia of roofing	Metal Roof at lap joint of metal drip ledge over EFIS. Photo R787	None Detected
WMC920-A43	Clear yellow sealant at roofing	Metal Roof, sealant between roofing and metal angle edge flashing into gutter. Photo R786	None Detected
WMC920-A44	Tar paper under metal roofing	Metal roof, under main roof, over decking. Photo R789	None Detected
WMC920-A45	Foam Robber filler at roofing	Metal roof, at edge box of roofing. B105	None Detected
WMC920-A46	Gray sticky putty sealant at roofing	Under metal roof, at edge flashing. B106	None Detected
WMC920-A47	EFIS Stucco & sealant	At column of main entrance drive-through. Photo B109	None Detected, both layers
WMC920-A48	GWB of Soffit	At water damaged at underside of soffit at main entrance drive-through. Photo R791-793	None Detected
WMC920-A49	Joint compound of soffit	At water damaged at underside of soffit at main entrance drive-through. Photo R791-793	None Detected

HAZARDOUS MATERIALS ASSESSMENT

SAMPLE NUMBER	MATERIAL	LOCATION	ASBESTOS CONTENT
WMC920-A50	Concrete Sacking	Exterior Foundation wall of 1974 Addition, At snap-tie hole. Photo B110	None Detected
WMC920-A51	Gypsum wall board, joint compound & tape	Ceiling of exterior soffit of walkway going to "morgue door". Photo R807	None Detected, both layers
WMC920-A52	Gray sticky sealant with black foam backer rod	Between door frame and concrete of "morgue door" to 1974 era. Photos R805 & 806	None Detected, both layers
WMC920-A53	White window frame sealant	Between window frame and EFIS. Photo B111	None Detected
WMC920-A54	Harder cream sealant	Sealant at plywood of boarded up window around Air Conditioning Unit. Photo B112 & 113	None Detected
WMC920-A55	Black Tarry Waterproofing at foundation	In crawl space. At former exterior wall of 1974 addition. Photo R836 & 837	None Detected
WMC920-A56	Cement asbestos pipe	In crawl space. At capped pipe coming out of soil. Photo B114, R832	10% chrysotile, 10% crocidolite
WMC920-A57	Cement asbestos pipe	In crawl space. At active sewer pipe. Photo B118, R841	12% chrysotile, 8% crocidolite
WMC920-A58	Hard Fitting insulation	In crawl space. Probably on a hot water pipe. Photo R843 & 845	0.5% chrysotile, 1.2% crocidolite
WMC920-A59	Hard Fitting insulation	In crawl space, on ground. Photo R855	20% chrysotile, 1.5% crocidolite
WMC920-A60	Black Tarry Waterproofing at foundation	At exterior wall of 1974 addition. Photo R885	None Detected
WMC920-A61	Sticky cream sealant at EFIS	At EFIS over 1974 addition. Between metal frame of louver & EFIS. Photo B119	None Detected
WMC920-A62	Sticky cream sealant at EFIS	At EFIS over 1988 addition. Between metal frame of window & EFIS. Photo R1674 & 1675	None Detected
WMC920-A63	Black rubbery glazing at alum windows	Aluminum framed window of 1988 addition. Photo R1674 & 1675	4.5 % chrysotile
WMC920-A64	Sticky cream sealant at EFIS	At EFIS over 1988 addition. Between GWB soffit & EFIS. Photo R1677	None Detected
WMC920-A65	Whiter caulking at EFIS	At EFIS over 1988 addition. Between metal generator louver & EFIS. Photo R1678	None Detected
WMC920-A66	Pinkish caulking	At 1988 addition. Between metal generator louver & louver frame. Photo R1679	None Detected

HAZARDOUS MATERIALS ASSESSMENT

SAMPLE NUMBER	MATERIAL	LOCATION	ASBESTOS CONTENT
WMC920-A67	EFIS Stucco & fiberglass mesh	At 1988 addition. At drip edge of EFIS. Photo R1692	None Detected
WMC920-A68	Clear sealant at window	At 1992 addition. At wood frame to plastic window joint. Photo R1693	None Detected
WMC920-A69	White sealant at siding	At 1992 addition. At vent pipe penetration of metal siding. Photo R1719	None Detected
WMC920-A70	White sealant at soffit fascia	At 1992 addition. At lap joint of lower soffit flashing. Photo R1721	None Detected
WMC920-A71	White sealant at standing seam roof.	At 1992 addition. At folded top seam of rib joints. Photo R1722	None Detected
WMC920-A72	Tar paper under metal roofing	At 1992 addition. Under main metal roofing. Photo R1724	None Detected
WMC920-A73	Gray sealant at metal roofing	At 1992 addition. At flashing between metal siding and transition flashing over vestibule roof. Photo R1725	None Detected
WMC920-A74	Sticky cream sealant at EFIS	At EFIS over 1988 addition. At Fire Dept. Connection. Photo R1680 R 1726 and B223	None Detected
WMC920-A75	Sticky cream sealant at EFIS	At EFIS over 1967 Orig. Between GWB soffit & EFIS. Photo B224	None Detected
WMC920-A76	Gypsum board & Joint compound	1992 Addition. Corner of Rm 25, Bulk Storage. Photo R1850	None Detected all three layers
WMC920-A77	CB-1, 4" gray cove base with cream mastic, joint compound and gypsum wall board	1992 Addition. Corner of Rm 29, Vestibule. Photo R1859	None Detected all five layers
WMC920-A78	Gypsum wall board & joint compound	1967 era, Sprinkler Room 30, but wall supposedly built with 1988 addition. Photo R1870	None Detected all three layers
WMC920-A79	Gypsum wall board & joint compound	1967 era, Sprinkler Room 30, 1967 exterior wall. Photo R1871	None Detected in gypsum bd, 2.8% chrysotile in joint
WMC920-A80	CB-2, 4" green (painted) cove base with dark brown mastic.	1967 era, Sprinkler Room 30, 1967 exterior wall. Appears original. Photo R1871	None Detected, both layers
WMC920-A81	Hard fitting insulation	1967 era, Boiler Rm. 108. On yellow boiler supply pipe. Photo R1918	10% chrysotile
WMC920-A82	Hard fitting insulation	1967 era, Boiler Rm. 108. On yellow boiler supply pipe. Photo R1919	10% chrysotile, trace amosite

HAZARDOUS MATERIALS ASSESSMENT

SAMPLE NUMBER	MATERIAL	LOCATION	ASBESTOS CONTENT
WMC920-A83	Hard fitting insulation	1967 era, Boiler Rm. 108. On blue cold water supply. Photos R1908 & 1925	10% chrysotile, trace amosite
WMC920-A84	Black tarry coating inside ceiling speaker box	1988 era. Staff Lounge, 115. Inside red speaker box. Photos R1940 & 1941	None Detected
WMC920-A85	LCT-2, 2' x 4' "Galaxy" pattern suspended ceiling tile. Random small fissures	1988 era. Staff Lounge, 115. Main tile in room. Photo R1938	None Detected
WMC920-A86	CB-2, 4" green (painted) cove base with dark brown mastic & old (on back of CB) & newer Joint Compound (on face of CB)	1967 era, Elec Rm 34, Possible 1988 wall, but appears original. Photo B229	None Detected in three layers, 2.6% chrysotile in joint compound
WMC920-A87	LCT-1, 2' x 4' shallow directional fissures, 1/16" & 1/8" holes	1967 era, but newer tile. Hallway to 1992 addition. Photo B230	None Detected
WMC920-A88	SV-1, cream sheet vinyl with white shading and tiny brown specks	1967 era, but newer flooring. Hallway to 1992 addition. Photo B231	None Detected, both layers
WMC920-A89	CB-3, Gray 4" cove base with light tan mastic	1988 addition, Janitor Closet 109. Photo R1958 & 1959	None Detected, both layers
WMC920-A90	SV-2, Cream with small 3/8" & smaller light tan & gray chips, tan mastic	1988 addition, Janitor Closet 109. Photo R1959	None Detected, both layers
WMC920-A91	"Ventglas" Black neoprene duct flexible connector	1967 Penthouse Fan Rm. At exhaust fan #10019. Photo B232 & 233	None Detected
WMC920-A92	"Ventglas" Black neoprene duct flexible connector	1967 Penthouse Fan Rm. At central AHU. Photo B234	None Detected
WMC920-A93	SV-1, cream sheet vinyl with white shading and tiny brown specks, brown mastic	1967 era, but newer flooring. Store Rm 102. Photo R1966	None Detected, both layers
WMC920-A94	Leveling compound or "Float" over concrete	1967 era. Store Rm 102. Appears to be 1/2" thick over painted concrete. Photo R1966 & 1967	None Detected
WMC920-A95	Tar paper between layers of plywood (ignore wood)	1967 era. At hatch in Janitor Closet 38. Appears to be original slip-sheet between plywood subfloor and plywood underlayment. Photo R1975	None Detected
WMC920-A96	Tar mastic? under particle board (ignore wood)	1967 era. At hatch in Janitor Closet 38. Appears to be original black mastic under particle board underlayment. Photo R1975	4.1% chrysotile

HAZARDOUS MATERIALS ASSESSMENT

SAMPLE NUMBER	MATERIAL	LOCATION	ASBESTOS CONTENT
WMC920-A97	SV-1, cream sheet vinyl with white shading and tiny brown specks, brown mastic, particle board (ignore wood)	1967 era. At hatch in Janitor Closet 38. Top layer over particle board. Photo R1975	None Detected, both layers
WMC920-A98	SV-3, fake wood sheet flooring, white leveling compound, sticky brown contact cement	1988 era, PT Room, 132. At in-floor duct grille by entrance. Photo R1992	None Detected all three layers
WMC920-A99	White leveling compound, brown mastic	1988 era, PT Room, 132. At in-floor duct grille by entrance. Photo R1992	None Detected, both layers
WMC920-A100	Brown mastic on side of metal duct	1988 era, PT Room, 132. Probably original flooring mastic. At in-floor duct grille by entrance. Photo R1993	None Detected
WMC920-A101	White seal at ductwork	1988 era, PT Room, 132. At opposed blade damper in relief. Photo R1998	None Detected
WMC920-A102	Gypsum wall board and joint compound	1988 era, PT Room, 132. At wall above ceiling grid. Nailed on. Photo R2001	None Detected, both layers
WMC920-A103	SV-2, Cream with small 3/8" & smaller light tan & gray chips, tan mastic (ignore wood)	1988 era, Closet 143. At hatch to crawl space. Photo R2052, 2062	None Detected, both layers
WMC920-A104	CB-3, Gray 4" cove base with cream mastic.	1988 era, Exam Rm 151. Photo R2090	None Detected, both layers
WMC920-A105	Yellow carpet mastic	1988 era, Hallway outside Restroom 142. Photo R2091	None Detected
WMC920-A106	Yellow carpet mastic & gray leveling compound	1988 Era, Waiting Area 81, by vestibules. Photo B260	None Detected, both layers
WMC920-A107	Joint compound	1988 Era, Waiting Area 81, by corner near Admin 79. Photo B261	None Detected
WMC920-A108	Gypsum wall board	1988 Era, Waiting Area 81, by corner near Admin 79. Photo B262	None Detected, both layers
WMC920-A109	Exterior stucco of EFIS at added walls around Dining/Activity 69	Unknown date, reportedly within the past 10 years. Photo B263	None Detected, both layers
WMC920-A110	Exterior stucco, red sealant of EFIS at added walls around Dining/Activity 69	Unknown date, reportedly within the past 10 years. Photo R2251	None Detected
WMC920-A111	Black rubber stair tread with brown mastic	1974 era. Base of stairs. Photo R2262	None Detected, both layers
WMC920-A112	Black rubber stair stringer with brown mastic	1974 era. Base of stairs. Photo R2263	1% chrysotile in rubber, None Detected in mastic

HAZARDOUS MATERIALS ASSESSMENT

SAMPLE NUMBER	MATERIAL	LOCATION	ASBESTOS CONTENT
WMC920-A113	Black Sink undercoating	1974 era. Break Rm. 9 Stainless steel sink. Photo R2272	2.6% chrysotile
WMC920-A114	"Marlite" and brown mastic	1974 era. Restroom 12. At cleanout. Photo R2277	None detected in marlite, trace chrysotile in mastic
WMC920-A115	White, chalky fire door insulation	1974 era. Door between back hallway and Laundry 15. UL listed 1.5 hour rating. Photo R2279	60% chrysotile
WMC920-A116	Red duct sealant	1974 era. Mech/fan Rm. 3 on Mixing side of plenum wall. Photo R2289	5.2% chrysotile
WMC920-A117	Red duct sealant	1974 era. Mech/fan Rm. 3 at bare steel flange. Photo B264	5% chrysotile
WMC920-A118	Gray sealant at Fan sections	1974 era. Mech/fan Rm. 3. Fan 10013. Photo R2290	None Detected
WMC920-A119	"Ventglas" Black neoprene duct flexible connector	1974 era. Mech/fan Rm. 3. Outlet side of Squirrel cage fan. Photo R2291	None Detected
WMC920-A120	Gray ceramic tile grout	1974 era. Restroom 12. Loose grout in crack in base by door Photo R2278	None Detected
WMC920-A121	GCT-1, 12" x 12" Glued on ceiling tile, groove for concealed grid, directional medium fissures, 1/16" holes, Brown mastic	1974 era. Hallway 6, at Speaker box. Photo B265 & 266	None Detected, both layers
WMC920-A122	Black tarry lining of red speaker box.	1974 era. Hallway 6, at Speaker box. Photo B266 & R 2296	None Detected
The testing method used (polarized light microscopy [PLM]) is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Before this material can be considered or treated as non-asbestos containing, confirmation should be made by quantitative transmission electron microscopy (TEM).			

A previous limited survey for asbestos-containing materials was conducted in the Wrangell Medical Center in 2018, and this assessment by EHS-Alaska supplemented that previous survey. Many of the samples taken in the 2018 survey were not able to be located, because of the poor quality of the sample location drawings. The following materials have been found to contain asbestos in this or previous surveys, or were assumed to contain asbestos.

1. Built-Up Roofing materials of the original 1967 building (confirmed asbestos)
2. Built-Up Roofing materials of the original 1974 building (confirmed asbestos)
3. Remnants of the temporary roofing materials over the modular buildings of the 1988 addition (confirmed asbestos).
4. Loose container of ATCO roof patching tar found in attic (confirmed asbestos).
5. Patching tars of 1988 metal roofing and 1992 metal roofing (assumed asbestos).
6. Gray sealants at the ductwork of the original 1967 building (confirmed asbestos).
7. Gray, sticky putty-like sealants at joints between sections of AHU's in 1967 building.
8. Red sealant at ductwork. Found in attic above 1967 building, and in 1974 era (confirmed asbestos).

9. Pale green caulking of windows of original 1967 construction (confirmed asbestos).
10. Sealant around stored window frame (appears to be similar to 1974 era windows, confirmed asbestos).
11. Glazing compound of stored windows (appears to be similar to 1974 era windows, confirmed asbestos).
12. Black rubber glazing (likely original from manufacturer) in aluminum windows of 1988 era (confirmed asbestos).
13. Joint compound in gypsum wallboard systems on the ceilings and walls of the original 1967 and 1974 long-term care addition (confirmed asbestos).
14. Black sink undercoatings (confirmed asbestos).
15. Cement asbestos pipe at exterior near 1974 long-term care addition (confirmed asbestos).
16. Cement asbestos pipe abandoned in crawl space under original 1967 building (confirmed asbestos).
17. Cement asbestos waste pipe in crawl space under original 1967 building (confirmed asbestos).
18. Cement asbestos board (CAB) soffits shown on as-built drawings of the 1967 original construction. Not found, but possibly present in multiple layers of concealed and abandoned roof areas (assumed asbestos and assumed to still be present).
19. Cement asbestos board (CAB) siding shown on as-built drawings of the 1967 building and the 1974 long-term care addition but is currently covered by EIFS siding (assumed asbestos and assumed to still be present).
20. Hard and chalky insulation at pipe valves and fittings of original 1967 (confirmed asbestos) and 1974 long-term care addition (assumed asbestos).
21. Debris from the hard and chalky insulation mixed into the soil of the original 1967 crawl space (confirmed asbestos).
22. Boiler gaskets and sealants in original 1967 era Boiler Room (assumed asbestos).
23. Flange gaskets on piping of all eras (assumed asbestos).
24. "Van-Packer" Boiler Stack in original 1967 era Boiler Room (confirmed asbestos).
25. Tarry sound absorption lining of abandoned exhaust fan in attic space (confirmed asbestos).
26. Carpeting mastics (found to be contaminated from original black mastic from vinyl tile, 1967 era and 1974 era).
27. Black rubber stair stringer coving of 1974 era (confirmed asbestos)
28. Various colors of 12" x 12" Floor tiles in 1967 era (some tiles confirmed asbestos, non-asbestos tiles contaminated by black mastic).
29. Mastic to "Marlite" paneling of 1974 restroom (trace of chrysotile found, possible contamination from joint compound of gypsum wall board)
30. Hard and chalky insulation in original wooden fire doors of 1974 era (confirmed asbestos).
31. Insulation board lining of attic access hatches in original 1967 era (assumed asbestos).

The effects of the above asbestos-containing materials on the proposed renovation are discussed below.

Built-Up Roofing of 1967 and 1974 Buildings

The original, near flat roof of the 1967 and 1974 buildings remain underneath the slanted metal roofing installed in 1988. Those roofs have been partially removed in places for new construction or new penetrations, but the existing built-up roofing has been found to contain asbestos, and is non-friable except where cut and damaged. The original vapor barriers at the bottom of the roof assembly are assumed to also contain asbestos. Roofing disturbance or removal is Class II asbestos work, but may be left in place during demolition if the entire roof structure is disposed of as asbestos waste.

Remnants of Roofing Material in 1988 Modular Building

Much of the 1988 portion of the building was of modular construction. Those modules were temporarily covered with a waterproof membrane that was subsequently removed. The original membrane and patching tars were left in place, mostly around duct penetrations and at the joints between modules, and the patching tars were found to contain asbestos. These materials are not friable. Roofing disturbance or removal is Class II asbestos work, but may be left in place during demolition if the entire roof structure is disposed of as asbestos waste, but these materials are likely to be able to be removed separately from the plywood module roof structure.

Patching Tars of 1988 Pitched Metal Roofing and 1992 metal roofing

The entire building (except the 1992 addition) was covered with a pitched metal roof installed in 1988. The roofing was inspected only at the perimeter, due to the lack of fall protection available. The metal roof over the 1992 addition was similar, but not accessible. It is assumed that there are some patching tars that have been used on the roofs, and those patching tars are assumed to contain asbestos. These materials are not friable. Roofing disturbance or removal is Class II asbestos work, but may be left in place during demolition if the entire roof structure is disposed of as asbestos waste, but the patching tars are likely to be able to be removed separately from the metal roofing.

Gray Duct Sealants

Gray Sealants at the joints of the site-built fan plenums, as well as on some larger ducts in the 1967 portion of the building was found to contain asbestos. A similar, but still soft and sticky, gray putty-like sealant was found at the joints between the fan unit sections in the 1967 attic fan room. The sealants were in good condition and were not friable. Any disturbance or removal is Class II asbestos work, but the sealants may be left in place during demolition if the ductwork is disposed of as asbestos waste.

Red Duct Sealants

Red Sealants at the ducts of the 1974 portion of the building was found to contain asbestos. Several loose sections of ductwork with a similar red sealant was found stored in the "attic" above the 1967 portion of the building. The sealant was in good condition and was not friable. Any disturbance or removal is Class II asbestos work, but the sealants may be left in place during demolition if the demolition if the materials they are attached to are disposed of as asbestos waste.

Door, Window and Penetration Sealants and Window Glazing Compounds

The "pale green caulking" at the interior of the windows of the 1967 construction was found by the previous EMI inspection to contain asbestos. It is not clear if that was a glazing compound holding the glass into the frame, or a sealant around the window frame. Both the glazing compounds and the frame sealants were found to contain asbestos in samples taken from loose, stored windows found in the attic space over the 1988 portion of the building. Those loose windows were similar to the windows of the 1974 era, and are assumed to have been removed from that area. The rubber molding between the aluminum window frame and the glass of the 1988 era windows were found to contain asbestos, although the sealants between the window frames and the EIFS siding did not contain asbestos. It is assumed that older sealants at penetrations through the outer walls had an asbestos-containing sealant, including around door and window frames, as well as other penetrations, which, in the 1967 and 1974 eras of construction are covered over by the EIFS of the 1988 construction. Window glazing compounds are assumed to contain asbestos. The sealants are assumed to be not friable and in good condition. Any disturbance or removal is Class II asbestos work, but the sealants and glazing may be left in place during demolition if the materials they are attached to are disposed of as asbestos waste.

Gypsum Board Joint Compound

Gypsum board joint compound in the original walls and ceilings of the 1967 and 1974 portions of the building was asbestos-containing. No asbestos has been detected in the gypsum board. Joint compound was in good condition and is not considered friable unless damaged. There have been fairly extensive renovations in the 1967 portion of the building, with fewer renovations in the 1974 portion, and those newer renovations had gypsum board without asbestos-containing joint compound. Those newer renovations are presumed to have covered over older gypsum board materials with asbestos-containing joint compound where newer finishes were installed at original wall or ceiling locations. Any disturbance or removal is Class II asbestos work, but the joint compound and gypsum board may be left in place during demolition if the gypsum board wastes are disposed of as asbestos waste.

Sink Undercoating

Stainless steel sinks mostly in the 1967 and 1974 portions of the building, but possibly in other areas were coated on the underside with a black spray-applied material containing asbestos. Other white and green sink undercoatings were noted, sampled and found to not contain asbestos. This material was in good condition and is not considered friable. Any disturbance is Class II asbestos work, but the sinks may be

left in place during demolition if the waste stream they are included within, are disposed of as asbestos waste.

Cement Asbestos Piping

Cement asbestos piping, also known as "Transite" piping was commonly used in sewer, roof drain, and low pressure water piping. There was cement asbestos waste piping found in the crawl space under the 1967 portion of the building that was still in use. There was abandoned cement asbestos piping also found within that same crawl space, as well as a possibly abandoned cement asbestos vent or clean-out pipe noted near the east side of the 1974 building. The cement asbestos piping was typically in good condition and was not friable, but is likely to become friable during demolition or removal. Any disturbance or removal is Class II asbestos work, and would be recommended to be removed prior to demolition, with proper care taken during excavation.

Cement Asbestos Board Soffit

The soffit beneath the overhang of the original 1967 roof was called out to be covered with cement asbestos board. That CAB soffit paneling was not found, but is possibly present in the multiple layers of concealed and abandoned roof areas. Any disturbance or removal is Class II asbestos work, and would be recommended to be removed prior to demolition, with proper care taken when doing pre-demolition exploration for concealed materials.

Cement Asbestos Siding

Portions of the siding of the original 1967 and the 1974 eras of the building were called out on original as-built drawings as cement asbestos board. That CAB siding was not found, but is assumed to be present underneath the EIFS siding which was installed in 1988. Any disturbance or removal is Class II asbestos work, and would be recommended to be removed prior to demolition, with proper care taken when doing pre-demolition exploration for concealed materials.

Pipe Fitting Insulation

Piping concealed above the ceilings, in walls, in the attic, and in mechanical spaces of the 1967 and 1974 eras is insulated at fittings with asbestos-containing insulation. The insulation is generally in good condition but is considered friable. It is recommended that pre-demolition exploration for concealed asbestos-containing insulation be conducted, including multiple "attics" and concealed spaces in the 1967 and 1974 eras. If any concealed piping is found to have hard and chalky or other insulation suspected of containing asbestos, those materials shall be sampled or assumed to contain asbestos prior to disturbance. Any disturbance or removal of pipe insulation is Class I asbestos work, and the asbestos-containing pipe insulation is required to be removed prior to demolition.

Contaminated Soil of 1967 Crawl Space

The domestic water and heating piping in the crawl space of the 1967 era had significant damage to the asbestos-containing insulation. The dirt floor of the crawl space had debris from that pipe insulation mixed into the soil, and the raised dusts pose a significant hazard to personnel crawling through the crawl space to perform maintenance. The corrective action in the crawl space could change depending on whether renovation or demolition of the building is proposed, but it is likely that a minimum of two to four inches of the soil would need to be removed to abate the contaminated soils. Removal of the soil is considered Class I asbestos work.

Boiler Gaskets and Sealants

The boilers appeared to have been replaced in 1999. Due to their age, gaskets and sealants on the boilers are assumed to be asbestos-containing. These materials are difficult to sample without disassembly of equipment and no sampling was performed. These materials were in good condition but may become friable during removal for replacement. The gaskets and sealants could be removed and disposed of intact with the rest of the boilers as Class IV asbestos work.

Flange Gaskets and Valve Packing

Due to their age, gaskets and valve packing on mechanical equipment throughout the building, but mostly in mechanical and fan rooms are assumed to be asbestos-containing. These materials are difficult to

sample without disassembly of equipment and no sampling was performed. These materials were in good condition but may become friable during removal for replacement. The gaskets and packings could be removed and disposed of intact with the rest of the piping as Class IV asbestos work.

Boiler Stack Insulation

What appeared to be the original 1967 "Van-Packer" boiler stack was insulated with asbestos-containing insulation. The hard and chalky insulation was covered with a metal jacket, but would become friable if removed or demolished. Removal or demolition of the boiler stack is Class I asbestos work and would be required to be removed prior to demolition of the building.

Exhaust Fan Coatings

Sound dampening coatings on an older, abandoned roof mounted exhaust fan in the attic space contained asbestos. The exhaust fan can be removed as Class IV asbestos work, if it is removed intact. This material was in good condition and was not friable and may be left in place during demolition if the intact fan is disposed of as asbestos waste.

Floor Tiles and Black Mastic, Including Contamination of Newer Flooring

The original as-builts of the 1967 and 1974 eras called for vinyl asbestos floor tiles, or "conductive vinyl tile". Only some of those tiles were still present, and where tested, both the floor tiles and black mastic did contain asbestos. The 1988 renovation appeared to have covered over much of the original flooring on the main floor of the 1967 and 1974 eras. This investigation found the asbestos-containing black flooring mastic underneath both a particle board subflooring, as well as an ~1/2" thick cementitious leveling compound in the 1967 era, as well as a black mastic contamination of carpeting or replacement floor tiles where the original flooring was removed, but the asbestos-containing mastic was left behind during a previous renovation. The newer welded seam sheet vinyl flooring that was located in most areas of the 1967 era and those subfloors covered over the original asbestos black mastic, which are assumed to be present throughout the original 1967 era, except in a few rooms that were called out in the original as-builts to have bare floors, such as the boiler room, generator room, janitor closet and storage rooms. The tile and mastic was typically not friable, and any disturbance or removal would be Class II asbestos work. This material was in good condition and was not friable and may be left in place during demolition if the entire flooring system is disposed of as asbestos waste.

Rubber Stair Stringer of 1974 era

The black rubber stringer of the stairs in the 1974 era contained asbestos, the mastic did not contain asbestos. The rubber stringers were in good condition and were not friable disturbance or removal would be Class II asbestos work. The stringer may be left in place during demolition if the stairs and attached components are disposed of as asbestos waste.

Marlite Mastics

One sample of a mastic used to secure "Marlite" paneling to a bathroom wall in a restroom in the 1974 era contained asbestos. That asbestos could have been in the mastic itself, or could have been a contamination from the asbestos-containing joint compound of that era. Because the "Marlite" mastic is attached to the joint compound, it typically would be removed as Class II asbestos work. Mastics were in good condition and were not friable and the mastics may be left in place during demolition if the gypsum board / Marlite wastes are disposed of as asbestos waste.

Door Insulation

Interior wood doors in the 1974 era were insulated with asbestos. Insulated wood doors were typically located in hallways at entrances to storage rooms or at fire rated walls. Door insulation is considered non friable if completely sealed within the door skin. Damaged doors are considered friable. The doors can be removed as Class IV asbestos work, if the doors remain intact. The doors would be required to be removed prior to demolition.

Access Hatch Insulation Board Lining

A metal ceiling hatch in the 1967 era for the Fan Room access was assumed to be insulated with asbestos. Insulated metal hatch was typically small and provided access to mechanical spaces. Hatch insulation is

considered non friable if completely sealed within the metal skin. Damaged doors are considered friable. The doors can be removed as Class IV asbestos work, if the doors remain intact. The doors would be required to be removed prior to demolition.

2. Asbestos in Dusts

The settled and concealed dusts were examined by an EPA Certified Building Inspector but no samples for asbestos in dusts were authorized for this project. Based on their visual inspection and experience from similar buildings, the inspector determined that the typical settled and concealed dusts are not "asbestos debris" from an asbestos-containing building material (ACBM). Based on similar sampling from similar buildings, the inspector also determined that the dusts are unlikely to contain more than one percent (1%) asbestos by weight, and therefore are not an asbestos-containing material (ACM).

3. Lead-Containing Materials

Lead-Testing

EHS-Alaska tested paint and other materials throughout the accessible areas of the building using a Heuresis XRF lead paint analyzer. Lead in paints tested varied from a trace amount to 0.36 mg/cm². Lead in other materials tested varied from a trace amount to 21.34 mg/cm². Refer to the Lead Analyzer Test Results Table in Appendix B that identifies the surfaces tested, and the results. The Lead Test Locations are shown in the Drawings in Appendix C.

Paints

There were varying lead contents found in the paints, based on what surfaces they are on, with most surfaces containing little lead (but are still classified as lead-containing materials by OSHA). The highest levels of lead were found on doors, walls, structural members and miscellaneous steel, with lower levels on walls and other painted surfaces, and lowest levels on pre-finished materials.

Lead based paints (paint containing more than 1.0 mg/cm² of lead) were not identified. It is anticipated that other items, including older structural steels which are hidden, concealed, or otherwise not tested may be painted with lead-based paint. Lead was detected at very low levels in most of the painted floor, wall and ceiling surfaces. XRF testing is not able to "prove" that "no" lead exists in the paint. Low levels of lead found by XRF testing does not mean that the paints are free of lead, the paints may contain lead. However, these paints may not present a hazard to occupants or workers performing renovation or demolition if lead-safe work practices are followed.

Ceramic Wall Tile and Glazing

Relatively high concentrations of lead were found in the glazing of ceramic plumbing fixtures. The glazing of bathroom sinks, toilets, etc. contained high lead levels. The concentrations of lead in ceramic glazing compounds should not be compared to lead-based paint criteria, as the glazing is inherently less likely to cause lead to be present in dusts or on surfaces, where it can be ingested. Lead in ceramic tile glazing may not pose a hazard to occupants, or workers performing renovation or demolition if lead-safe work practices are followed. All ceramic tiles and fixtures in the facility should be assumed to contain lead.

Plastic Components

Relatively high concentrations of lead were found in plastic components, such as "Formica" plastic laminate panels. The concentrations of lead in plastic compounds should not be compared to lead-based paint criteria. Lead in plastic compounds may have surface deterioration and if not cleaned regularly, lead may be present in dusts or on surfaces, where it can be ingested. Lead in plastic compounds may not pose a hazard to occupants, or workers performing renovation or demolition if good work practices are followed.

Metallic Lead in X-Ray Shielding, Batteries, Pipe Solder and Flashing

Metallic lead items identified in the building included sheet lead x-ray shielding around x-ray rooms, including at doors, and high-lead content window glass, lead soldering at the sheet metal roof flashings, lead solder at copper piping, and poured lead sealants at bell and spigot joints of waste and vent piping and lead acid batteries in emergency lights and other battery backup equipment. If removed during renovation or demolition they should be recycled or disposed of as hazardous waste.

Settled and Concealed Dust

The settled and concealed dusts were examined but no samples for lead in dusts were authorized for this project. Based on their visual inspection and similar sampling from similar buildings, the inspector also determined that the dusts are likely to have measurable concentrations of lead in the dusts.

4. PCB-Containing Materials**Light Ballasts**

Older fluorescent lights typically have PCB-containing ballasts. PCB-containing ballasts in fluorescent lights were banned in 1978, but manufacturers were allowed to use up existing stocks, and lights may have been reused from other facilities. The survey included examination of what were considered to be representative light fixtures, but not all fixtures were able to be accessed. All lights shall be inspected during removal or relocation. Unless ballasts were marked "No PCBs," they must be assumed to contain PCBs and must be disposed of as a hazardous waste when removed for disposal. Fluorescent light fixtures with PCB-containing ballasts are assumed to be present in the building in the older portions. If removed during renovation or demolition, the fluorescent light fixtures will need to be inspected for PCB-containing ballasts or contamination, and disposed of accordingly.

Older HID lights may have PCB-containing ballasts. Due to height restrictions and sealed ballast enclosures, the HID fixtures were not able to be accessed. All HID lights shall be inspected during removal or relocation. If ballasts are not marked "No PCBs," we suggest contacting the manufacturer of the lights to determine if the ballasts contain PCB's, or assume that they contain PCB's and be disposed of as a hazardous waste. If removed during renovation or demolition, the HID Lights will need to be inspected for PCB-containing ballasts or contamination, and disposed of accordingly.

Bulk Products

Some older paints, sealants and other building materials may contain measurable amounts of PCB's. PCB use in paints and sealants was supposed to have been discontinued in 1979. The EPA does not require the sampling of bulk products, and no sampling of "Bulk Products" were authorized for this project.

5. Mercury-Containing Materials**Fluorescent Lamps**

Fluorescent lamps use mercury to excite the phosphor crystals that coat the inside of the lamp. These lamps contain from 15 to 48 milligrams of mercury depending on their age and manufacturer. If removed during renovation or demolition, the mercury-containing compact or linear tube lamps should be disposed of as Universal Wastes.

Thermostats

Older thermostats or other electrical switches that may contain mercury were noted in the building.

High Intensity Discharge Lamps

High Intensity Discharge (HID) lamps use mercury and sodium vapors in the lamp, and also typically have lead-containing solders at the bases. These lamps contain varying amounts of mercury depending on their age and manufacturer. If removed during renovation or demolition, the mercury-containing HID lamps should be disposed of as Universal Wastes..

All mercury-containing items being removed by this project are required to be disposed of as hazardous waste or recycled.

6. Other Hazardous Materials

Self-Illuminating Exit Signs and Smoke Detectors

Several radioactive, self-illuminating exit signs and smoke detectors were found in the building. If any radioactive items are removed, they are required be disposed of as hazardous waste or recycled.

Hydraulic Lifts

There was one hydraulic elevator in the 1974 portion. The hydraulic fluids shall be removed and properly disposed of prior to disposal of the metallic portions, or the entire unit may be reused or recycled by the contractor.

Household Chemicals

Common household chemicals, including quantities of construction repair materials, acids, paint products, paint thinners, caustics, cleaners, pesticides, herbicides, disinfectants, poisons, printing and photographic chemicals, , or s (antifreeze), floor or furniture wax, furniture or paint strippers, solvents, fuel, new or used lubrication products, wood preservatives, old medications, resins, adhesives were present in the building. It cannot be determined what will be the fate of those materials at this time.

Soil Contamination

The scope of work for EHS-Alaska, Inc. did not include investigation of soils for petroleum or other contaminations. The dirt soil of the crawl space under the original portion of the building was noted to be contaminated by asbestos debris from the asbestos-containing pipe insulation.

Refrigerants

Refrigerators, freezers, ice machines, and water coolers were identified in the building that may contain ozone depleting refrigerants. Air conditioning units may also be present. Ozone depleting substances (ODS) are regulated by the EPA and must be removed by certified technicians prior to equipment disposal.

Heat Transfer Fluids

The existing heating and cooling system is assumed to contain heat transfer fluids, including glycol or other boiler treatment chemicals. Any heat transfer fluids removed from the heating system shall be recovered and properly disposed of or recycled.

E. REGULATORY CONSTRAINTS

1. Asbestos-Containing Materials

The Federal Occupational Safety and Health Administration (29 CFR 1926.1101) and the State of Alaska Department of Labor (8 AAC 61) have promulgated regulations requiring testing for airborne asbestos fibers; setting allowable exposure limits for workers potentially exposed to airborne asbestos fibers; establishing contamination controls, work practices, and medical surveillance; and setting worker certification and protection requirements. These regulations apply to all workplace activities involving asbestos-containing materials.

The EPA regulations, issued as Title 40 of the Code of Federal Regulations, Part 61 (40 CFR 61), Subpart M under the National Emission Standards for Hazardous Air Pollutants (NESHAP), established procedures for handling ACM during asbestos removal and waste disposal. It is recommended that clearance sampling which complies with the EPA's Asbestos Hazard Emergency Response Act (AHERA) protocol be required following removal of asbestos-containing materials to document that the asbestos has been properly removed.

The EPA regulations require an owner (or the owner's contractor) to notify the EPA of asbestos removal operations and to establish responsibility for the removal, transportation, and disposal of asbestos-containing materials.

The disposal of asbestos waste is regulated by the EPA, the Alaska Department of Environmental Conservation, and the disposal site operator. Wastes being transported to the disposal site must be sealed in leak tight containers prior to disposal and must be accompanied by disposal permits and waste manifests.

2. Dusts with Asbestos

Settled and concealed dusts above ceilings, and at other areas that are not routinely cleaned (such as inside ducts and at roofs, etc.) are assumed to have measurable concentrations of asbestos. Based on sampling of similar settled and concealed dusts at similar buildings, those dusts are assumed to contain less than 1 percent asbestos. Normal settled and concealed dusts are distinct and treated differently from debris resulting from damaged asbestos-containing materials.

Background levels of asbestos in dusts for a particular location will depend on many factors, including whether or not asbestos occurs naturally in soils in the area.

Likely sources of asbestos in dusts include natural occurrences of asbestos

The types of asbestos found in settled and concealed dusts often contain actinolite, anthophyllite and tremolite forms of asbestos which are not commonly found in bulk samples taken of materials from buildings. Those forms of asbestos may come from natural occurrences of asbestos in an outside source, such as rock or ore deposits, which appear to be common in Alaska.

Because the type of disturbance, concentration of asbestos in the dusts, cohesiveness of the dusts and room sizes will change, the airborne asbestos levels expected during the project will depend on the contractor's means and methods of conducting the work. The mere presence of asbestos in the dusts does not necessarily imply that a "hazard" exists which would require the use of specially trained workers to "abate" the "hazard". All dusts will likely be required to be removed from the areas where asbestos-containing materials are being removed (abatement areas) in order to achieve clearances. The dusts in the other areas are to be controlled so as to limit worker exposures and prevent contamination of occupied areas of the building.

There is no established correlation between settled or adhered dusts with measurable concentrations of asbestos and airborne concentrations. The definition in the OSHA regulations of asbestos-containing materials as those materials that contain 1 percent or more asbestos by weight, apply to cohesive materials and not to dusts. The OSHA regulations are essentially "performance based", if workers are exposed above the permissible exposure limits, then all of the requirements in the regulations become effective.

3. Lead-Containing Materials

The EPA Standard 40 CFR 745, Lead-Based Paint Poisoning Prevention in Certain Residential Structures, defines lead-based paint hazards and regulates lead based paint activities in target housing and child-occupied facilities. The requirements of this regulation include training certification, pre-work notifications, work practice standards and record keeping. Areas typically classified as child occupied facilities may include but are not limited to: day care facilities, preschools, kindergarten classrooms, restrooms, multipurpose rooms, cafeterias, gyms, libraries and other areas routinely used by children under 6 years of age. Training requirements for Firms (Contractors) and Renovators (Workers) became effective on April 22, 2010. The building is not classified as a child occupied facility, therefore the requirements of 40 CFR 745 do not apply.

Federal OSHA (29 CFR 1926.62) and the State of Alaska (8 AAC Chapter 61) have promulgated regulations that apply to all construction work where employees may be exposed to lead. The disturbance of any surfaces painted with lead-containing paint requires lead-trained personnel, personnel protective procedures, and air monitoring until exposure levels can be determined. If initial monitoring verifies that the work practices being used are not exposing workers, monitoring and protection procedures may be relaxed. Experience has shown that some paints in most buildings will contain low concentrations of lead and disturbance of those paints are still regulated under the OSHA lead standard, 29 CFR 1926.62. Low

levels of lead found by XRF testing does not mean that the paints are free of lead, the paints may contain lead, and OSHA regulations apply anytime measurable amounts of lead are present in paints.

Settled and concealed dust above ceilings, and at other areas that are not routinely cleaned are assumed to have measurable concentrations of lead. Background levels of lead in dusts for a particular location will depend on many factors, including whether or not engines utilizing leaded gasoline were run in or near a building, and upon the age of the building, and thus the age of the dusts. Because the type of disturbance, quantity of lead dusts, cohesiveness of the dusts and room sizes will change, the airborne lead levels expected during the project will depend on the contractor's means and methods of conducting the work. The mere presence of lead in the dusts does not necessarily imply that a "hazard" exists which would require the use of specially trained workers to "abate" the "hazard".

There is no established correlation between settled or adhered lead dust concentrations and airborne concentrations. The OSHA regulations are essentially "performance based", if workers are exposed above the permissible exposure limits, then all of the requirements in the regulations become effective.

The EPA requires that actual construction or demolition debris that contains lead or lead-containing paint or other heavy metals be tested using the TCLP test to determine if the waste must be treated as hazardous waste. All federal, state and local standards regulating lead and lead-containing wastes are required to be followed during the renovation or demolition of portions of this building.

If the TCLP tests done on the waste stream(s) that are produced by the contractor are found to be classified as hazardous wastes, then those waste stream(s) will have to be packaged for shipping and disposal in accordance with hazardous waste and transportation regulations. Because there are no hazardous waste landfills in Alaska, this report assumes that disposal will take place in Seattle or elsewhere in the Pacific Northwest.

4. PCB-Containing Materials

The EPA has promulgated regulations (40 CFR Part 761) that cover the proper handling and disposal of PCB-containing materials. PCB-containing equipment was found by this survey, and any removed PCB-containing equipment is required to be disposed of at fully permitted hazardous waste facilities. The EPA regulates liquid PCBs differently from non-liquid materials. Workers who remove or handle PCB-containing or PCB-contaminated materials or who transport or dispose of PCB wastes must be trained and certified in hazardous waste operations and emergency response (HAZWOPER) as required by 29 CFR 1910.120 and the State of Alaska Department of Labor (8 AAC 61). The Department of Transportation under 49 CFR Parts 100-199 regulates the marking, packaging, handling and transportation of hazardous materials. All federal, state and local standards regulating PCBs and PCB waste must be followed during this project.

5. Mercury-Containing Materials

Thermostats and mercury-containing lamps are classified by the EPA as Universal Wastes. The EPA encourages that all Universal Wastes be recycled in accordance with 40 CFR 273. Mercury and mercury-containing products are considered hazardous waste if TCLP testing of the waste for mercury confirms the mercury content to be greater than the EPA criteria of 0.2 mg/l.

6. Other Hazardous Materials

Refrigerants

Refrigerators, freezers, ice machines, and water coolers were present in the building. Air conditioning systems were also present. Typically, refrigeration and air conditioning systems with ODS shall be maintained in order to prevent discharge of ODS. Systems that are to be removed, or dismantled shall have refrigerants containing ODS recovered and disposed of or recycled in accordance with 40 CFR 82.

Chemical Hazards

The EPA has promulgated regulations (40 CFR Parts 260 to 299 amongst others) that cover the proper handling and disposal of waste chemicals, including listed wastes, which are ignitable, corrosive, reactive, toxic, or an acute hazardous waste or wastes that exhibit the characteristics of toxicity. All construction workers who are required to remove or handle chemical hazards or to transport or dispose of chemical wastes shall be trained and certified as required by the U.S. Department of Labor (29 CFR 1910.120) and the State of Alaska Department of Labor (8 AAC 61). Transportation of chemical hazards are regulated by Department of Transportation regulations under 49 CFR Parts 171 to 178 amongst others.

Waste heat transfer fluids (such as used heating/cooling system glycol or other circulating heating/cooling fluids) are a potentially hazardous waste and are required to be TCLP tested prior to disposal to determine if the fluids are classified as hazardous or non-hazardous waste per the EPA's RCRA regulations governing hazardous wastes. According to a study performed by the University of Northern Iowa, standard TCLP analysis using ICP SW 6010 testing procedures commonly report levels of Arsenic and Selenium over regulatory thresholds due to interferences in the matrix. That report concluded that additional analysis should be performed to refute the presence of Arsenic or Selenium over the regulatory levels by either mass spectrometry using method SW 6020, or by graphite furnace using method SW 7060. Some heat transfer fluids may also contain potentially hazardous additives that modify the properties of the fluids for use in a particular system. It is recommended that the contractor consult with the persons responsible for maintaining the system to determine if any additives that may be potentially hazardous were used in the system to further determine disposal requirements.

Radioactive Materials

Self-luminous products that contain Tritium, Krypton-85, or Promethium-147 are considered radioactive. There are special disposal requirements for products that contain Tritium, Krypton-85, or Promethium-147 that are generally licensed. Data from the Nuclear Regulatory Commission (NRC) indicates that most all Tritium powered exit signs are generally licensed and therefore must be disposed of at a licensed disposal facility or returned to the manufacturer/distributor for disposal. Licensed radioactive products are regulated by Nuclear Regulatory Commission standard 10 CFR 20 and 10 CFR 32. Smoke detectors were present in the project area that may contain a radioactive material. If the detectors are of the ionization type they typically contain a small amount of Americium. If removed during renovation, the detectors should be returned to the owner for reuse or returned to the manufacturer for disposal or recycling. There are no licensed disposal facilities for radioactive wastes in Alaska.

F. RECOMMENDATIONS

Disposal of hazardous materials is often difficult and expensive in Rural Alaska. It is possible to obtain a one-time permit to dispose of non-friable, non-RACM asbestos materials from the Alaska Department of Environmental Conservation, however that process is neither fast nor inexpensive, and is highly dependent on getting permission for an asbestos monofill from a landowner, and may not be financially feasible at many locations. Because Wrangell receives barge services, it is likely to be less expensive to barge out asbestos materials. Lead-containing materials, if they are not also asbestos-containing materials are often possible to dispose of locally, but in general, painted materials, with lead at measurable concentrations, are not allowed to be burned. Lead-containing materials which have been classified as hazardous waste, and chemical hazards are required to be disposed of at permitted landfills, which will require air freight or barge for disposal.

1. Asbestos-Containing Materials

The asbestos-containing materials identified in the building are typically in intact condition and are classified as both friable and non-friable ACM. All asbestos-containing materials that will be disturbed by the planned renovation work are required to be removed by trained asbestos workers.

2. Dusts with Asbestos

Dusts with measurable concentrations of asbestos are assumed to be present, but are not classified as asbestos-containing materials, or as debris from asbestos-containing materials. Workers disturbing dusts

are required to have hazard communication training in accordance with OSHA regulations, but are not required to receive 40 hours of training, which is required for asbestos workers. The contractor will need to choose means and methods to control worker exposures to airborne contaminants. At least an initial exposure assessment or data from previous air monitoring is needed to show that worker exposures are maintained below the OSHA permissible exposure limits (PELs).

3. Lead-Containing Materials

Federal OSHA (29 CFR 1926.62) and the State of Alaska (8 AAC Chapter 61) have promulgated regulations that apply to all construction work where employees may be exposed to lead, including disturbance of paints with low concentrations of lead.

Worker exposure to lead may be able to be controlled below the OSHA permissible exposure limit if proper engineering controls and procedures are used during renovation. Lead is a potentially hazardous waste and the EPA requires that all wastes that contains lead be tested to determine if they must be treated as hazardous waste. A TCLP test of the waste stream(s) produced by the Contractor's means and methods are required to be performed to determine if those wastes will be classified as hazardous or non-hazardous.

4. PCB-Containing Materials

PCB-containing ballasts scheduled for removal or replacement will need to be removed, handled, packaged and disposed of in accordance with all regulations. If any PCB-containing ballasts are discovered, and they are removed or replaced, they will need to be removed, handled, packaged and disposed of in accordance with all regulations.

5. Mercury-Containing Materials

If any mercury-containing materials are removed or replaced, they will need to be removed, handled, packaged and disposed of in accordance with all regulations. If mercury-containing lamps and thermostats are handled and disposed of in accordance with the Universal Waste Regulations, no TCLP test is required. If the Contractor chooses to perform a TCLP test of fluorescent lamps, the test shall be conducted in accordance with the requirements of ANSI/NEMA Standard Procedure for Fluorescent Lamp Sample Preparation and Toxicity Characteristic Leaching Procedure, C78.LL 1256-2003 or latest version.

6. Other Hazardous Materials

If any radioactive materials are removed or replaced, they will need to be removed, handled, packaged and disposed of in accordance with all regulations.

If any ODS are removed or replaced, they will need to be removed, handled, packaged and disposed of in accordance with all regulations.

If any hydraulic fluids are removed or replaced, they will need to be removed, handled, packaged and disposed of in accordance with all regulations.

If any heat transfer fluids are removed or replaced, they will need to be removed, handled, packaged and disposed of in accordance with all regulations.

G. LIMITATIONS

The conclusions and recommendations contained in this report are based upon professional opinions with regard to the subject matter. These opinions have been arrived at in accordance with currently accepted environmental consulting and engineering standards and practices and are subject to the following inherent limitations:

1. Accuracy of Information

The laboratory reports utilized in this assessment were provided by the accredited laboratories cited in this report. Although the conclusions, opinions, and recommendations are based in part, on such information, our services did not include the verification of accuracy or authenticity of such reports. Should such information provided be found to be inaccurate or unreliable, EHS-Alaska, Inc. reserves the right to amend or revise its conclusions, opinions, and/or recommendations.

2. Site Conditions

This limited survey did not include investigation of the entire site and may not be valid outside the survey area. The intent of this survey was to identify common hazardous materials that may be disturbed during routine maintenance or renovations. This survey is not intended to be utilized as the sole design document for abatement. This survey was conducted while the site was occupied. All inspections were performed with furniture, equipment and/or stored items in place. The scope of work for this survey did not include identification of all potentially hazardous materials that may be present at this site, and was limited to the scope of work agreed upon with our client. Although a concerted effort was made to identify those common hazardous materials likely to be affected by this project, some hazardous materials may have been hidden by furniture, equipment or stored items and may not have been identified. The survey investigated representative materials and items, such as lights and mechanical components. Variations may occur between materials and items that appear to be the same, but are actually of different construction or materials. Other asbestos-containing or potentially hazardous materials may be present in the facilities that were concealed by structural members, walls, ceilings or floor coverings, or in materials where testing was not conducted.

3. Changing Regulatory Constraints


The regulations concerning hazardous materials are constantly changing, including the interpretations of the regulations by the local and national regulating agencies. Should the regulations or their interpretation be changed from our current understanding, EHS-Alaska, Inc. reserves the right to amend or revise its conclusions, opinions, and/or recommendations.

APPENDIX A

Asbestos Bulk Sample Field Survey Data Sheets and Laboratory Reports

RECEIVED

OCT 08 2020



EHS-ALASKA, INC.

EHS ALASKA
INCORPORATED

EHS Alaska, Inc.

11901 Business Blvd., Suite 208, Eagle River, AK 99577

(907) 694-1383 • (907) 694-1382 fax

e-mail • ehsak@ehs-alaska.com


PROJECT NO: 7795-03	PROJECT NAME: Wrangell Medical Center	FACILITY: Wrangell Medical Center	COLLECTION DATE: 09-14-2020
-------------------------------	---	---	---------------------------------------

CHAIN OF CUSTODY RECORD

ANALYSIS REQUESTED:	<input type="checkbox"/> PLM BULK <input type="checkbox"/> LEAD DUST <input type="checkbox"/> TEM MICROVAC DUST (ASTM 5756)	<input type="checkbox"/> PLM DUST <input type="checkbox"/> LEAD TCLP	<input type="checkbox"/> TEM BULK <input type="checkbox"/> LEAD PPM	TYPE: <input type="checkbox"/> ASBESTOS <input type="checkbox"/> LEAD	TURNAROUND: 2 DAYS	DISPOSAL: NORMAL	QUANTITY: 100 30
COLLECTED BY (signature) <i>Robert A. French</i>		IATL SELECTED LABORATORY		SPECIAL INSTRUCTIONS / COMMENTS:			
PRINTED NAME Robert A. French		SAMPLES ACCEPTED BY		LAB: RETURN A SIGNED COPY OF THIS FORM WITH THE FINAL REPORT TO EHS-ALASKA, INC.			
CERT# / AHERA# 1564 88IMP-0028		DATE/TIME SEP 25 2020		See sample location drawing for more detailed explanation of exact locations.			
SHIPPING METHOD Fed Ex		ANALYST'S SIGNATURE <i>[Signature]</i>		9/25/20			
COURIER (signature) <i>[Signature]</i>		DATE		70 Asbestos			
DATE/TIME							

FIELD SURVEY DATA

EHS SAMPLE NO. LAB ID NO	SAMPLE DESCRIPTION. (COLOR, MATERIAL TYPE, LAYERS, FRIABILITY)	LOCATION/COMMENTS (INCLUDING PHOTO/XREF)	RESULTS FOR EHS-ALASKA USE ONLY
WMS0920-A01 7067217	White, Chalky "Hard Fitting" insulation	Attic Fan room in 1967 Era. On white pipe above fan unit near Hatch. Photo B72	3.2% Chrysotile 2.2% Crocidolite 1% amosite
WMS0920-A02 7067218	White, Chalky "Hard Fitting" insulation	Attic Fan room in 1967 Era. On loose yellow painted insulation in plastic box near Hatch. Photo B73	3.4% Chrysotile 2.4% Crocidolite 1.2% amosite
WMS0920-A03 7067219	White, Chalky "Hard Fitting" insulation	Attic Fan room in 1967 Era. Broken elbow near fan-coil. Photo B74	3.0% Chrysotile 6% amosite
WMS0920-A04 7067220	Gray sticky sealant in HVAC Unit	Attic Fan room in 1967 Era. Filter bank chamber downstream of the Heat Recovery Wheel. Photo R575	3.4% Chrysotile
WMS0920-A05 7067221	Joint compound at Ceiling	Attic Fan room in 1967 Era. Ceiling above Fan Unit Photo B75	1.6% Chrysotile
WMS0920-A06 7067222	GCT-1; 12x12 Ceiling tiles with dark brown mastic	Attic Fan room in 1967 Era. Loose, stored tiles "in case they are needed". Photo B76	None Detected both layers
WMS0920-A07 7067223	GCT-1; 12x12 Ceiling tiles with dark brown mastic	Attic Fan room in 1967 Era. Loose, stored tiles "in case they are needed". Photo B77	None Detected both layers
WMS0920-A08 7067224	Gray sticky sealant in HVAC Unit	Attic Fan room in 1967 Era. Filter bank chamber downstream of the Heat Recovery Wheel. No photo	3.2% Chrysotile
WMS0920-A09 7067225	Gray sticky sealant at ductwork	Attic Fan room in 1967 Era. At shiny ducts of Kitchen Exhaust Fan. Photo B78	3.4% Chrysotile



EHS ALASKA
INCORPORATED

EHS Alaska, Inc.

11901 Business Blvd., Suite 208, Eagle River, AK 99577

(907) 694-1383 • (907) 694-1382 fax

e-mail • ehsak@ehs-alaska.com

PROJECT NO: 7795-03	PROJECT NAME: Wrangell Medical Center	FACILITY: Wrangell Medical Center	COLLECTION DATE: 09-14-2020
-------------------------------	---	---	---------------------------------------

FIELD SURVEY DATA			
EHS SAMPLE NO. LAB ID NO	SAMPLE DESCRIPTION, (COLOR, MATERIAL TYPE, LAYERS, FRIABILITY)	LOCATION/COMMENTS (INCLUDING PHOTO/XREF)	RESULTS FOR EHS-ALASKA USE ONLY
WMS0920-A10 7067226	Gray sticky sealant in HVAC Unit	Attic Fan room in 1967 Era. Filter bank chamber for Fan 10016. Photos R601, 602	3.4% Chrysotile
WMS0920-A11 7067227	Dark Brown mastic for TJI Wood joists Ignore wood layer!	Attic, Joists of the 1988 roof structure. Near peak of the roof above the 1967 era. Photo B88	None Detected
WMS0920-A12 7067228	Dark Brown mastic for TJI Wood joists Ignore wood layer!	Attic, Joists of the 1988 roof structure. Near peak of the roof above the 1967 era. Photo B89	None Detected
WMS0920-A13 7067229	Joint Compound	Attic. On exterior "wall" of the 1967 fan rom, but likely installed in 1988. Photo B90	None Detected
WMS0920-A14 7067230	Tar Paper under 1988 metal Roof	Attic, at hole for Boiler stack through the 1988 roof. Photo R 639	None Detected
WMS0920-A15 7067231	Brown hard insulation of "Van Packer" boiler stack	Attic. Appears to be original 1967 stack. Photo R 640 & 41	40% Chrysotile
WMS0920-A16 7067232	White fabric and Black Tar sealant	Attic above PT. Remnant of temporary roof over 1988 modular buildings. At Duct penetration. Photo B91	3.4% Chrysotile
WMS0920-A17 7067233	White fabric and Black Tar sealant	Attic above PT. Remnant of temporary roof over 1988 modular buildings. At Duct penetration. Photo R655 & 656	None Detected
WMS0920-A18 7067234	GCT 12x12 Ceiling tiles with dark brown mastic. "PyROTECT on back.	Attic above PT. Loose, stored tiles "in case they are needed". Photo B95	None Detected both layers
WMS0920-A19 7067235	GCT 12x12 Ceiling tiles with dark brown mastic. "PyROTECT on back.	Attic above PT. Loose, stored tiles "in case they are needed". Photo B97	None Detected both layers
WMS0920-A20 7067236	Black tarry coating inside old Pace Exhaust Fan	Attic above boiler room. Fan appears to be abandoned. Photo R633 & 638	5.2% Chrysotile
WMS0920-A21 7067237	Cream Window Frame Sealant, between frame and (missing) siding (21" x 5'-6")	Attic above PT. Loose stored windows. Likely to be from the 1974 Dayroom. Photo R670	4.1% Chrysotile
WMS0920-A22 7067238	Cream Window Frame Sealant, between frame and (missing) siding (21" x 5'-6")	Attic above PT. Loose stored windows. Likely to be from the 1974 Dayroom. Photo R670	3.8% Chrysotile
WMS0920-A23 7067239	Lighter yellow-white window glazing compound at edge of glass (21" x 5'-6")	Attic above PT. Loose stored windows. Likely to be from the 1974 Dayroom. Photo R671 & 2	1.6% Chrysotile

Asbestos

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated
11901 Business Blvd., Ste 208
Eagle River AK 99577

Report Date: 9/25/2020
Report No.: 620075 - PLM
Project: Wrangell Medical Center
Project No.: 7795-03

Client: EHS511

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7067217
Client No.: WMS0920-A01

Analyst Observation: White Insulation
Client Description: White, Chalky "Hard Fitting" Insulation

Location: Attic Fan Room in 1967 Era. On White Pipe Above Fan Unit Near Hatch. - Photo B72

Percent Asbestos:
PC 3.2 Chrysotile
PC 2.2 Crocidolite
PC 1 Amosite

Percent Non-Asbestos Fibrous Material:
30 Fibrous Glass

Facility:
Percent Non-Fibrous Material:
63.6

Lab No.: 7067218
Client No.: WMS0920-A02

Analyst Observation: White Insulation
Client Description: White, Chalky "Hard Fitting" Insulation

Location: Attic Fan Room in 1967 Era. On Loose Yellow Painted Insulation in Plastic Box Near Hatch. - Photo B7

Percent Asbestos:
PC 3.4 Chrysotile
PC 2.4 Crocidolite
PC 1.2 Amosite

Percent Non-Asbestos Fibrous Material:
30 Fibrous Glass

Facility:
Percent Non-Fibrous Material:
63

Lab No.: 7067219
Client No.: WMS0920-A03

Analyst Observation: White/Yellow Insulation
Client Description: White, Chalky "Hard Fitting" Insulation

Location: Attic Fan Room in 1967 Era. Broken Elbow Near Fan-Coil. - Photo B74

Percent Asbestos:
30 Chrysotile
PC 6 Amosite

Percent Non-Asbestos Fibrous Material:
30 Fibrous Glass

Facility:
Percent Non-Fibrous Material:
34

Lab No.: 7067220
Client No.: WMS0920-A04

Analyst Observation: Grey/Black Caulk
Client Description: Grey Sticky Sealant In HVAC Unit


Location: Attic Fan Room in 1967 Era. Filter Bank Chamber Downstream of the Heat Recovery Wheel. - Photo R575


Percent Asbestos:
PC 3.4 Chrysotile

Percent Non-Asbestos Fibrous Material:
2 Talc

Facility:
Percent Non-Fibrous Material:
94.6

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 9/25/2020
Date Analyzed: 09/25/2020
Signature: 
Analyst: Michael Moore

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated
11901 Business Blvd., Ste 208
Eagle River AK 99577

Report Date: 9/25/2020
Report No.: 620075 - PLM
Project: Wrangell Medical Center
Project No.: 7795-03

Client: EHS511

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7067221 **Analyst Observation:** White Joint Compound
Client No.: WMS0920-A05 **Client Description:** Joint Compound at Ceiling
Location: Attic Fan Room in 1967 Era.
Ceiling Above Fan Unit. - Photo B75
Facility:
Percent Asbestos: **Percent Non-Asbestos Fibrous Material:**
PC 1.6 Chrysotile None Detected **Percent Non-Fibrous Material:**
98.4


Lab No.: 7067222 **Analyst Observation:** Beige Ceiling Tile
Client No.: WMS0920-A06 **Client Description:** GCT-1; 12x12 Ceiling Tiles With Dark
Brown Mastic
Location: Attic Fan Room in 1967 Era.
Loose Stored Tiles "In Case They Are
Needed". - Photo B77
Facility:
Percent Asbestos: **Percent Non-Asbestos Fibrous Material:**
None Detected 50 Fibrous Glass **Percent Non-Fibrous Material:**
30 Cellulose 20


Lab No.: 7067222(L2) **Analyst Observation:** Brown Mastic
Client No.: WMS0920-A06 **Client Description:** GCT-1; 12x12 Ceiling Tiles With Dark
Brown Mastic
Location: Attic Fan Room in 1967 Era.
Loose Stored Tiles "In Case They Are
Needed". - Photo B77
Facility:
Percent Asbestos: **Percent Non-Asbestos Fibrous Material:**
None Detected 2 Fibrous Glass **Percent Non-Fibrous Material:**
98

Lab No.: 7067223 **Analyst Observation:** Beige Ceiling Tile
Client No.: WMS0920-A07 **Client Description:** GCT-1; 12x12 Ceiling Tiles With Dark
Brown Mastic
Location: Attic Fan Room in 1967 Era.
Loose Stored Tiles "In Case They Are
Needed". - Photo B77
Facility:
Percent Asbestos: **Percent Non-Asbestos Fibrous Material:**
None Detected 50 Fibrous Glass **Percent Non-Fibrous Material:**
30 Cellulose 20

Lab No.: 7067223(L2) **Analyst Observation:** Brown Mastic
Client No.: WMS0920-A07 **Client Description:** GCT-1; 12x12 Ceiling Tiles With Dark
Brown Mastic
Location: Attic Fan Room in 1967 Era.
Loose Stored Tiles "In Case They Are
Needed". - Photo B77
Facility:
Percent Asbestos: **Percent Non-Asbestos Fibrous Material:**
None Detected 2 Fibrous Glass **Percent Non-Fibrous Material:**
98

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 9/25/2020
Date Analyzed: 09/25/2020
Signature: 
Analyst: Michael Moore

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director


CERTIFICATE OF ANALYSIS


Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 9/25/2020 Report No.: 620075 - PLM Project: Wrangell Medical Center Project No.: 7795-03
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7067224 Client No.: WMS0920-A08	Analyst Observation: Grey Sealant Client Description: Grey Sticky Sealant In HVAC Unit	Location: Attic Fan Room in 1967 Era. Filter Bank Chamber Downstream of the Heat Recovery Wheel. - No Photo Facility: <u>Percent Non-Fibrous Material:</u> 96.8
<u>Percent Asbestos:</u> PC 3.2 Chrysotile	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	
Lab No.: 7067225 Client No.: WMS0920-A09	Analyst Observation: Grey Sealant Client Description: Grey Sticky Sealant at Duct Work	Location: Attic Fan Room in 1967 Era. At Shiny Ducts of Kitchen Exhaust Fan. - Photo B78 Facility: <u>Percent Non-Fibrous Material:</u> 96.6
<u>Percent Asbestos:</u> PC 3.4 Chrysotile	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	
Lab No.: 7067226 Client No.: WMS0920-A10	Analyst Observation: Grey Sealant Client Description: Grey Sticky Sealant in HVAC Unit	Location: Attic Fan Room in 1967 Era. Filter Bank Chamber for Fam 10016. - Photo's R601, 602 Facility: <u>Percent Non-Fibrous Material:</u> 96.6
<u>Percent Asbestos:</u> PC 3.4 Chrysotile	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	
Lab No.: 7067227 Client No.: WMS0920-A11	Analyst Observation: Dk Brown Mastic Client Description: Dark Brown Mastic for TJI Wood Joists (Ignore Wood Layer))	Location: Attic Joists of the 1988 Roof Structure. Near Peak of the Roof Above the 1967 Era. - Photo B88 Facility: <u>Percent Non-Fibrous Material:</u> 100
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	
Lab No.: 7067228 Client No.: WMS0920-A12	Analyst Observation: Dk Brown Mastic Client Description: Dark Brown Mastic for TJI Wood Joists (Ignore Wood Layer))	Location: Attic Joists of the 1988 Roof Structure. Near Peak of the Roof Above the 1967 Era. - Photo B88 Facility: <u>Percent Non-Fibrous Material:</u> 100
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 9/25/2020
Date Analyzed: 09/25/2020
Signature: 
Analyst: Michael Moore

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director


CERTIFICATE OF ANALYSIS


Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 9/25/2020 Report No.: 620075 - PLM Project: Wrangell Medical Center Project No.: 7795-03
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7067229 Client No.: WMS0920-A13	Analyst Observation: White Joint Compound Client Description: Joint Compound	Location: Attic. On Exterior "Wall" of the 1967 Fan Room, But Likely Installed in 1988. - Photo B90 Facility: Percent Non-Fibrous Material: 100
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	
Lab No.: 7067230 Client No.: WMS0920-A14	Analyst Observation: Black Tar Paper Client Description: Tar Paper Under 1988 Metal Roof	Location: Attic, at Hole for Boiler Stack Through the 1988 Roof. - Photo R639 Facility: Percent Non-Fibrous Material: 70
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 30 Cellulose	
Lab No.: 7067231 Client No.: WMS0920-A15	Analyst Observation: Grey/Tan Insulation Client Description: Brown Hard Insulation of "Van Packer" Boiler Stack	Location: Attic, Appears to be Original 1967 Stack. - Photo 640 & 41 Facility: Percent Non-Fibrous Material: 60
<u>Percent Asbestos:</u> <i>40 Chrysotile</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	
Lab No.: 7067232 Client No.: WMS0920-A16	Analyst Observation: Black/White Sealant Client Description: White Fabric and Black Tar Sealant	Location: Attic, Above PT. Remnant of Temporary Roof Over 1988 Modular Buildings. At Duct Penetration. - Photo Facility: Percent Non-Fibrous Material: 96.6
<u>Percent Asbestos:</u> <i>PC 3.4 Chrysotile</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	
Lab No.: 7067233 Client No.: WMS0920-A17	Analyst Observation: Black Sealant Client Description: White Fabric and Black Tar Sealant	Location: Attic, Above PT. Remnant of Temporary Roof Over 1988 Modular Buildings. At Duct Penetration. - Photo Facility: Percent Non-Fibrous Material: 98
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 2 Cellulose	

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 9/25/2020
Date Analyzed: 09/25/2020
Signature: 
Analyst: Michael Moore

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 9/25/2020 Report No.: 620075 - PLM Project: Wrangell Medical Center Project No.: 7795-03
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7067234 Client No.: WMS0920-A18	Analyst Observation: White/Tan Ceiling Tile Client Description: GCT 12x12 Ceiling Tiles With Dark Brown Mastic "PyROTECT" on Back	Location: Attic, Above PT. Loose Stored Tiles "In Case They Are Needed". - Photo B95
---	--	---

<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 80 Cellulose	Facility: <u>Percent Non-Fibrous Material:</u> 20
--	---	--

Lab No.: 7067234(L2) Client No.: WMS0920-A18	Analyst Observation: Brown Mastic Client Description: GCT 12x12 Ceiling Tiles With Dark Brown Mastic "PyROTECT" on Back	Location: Attic, Above PT. Loose Stored Tiles "In Case They Are Needed". - Photo B95
---	--	---

<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 5 Talc	Facility: <u>Percent Non-Fibrous Material:</u> 95
--	---	--

Lab No.: 7067235 Client No.: WMS0920-A19	Analyst Observation: White/Tan Ceiling Tile Client Description: GCT 12x12 Ceiling Tiles With Dark Brown Mastic "PyROTECT" on Back	Location: Attic, Above PT. Loose Stored Tiles "In Case They Are Needed". - Photo B97
---	--	---

<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 80 Cellulose	Facility: <u>Percent Non-Fibrous Material:</u> 20
--	---	--


Lab No.: 7067235(L2) Client No.: WMS0920-A19	Analyst Observation: Brown Mastic Client Description: GCT 12x12 Ceiling Tiles With Dark Brown Mastic "PyROTECT" on Back	Location: Attic, Above PT. Loose Stored Tiles "In Case They Are Needed". - Photo B97
---	--	---


<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 5 Talc	Facility: <u>Percent Non-Fibrous Material:</u> 95
--	---	--

Lab No.: 7067236 Client No.: WMS0920-A20	Analyst Observation: Black Tar Client Description: Black Tarry Coating Inside Old Pace Exhaust Fan	Location: Attic Above Boiler Room. Fan Appears to be Abandoned. - Photo R633 & 638
---	---	---

<u>Percent Asbestos:</u> PC 5.2 Chrysotile	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	Facility: <u>Percent Non-Fibrous Material:</u> 94.8
--	--	--

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 9/25/2020
Date Analyzed: 09/25/2020
Signature: 
Analyst: Michael Moore

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 9/25/2020 Report No.: 620075 - PLM Project: Wrangell Medical Center Project No.: 7795-03
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7067237 Client No.: WMS0920-A21	Analyst Observation: Off-White Sealant Client Description: Cream Window Frame Sealant, Between Frame and (Missing) Siding (21" x 5' - 6")	Location: Attic Above PT. Loose Stored Windows. Likely to be From the 1974 Dayroom. - Photo R670
---	--	---

<u>Percent Asbestos:</u> PC 4.1 Chrysotile	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 95.9
--	--	--

Lab No.: 7067238 Client No.: WMS0920-A22	Analyst Observation: Off-White Sealant Client Description: Cream Window Frame Sealant, Between Frame and (Missing) Siding (21" x 5' - 6")	Location: Attic Above PT. Loose Stored Windows. Likely to be From the 1974 Dayroom. - Photo R670
---	--	---

<u>Percent Asbestos:</u> PC 3.8 Chrysotile	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 96.2
--	--	--

Lab No.: 7067239 Client No.: WMS0920-A23	Analyst Observation: Off-White Glazing Client Description: Lighter Yellow-White Window Glazing Compound at Edge of Glass (21" x 5'-6")	Location: Attic Above PT. Loose Stored Windows. Likely to be From the 1974 Dayroom. - Photo R671 & 2
---	---	---

<u>Percent Asbestos:</u> PC 1.6 Chrysotile	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 98.4
--	--	--


Lab No.: 7067240 Client No.: WMS0920-A24	Analyst Observation: Grey/White Glazing Client Description: Grey Sticky Window Glazing Compound at Edge of Glass (21" x 5'-6")	Location: Attic Above PT. Loose Stored Windows. Likely to be From the 1974 Dayroom. - Photo R671 & 2
---	---	---


<u>Percent Asbestos:</u> PC 2.4 Chrysotile	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 97.6
--	--	--

Lab No.: 7067241 Client No.: WMS0920-A25	Analyst Observation: Off-White Glazing Client Description: Cream, Hard Window Glazing Compound at Edge of Glass (21" x 7'-8")	Location: Attic Above PT. Loose Stored Glass. - Photo R676 & 7
---	--	---

<u>Percent Asbestos:</u> PC 4.2 Chrysotile	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 95.8
--	--	--

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 9/25/2020
Date Analyzed: 09/25/2020
Signature: 
Analyst: Michael Moore

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 9/25/2020 Report No.: 620075 - PLM Project: Wrangell Medical Center Project No.: 7795-03
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7067242 Client No.: WMS0920-A26	Analyst Observation: White Sealant Client Description: White Sealant at Round Adjustable Duct	Location: Attic Above PT. Loose Stored Duct. - Photo R678 Facility: Percent Non-Fibrous Material: 90
Percent Asbestos: <i>None Detected</i>	Percent Non-Asbestos Fibrous Material: 10 Talc	


Lab No.: 7067243 Client No.: WMS0920-A27	Analyst Observation: White Sealant Client Description: White Sealant at Round Adjustable Duct	Location: Attic Above Reception Area. Active Duct. - Photo B100 Facility: Percent Non-Fibrous Material: 90
Percent Asbestos: <i>None Detected</i>	Percent Non-Asbestos Fibrous Material: 10 Talc	


Lab No.: 7067244 Client No.: WMS0920-A28	Analyst Observation: White Insulation Client Description: Chalky White Hard Fitting Insulation	Location: Attic Above Surgery Area. Debris on Ceiling. - Photo B101 Facility: Percent Non-Fibrous Material: 80
Percent Asbestos: <i>15 Chrysotile PC 5 Amosite</i>	Percent Non-Asbestos Fibrous Material: None Detected	

Lab No.: 7067245 Client No.: WMS0920-A29	Analyst Observation: Black Tar Paper Client Description: Tarry Craft Paper From Behind Cedar Shingle Siding	Location: Attic. Former Exterior Wall of 1974 Era. - B102 Facility: Percent Non-Fibrous Material: 70
Percent Asbestos: <i>None Detected</i>	Percent Non-Asbestos Fibrous Material: 30 Cellulose	

Lab No.: 7067246 Client No.: WMS0920-A30	Analyst Observation: Red Sealant Client Description: Red Duct Sealant	Location: Attic Above 1967 Era. Loose Duct in Attic Space. - Photo R734 Facility: Percent Non-Fibrous Material: 92.6
Percent Asbestos: <i>PC 4.4 Chrysotile</i>	Percent Non-Asbestos Fibrous Material: 3 Talc	

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 9/25/2020
Date Analyzed: 09/25/2020
Signature: 
Analyst: Michael Moore

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated
11901 Business Blvd., Ste 208
Eagle River AK 99577

Report Date: 9/25/2020
Report No.: 620075 - PLM
Project: Wrangell Medical Center
Project No.: 7795-03

Client: EHS511

Appendix to Analytical Report

Customer Contact: Cali Swatowski

Method: 40 CFR Appendix E to Subpart E of Part 763, interim method for the Determination of Asbestos in Bulk Insulation Samples, and USEPA 600, R93-116 as needed.

This appendix seeks to promote greater understanding of any observations, exceptions, special instructions, or circumstances that the laboratory needs to communicate to the client concerning the above samples. The information below is used to help promote your ability to make the most informed decisions for you and your customers. Please note the following points of contact for any questions you may have.

iATL Customer Service: customerservice@iatl.com

iATL Office Manager: wchampion@iatl.com

iATL Account Representative: Semih Kocahasan

Sample Login Notes: See Batch Sheet Attached

Sample Matrix: Bulk Building Materials

Exceptions Noted: See Following Pages

General Terms, Warrants, Limits, Qualifiers:

General information about iATL capabilities and client/laboratory relationships and responsibilities are spelled out in iATL policies that are listed at www.iATL.com and in our Quality Assurance Manual per ISO 17025 standard requirements. The information therein is a representation of iATL definitions and policies for turnaround times, sample submittal, collection media, blank definitions, quantification issues and limit of detection, analytical methods and procedures, sub-contracting policies, results reporting options, fees, terms, and discounts, confidentiality, sample archival and disposal, and data interpretation.

iATL warrants the test results to be of a precision normal for the type and methodology employed for each sample submitted. iATL disclaims any other warrants, expressed or implied, including warranty of fitness for a particular purpose and warranty of merchantability. iATL accepts no legal responsibility for the purpose for which the client uses test results. Any analytical work performed must be governed by our Standard Terms and Conditions. Prices, methods and detection limits may be changed without notification. Please contact your Customer Service Representative for the most current information.

This confidential report relates only to those item(s) tested and does not represent an endorsement by NIST-NVLAP, AIHA LAP LLC, or any agency of local, state or province governments nor of any agency of the U.S. government.

This report shall not be reproduced except in full, without written approval of the laboratory.

Information Pertinent to this Report:

Analysis by US EPA 600 93-116: Determination of Asbestos in Bulk Building Materials by Polarized Light Microscopy (PLM).

Certifications:

- NIST-NVLAP No. 101165-0
- NYSDOH-ELAP No. 11021
- AIHA-LAP, LLC No. 100188

Quantification at <0.25% by volume is possible with this method. (PC) Indicates Stratified Point Count Method performed. (PC-Trace) means that asbestos was detected but is not quantifiable under the Point Counting regimen. PC Trace represents a <0.25% amount. Analysis includes all distinct separable layers in accordance with EPA 600 Method. If not reported or otherwise noted, layer is either not present or the client has specifically requested that it not be analyzed (ex. analyze until positive instructions). Small asbestos fibers may be missed by PLM due to resolution limitations of the optical microscope. Therefore, PLM is not consistently reliable in detecting asbestos in non-friable organically bound (NOB) materials. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing.

Analytical Methodology Alternatives: Your initial request for analysis may not have accounted for recent advances in regulatory requirements or advances in technology that are routinely used in similar situations for other qualified projects. You may have the option to explore additional analysis for further information. Below are a few options, listed as the matrix followed by the appropriate methodology. Also included are links to more information on our website.

Bulk Building Materials that are Non-Friable Organically Bound (NOB) by Gravimetric Reduction techniques employing PLM and TEM: ELAP 198.6 (PLM-NOB), ELAP 198.4 (TEM-NOB)

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated
11901 Business Blvd., Ste 208
Eagle River AK 99577

Report Date: 9/25/2020
Report No.: 620075 - PLM
Project: Wrangell Medical Center
Project No.: 7795-03

Client: EHS511

Loose Fill Vermiculite Insulation, Attic Insulation, Zonolite (copyright), etc.: US EPA 600 R-4/004 (multi-tiered analytical process)
Sprayed On Insulation/Fireproofing with Vermiculite (SOF-V): ELAP 198.8 (PLM-SOF-V)

Soil, sludge, sediment, aggregate, and like materials analyzed for asbestos or other elongated mineral particles (ex. erionite, etc.): ASTM D7521, CARB 435, and other options available

Asbestos in Surface Dust according to one of ASTM's Methods (very dependent on sampling collection technique – by TEM): ASTM D 5755, D5756, or D6480

Various other asbestos matrices (air, water, etc.) and analytical methods are available.

Disclaimers / Qualifiers:

There may be some samples in this project that have a "NOTE:" associated with a sample result. We use added disclaimers or qualifiers to inform the client about something that requires further explanation. Here is a list with highlighted disclaimers that may be pertinent to this project. For a full explanation of these and other disclaimers, please inquire at customerservice@iatl.com.

- 1) Note: No mastic provided for analysis.
- 2) Note: Insufficient mastic provided for analysis.
- 3) Note: Insufficient material provided for analysis.
- 4) Note: Insufficient sample provided for QC reanalysis.
- 5) Note: Different material than indicated on Sample Log / Description.
- 6) Note: Sample not submitted.
- 7) Note: Attached to asbestos containing material.
- 8) Note: Received wet.
- 9) Note: Possible surface contamination.
- 10) Note: Not building material. 1% threshold may not apply.
- 11) Note: Recommend TEM-NOB analysis as per EPA recommendations.
- 12) Note: Asbestos detected but not quantifiable.
- 13) Note: Multiple identical samples submitted, only one analyzed.
- 14) Note: Analyzed by EPA 600/R-93/116. Point Counting detection limit at 0.080%.
- 15) Note: Analyzed by EPA 600/R-93/116. Point Counting detection limit at 0.125%.
- 16) Note: This sample contains >10% vermiculite mineral. See Appendix for Recommendations for Vermiculite Analysis.

Recommendations for Vermiculite Analysis:

Several analytical protocols exist for the analysis of asbestos in vermiculite. These analytical approaches vary depending upon the nature of the vermiculite mineral being tested (e.g. un-processed gange, homogeneous exfoliated books of mica, or mixed mineral composites). Please contact your client representative for pricing and turnaround time options available.

iATL recommends initial testing using the EPA 600/R-93/116 method. This method is specifically designed for the analysis of asbestos in bulk building materials. It provides an acceptable starting point for primary screening of vermiculite for possible asbestos.

Results from this testing may be inconclusive. EPA suggests proceeding to a multi-tiered analysis involving wet separation techniques in conjunction with PLM and TEM gravimetric analysis (EPA 600/R-04/004).

For New York State customers, NYSDOH requires disclaimers and qualifiers for various vermiculite containing samples that direct analysis via ELAP198.6 and ELAP198.8 for samples that contain >10% vermiculite mineral where ELAP198.6 may be used to evaluate the asbestos content of the material. However, any test result using ELAP198.6 will be reported with the following disclaimer: "ELAP198.6 method does not remove vermiculite and may underestimate the level of asbestos present in a sample containing >10% vermiculite."

Further information on this method and other vermiculite and asbestos issues can be found at the following: Agency for Toxic Substances and Disease Registry (ATSDR) www.atsdr.cdc.gov, United States Geological Survey (USGS) www.minerals.usgs.gov/minerals/, US EPA www.epa.gov/asbestos. The USEPA also has an informative brochure "Current Best Practices for Vermiculite Attic Insulation" EPA 747F03001 May 2003, that may assist the health and remediation professional. NYS customers please follow current NYSDOH ELAP requirements per policy on subject of surfacing and vermiculite, May 6, 2016, Testing Requirements for Surfacing Material Containing Vermiculite (https://www.wadsworth.org/sites/default/files/WebDoc/I198_8_02_2.pdf)

The following is a summary of the analytical process outlines in the EPA 600/R-04/004 Method:

- 1) **Analytical Step/Method:** Initial Screening by PLM, EPA 600R-93/116
Requirements/Comments: Minimum of 0.1 g of sample. ~0.25% for most samples.

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated
11901 Business Blvd., Ste 208
Eagle River AK 99577

Client: EHS511

Report Date: 9/25/2020
Report No.: 620075 - PLM
Project: Wrangell Medical Center
Project No.: 7795-03


2)**Analytical Step/Method:** Wet Separation by PLM Gravimetric Technique, EPA R-04/004
Requirements/Comments: Minimum 50g** of dry sample. Analysis of "Sinks" only.

3)**Analytical Step/Method:** Wet Separation by PLM Gravimetric Technique, EPA R-04/004
Requirements/Comments: Minimum 50g** of dry sample. Analysis of "Floats" only.

4)**Analytical Step/Method:** Wet Separation by TEM Gravimetric Technique, EPA R-04/004
Requirements/Comments: Minimum 50g** of dry sample. Analysis of "Sinks" only.

5)**Analytical Step/Method:** Wet Separation by TEM Gravimetric Technique, EPA R-04/004
Requirements/Comments: Minimum 50g** of dry sample. Analysis of "Suspension" only.
*With advance notice and confirmation by the laboratory.

**Approximately 1 Liter of sample in double-bagged container (~9x6 inch bag of sample).



EHS ALASKA
INCORPORATED

EHS Alaska, Inc.

11901 Business Blvd., Suite 208, Eagle River, AK 99577

(907) 694-1383 • (907) 694-1382 fax

e-mail • ehsak@ehs-alaska.com

PROJECT NO: 7795-03	PROJECT NAME: Wrangell Medical Center	FACILITY: Wrangell Medical Center	COLLECTION DATE: 09-17-2020
-------------------------------	---	---	---------------------------------------

CHAIN OF CUSTODY RECORD

ANALYSIS REQUESTED:	<input checked="" type="checkbox"/> PLM BULK <input type="checkbox"/> PLM DUST <input type="checkbox"/> TEM BULK <input type="checkbox"/> LEAD DUST <input type="checkbox"/> LEAD TCLP <input type="checkbox"/> LEAD PPM <input type="checkbox"/> TEM MICROVAC DUST (ASTM 5756)	TYPE:	TURNAROUND:	DISPOSAL:	QUANTITY:
		<input checked="" type="checkbox"/> ASBESTOS <input type="checkbox"/> LEAD	3 DAYS	NORMAL	92
COLLECTED BY (signature) <i>Robert A. French</i>	SELECTED LABORATORY IATL	SPECIAL INSTRUCTIONS / COMMENTS:			
PRINTED NAME Robert A. French.	SAMPLES ACCEPTED BY	LAB: RETURN A SIGNED COPY OF THIS FORM WITH THE FINAL REPORT TO EHS-ALASKA, INC. See sample location drawing for more detailed explanation of exact locations.			
CERT# / AHERA# 1564 88IMP-0028	DATE/TIME	<i>9% Asbestos None Detected = ND</i>			
SHIPPING METHOD Fed Ex	ANALYST'S SIGNATURE				
COURIER (signature) 7716 9397 3267	DATE				
DATE/TIME Oct 2, 2020, 14:00					

FIELD SURVEY DATA

EHS SAMPLE NO. LAB ID NO	SAMPLE DESCRIPTION, (COLOR, MATERIAL TYPE, LAYERS, FRIABILITY)	LOCATION/COMMENTS (INCLUDING PHOTO/REF)	RESULTS FOR EHS-ALASKA USE ONLY
WMC920-A31 7072792	Gray-green mastic of Stainless Corner Guard	Attic near 1974 era. Loose stored corner guard. Photo B103	None Detected
WMC920-A32 7072793	Built-up Roofing of 1974 era flat roof, with brown perlite board insulation	Attic of 1974 era. Under loose fiberglass at exhaust duct penetration through old roof into attic. Photo B104	20% chrysotile ND in Perlite
WMC920-A33 7072794	Tarry vapor barrier and tar and fesco board	Attic of 1974 era. Bottom of roof assembly at exhaust duct penetration through old roof into attic. Photo R745 & 746	None Detected Both layers
WMC920-A34 7072795	Probably hot mop and fesco board	Attic of 1974 era. Middle layer of fesco board insulation at exhaust duct penetration through old roof into attic. Photo R747	None Detected both layers
WMC920-A35 7072796	Built-up Roofing of 1974 era flat roof with brown perlite board insulation	Attic of 1974 era. Under loose fiberglass at supply duct penetration through old roof into attic. Photo R749	20% Chrysotile in 3 BUR layers. ND in perlite
WMC920-A36 7072797	Tarry vapor barrier and tar and fesco board	Attic of 1974 era. Bottom of roof assembly at supply duct penetration through old roof into attic. Photo R750	None Detected
WMC920-A37 7072798	ATCO Roof patch tar	Attic near 1974 era. Loose 5 gal can of Part # 1823. Photo R733	6.2% chrysotile
WMC920-A38 7072799	Tar paper under T&G Siding	Attic at "exterior" side of original 1967 Fan Room. Photo R762	None Detected
WMC920-A39 7072800	Tar paper and GWB sheathing under T&G Siding	Attic at "exterior" side of original 1967 Fan Room. Photo R763 & 4	None Detected Three layers



EHS ALASKA
INCORPORATED

EHS Alaska, Inc.

11901 Business Blvd., Suite 208, Eagle River, AK 99577

(907) 694-1383 • (907) 694-1382 fax

e-mail • ehsak@ehs-alaska.com

PROJECT NO: 7795-03	PROJECT NAME: Wrangell Medical Center	FACILITY: Wrangell Medical Center	COLLECTION DATE: 09-17-2020
-------------------------------	---	---	---------------------------------------

FIELD SURVEY DATA

EHS SAMPLE NO. LAB ID NO	SAMPLE DESCRIPTION, (COLOR, MATERIAL TYPE, LAYERS, FRIABILITY)	LOCATION/COMMENTS (INCLUDING PHOTO/REF)	RESULTS FOR EHS-ALASKA USE ONLY
WMC920-A40 7072801	White silicone sealant at roofing	Metal Roof under valley flashing canopy near main entrance. Photo R782 & 783	None Detected
WMC920-A41 7072802	Gray rubbery roof sealant	Metal Roof sealant under edge flashing, near main entrance. Photo R782 & 783	None Detected
WMC920-A42 7072803	Clear silicone sealant at fascia of roofing	Metal Roof at lap joint of metal drip ledge over EFIS. Photo R787	None Detected
WMC920-A43 7072804	Clear yellow sealant at roofing	Metal Roof, sealant between roofing and metal angle edge flashing into gutter. Photo R786	None Detected
WMC920-A44 7072805	Tar paper under metal roofing	Metal roof, under main roof, over decking. Photo R789	None Detected
WMC920-A45 7072806	Foam Robber filler at roofing	Metal roof, at edge box of roofing. B105	None Detected
WMC920-A46 7072807	Gray sticky putty sealant at roofing	Under metal roof, at edge flashing. B106	None Detected
WMC920-A47 7072808	EFIS Stucco & sealant	At column of main entrance drive-through. Photo B109	None Detected Both layers
WMC920-A48 7072809	GWB. of Soffit	At water damaged at underside of soffit at main entrance drive-through. Photo R791-793	None Detected
WMC920-A49 7072810	Joint compound of soffit	At water damaged at underside of soffit at main entrance drive-through. Photo R791-793	None Detected
WMC920-A50 7072811	Concrete Sacking	Exterior Foundation wall of 1974 Addition, At snap-tie hole. Photo B110	None Detected
WMC920-A51 7072812	Gypsum wall board, joint compound & tape	Ceiling of exterior soffit of walkway going to "morgue door". Photo R807	None Detected Both layers
WMC920-A52 7072813	Gray sticky sealant	Between door frame and concrete of "morgue door" to 1974 era. Photos R805 & 806	None Detected Both layers



EHS Alaska, Inc.

11901 Business Blvd., Suite 208, Eagle River, AK 99577

(907) 694-1383 • (907) 694-1382 fax

e-mail • ehsak@ehs-alaska.com

PROJECT NO: 7795-03	PROJECT NAME: Wrangell Medical Center	FACILITY: Wrangell Medical Center	COLLECTION DATE: 09-17-2020
-------------------------------	---	---	---------------------------------------

FIELD SURVEY DATA

EHS SAMPLE NO. LAB ID NO	SAMPLE DESCRIPTION, (COLOR, MATERIAL TYPE, LAYERS, FRIABILITY)	LOCATION/COMMENTS (INCLUDING PHOTO/XREF)	RESULTS FOR EHS-ALASKA USE ONLY
WMC920-A53 7072814	White window frame sealant	Between window frame and EFIS. Photo B111	<i>None Detected</i>
WMC920-A54 7072815	Harder cream sealant	Sealant at plywood of boarded up window around Air Conditioning Unit. Photo B112 & 113	<i>None Detected</i>
WMC920-A55 7072816	Black Tarry Waterproofing at foundation	In crawl space. At former exterior wall of 1974 addition. Photo R836 & 837	<i>None Detected</i>
WMC920-A56 7072817	Cement asbestos pipe	In crawl space. At capped pipe coming out of soil. Photo B114, R832	<i>10% Chrysotile 10% Crocidolite</i>
WMC920-A57 7072818	Cement asbestos pipe	In crawl space. At active sewer pipe. Photo B118, R841	<i>12% Chrysotile 8% Crocidolite</i>
WMC920-A58 7072819	Hard Fitting insulation	In crawl space. Probably on a hot water pipe. Photo R843 & 845	<i>0.5% Chrysotile 1.2% Crocidolite ND in yellow fiberglass</i>
WMC920-A59 7072820	Hard Fitting insulation	In crawl space, on ground. Photo R855	<i>20% Chrysotile 1.5% Crocidolite</i>
WMC920-A60 7072821	Black Tarry Waterproofing at foundation	At exterior wall of 1974 addition. Photo R885	<i>None Detected</i>
WMC920-A61 7072822	Sticky cream sealant at EFIS	At EFIS over 1974 addition. Between metal frame of louver & EFIS. Photo B119	<i>None Detected</i>
WMC920-A62 7072823	Sticky cream sealant at EFIS	At EFIS over 1988 addition. Between metal frame of window & EFIS. Photo R1674 & 1675	<i>None Detected</i>
WMC920-A63 7072824	Black rubbery glazing at alum windows	Aluminum framed window of 1988 addition. Photo R1674 & 1675	<i>4.5% Chrysotile</i>
WMC920-A64 7072825	Sticky cream sealant at EFIS	At EFIS over 1988 addition. Between GWB soffit & EFIS. Photo R1677	<i>None Detected</i>
WMC920-A65 7072826	Whiter caulking at EFIS	At EFIS over 1988 addition. Between metal generator louver & EFIS. Photo R1678	<i>None Detected</i>



EHS ALASKA
INCORPORATED

EHS Alaska, Inc.

11901 Business Blvd., Suite 208, Eagle River, AK 99577

(907) 694-1383 • (907) 694-1382 fax

e-mail • ehsak@ehs-alaska.com

PROJECT NO:	PROJECT NAME:	FACILITY:	COLLECTION DATE:
7795-03	Wrangell Medical Center	Wrangell Medical Center	09-17-2020
FIELD SURVEY DATA			
EHS SAMPLE NO. LAB ID NO	SAMPLE DESCRIPTION, (COLOR, MATERIAL TYPE, LAYERS, FRIABILITY)	LOCATION/COMMENTS (INCLUDING PHOTO/REF)	RESULTS FOR EHS-ALASKA USE ONLY
WMC920-A66 7072827	Pinkish caulking	At 1988 addition. Between metal generator louver & louver frame. Photo R1679	None Detected
WMC920-A67 7072828	EFIS Stucco & fiberglass mesh	At 1988 addition. At drip edge of EFIS. Photo R1692	None Detected
WMC920-A68 7072829	Clear sealant at window	At 1992 addition. At wood frame to plastic window joint. Photo R1693	None Detected
WMC920-A69 7072830	White sealant at siding	At 1992 addition. At vent pipe penetration of metal siding. Photo R1719	None Detected
WMC920-A70 7072831	White sealant at soffit fascia	At 1992 addition. At lap joint of lower soffit flashing. Photo R1721	None Detected
WMC920-A71 7072832	White sealant at standing seam roof.	At 1992 addition. At folded top seam of rib joints. Photo R1722	None Detected
WMC920-A72 7072833	Tar paper under metal roofing	At 1992 addition. Under main metal roofing. Photo R1724	None Detected
WMC920-A73 7072834	Gray sealant at metal roofing	At 1992 addition. At flashing between metal siding and transition flashing over vestibule roof. Photo R1725	None Detected
WMC920-A74 7072835	Sticky cream sealant at EFIS	At EFIS over 1988 addition. At Fire Dept. Connection. Photo R1680 R 1726 and B223	None Detected
WMC920-A75 7072836	Sticky cream sealant at EFIS	At EFIS over 1967 Orig. Between GWB soffit & EFIS. Photo B224	None Detected
WMC920-A76 7072837	Gypsum board & Joint compound	1992 Addition. Corner of Rm 25, Bulk Storage. Photo R1850	None Detected Three layers
WMC920-A77 7072838	CB-1, 4" gray cove base with cream mastic, joint compound and gypsum wall board	1992 Addition. Corner of Rm 29, Vestibule. Photo R1859	None Detected Five layers
WMC920-A78 7072839	Gypsum wall board & joint compound	1967 era, Sprinkler Room 30, but wall supposedly built with 1988 addition. Photo R1870	None Detected Three layers



EHS ALASKA
INCORPORATED

EHS Alaska, Inc.

11901 Business Blvd., Suite 208, Eagle River, AK 99577

(907) 694-1383 • (907) 694-1382 fax

e-mail • ehsak@ehs-alaska.com

PROJECT NO:	PROJECT NAME:	FACILITY:	COLLECTION DATE:
7795-03	Wrangell Medical Center	Wrangell Medical Center	09-17-2020
FIELD SURVEY DATA			
EHS SAMPLE NO. LAB ID NO	SAMPLE DESCRIPTION. (COLOR, MATERIAL TYPE, LAYERS, FRIABILITY)	LOCATION/COMMENTS (INCLUDING PHOTO/XREF)	RESULTS FOR EHS-ALASKA USE ONLY
WMC920-A79 7072840	Gypsum wall board & joint compound	1967 era, Sprinkler Room 30, 1967 exterior wall. Photo R1871 <i>Composite 0.25%</i>	ND in GWB 2.8% chrysotile in JC
WMC920-A80 7072841	CB-2, 4" green (painted) cove base with dark brown mastic.	1967 era, Sprinkler Room 30, 1967 exterior wall. Appears original. Photo R1871	None Detected both layers
WMC920-A81 7072842	Hard fitting insulation	1967 era, Boiler Rm. 108. On yellow boiler supply pipe. Photo R1918	10% Chrysotile
WMC920-A82 7072843	Hard fitting insulation	1967 era, Boiler Rm. 108. On yellow boiler supply pipe. Photo R1919	10% Chrysotile, Trace Amosite
WMC920-A83 7072844	Hard fitting insulation	1967 era, Boiler Rm. 108. On blue cold water supply. Photos R1908 & 1925	10% Chrysotile, Trace Amosite
WMC920-A84 7072845	Black tarry coating inside ceiling speaker box	1988 era. Staff Lounge, 115. Inside red speaker box. Photos R1940 & 1941	None Detected
WMC920-A85 7072846	LCT-2, 2' x 4' "Galaxy" pattern suspended ceiling tile. Random small fissures	1988 era. Staff Lounge, 115. Main tile in room. Photo R1938	None Detected
WMC920-A86 7072847	CB-2, 4" green (painted) cove base with dark brown mastic & old (on back of CB) & newer Jo(on face of CB) int Compound	1967 era, Elec Rm 34, Possible 1988 wall, but appears original. Photo B229	ND - 3 layers 2.6% chrysotile in joint Comp.
WMC920-A87 7072848	LCT-1, 2' x 4' shallow directional fissures, 1/16" & 1/8" holes	1967 era, but newer tile. Hallway to 1992 addition. Photo B230	None Detected
WMC920-A88 7072849	SV-1, cream sheet vinyl with white shading and tiny brown specks	1967 era, but newer flooring. Hallway to 1992 addition. Photo B231	None Detected both layers
WMC920-A89 7072850	CB-3, Gray 4" cove base with light tan mastic.	1988 addition, Janitor Closet 109. Photo R1958 & 1959	None Detected both layers
WMC920-A90 7072851	SV-2, Cream with small 3/8" & smaller light tan & gray chips, tan mastic	1988 addition, Janitor Closet 109. Photo R1959	None Detected both layers
WMC920-A91 7072852	"Ventglas" Black neoprene duct flexible connector	1967 Penthouse Fan Rm. At exhaust fan #10019. Photo B232 & 233	None Detected
WMC920-A92 7072853	"Ventglas" Black neoprene duct flexible connector	1967 Penthouse Fan Rm. At central AHU. Photo B234	None Detected



EHS ALASKA
INCORPORATED

EHS Alaska, Inc.

11901 Business Blvd., Suite 208, Eagle River, AK 99577

(907) 694-1383 • (907) 694-1382 fax

e-mail • ehsak@ehs-alaska.com

PROJECT NO:	PROJECT NAME:	FACILITY:	COLLECTION DATE:
7795-03	Wrangell Medical Center	Wrangell Medical Center	09-17-2020
FIELD SURVEY DATA			
EHS SAMPLE NO. LAB ID NO	SAMPLE DESCRIPTION. (COLOR, MATERIAL TYPE, LAYERS, FRIABILITY)	LOCATION/COMMENTS (INCLUDING PHOTO/XREF)	RESULTS FOR EHS-ALASKA USE ONLY
WMC920-A93 7072854	SV-1, cream sheet vinyl with white shading and tiny brown specks, brown mastic	1967 era, but newer flooring. Store Rm 102. Photo R1966	None Detected both layers
WMC920-A94 7072855	Leveling compound or "Float" over concrete	1967 era. Store Rm 102. Appears to be 1/2" thick over painted concrete. Photo R1966 & 1967	None Detected
WMC920-A95 7072856	Tar paper between layers of plywood (ignore wood)	1967 era. At hatch in Janitor Closet 38. Appears to be original slipsheet between plywood subfloor and plywood underlayment. Photo R1975	None Detected
WMC920-A96 7072857	Tar mastic? under particle board (ignore wood)	1967 era. At hatch in Janitor Closet 38. Appears to be original black mastic under particle board underlayment. Photo R1975	4.1% Chrysotile
WMC920-A97 7072858	SV-1, cream sheet vinyl with white shading and tiny brown specks, brown mastic, particle board (ignore wood)	1967 era. At hatch in Janitor Closet 38. Top layer over particle board. Photo R1975	None Detected both layers
fast → WMC920-A98 7072859	SV-3, fake wood sheet flooring, white leveling compound, sticky brown contact cement	1988 era, PT Room, 132. At in-floor duct grille by entrance. Photo R1992	None Detected Three layers
WMC920-A99 7072860	White leveling compound, brown mastic	1988 era, PT Room, 132. At in-floor duct grille by entrance. Photo R1992	None Detected both layers
WMC920-A100 7072861	Brown mastic on side of metal duct	1988 era, PT Room, 132. Probably original mastic. At in-floor duct grille by entrance. Photo R1993	None Detected
WMC920-A101 7072862	White seal at ductwork	1988 era, PT Room, 132. At opposed blade damper in relief. Photo R1998	None Detected
WMC920-A102 7072863	Gypsum wall board and joint compound	1988 era, PT Room, 132. At wall above ceiling grid. Nailed-on. Photo R2001	None Detected both layers
WMC920-A103 7072864	SV-2, Cream with small 3/8" & smaller light tan & gray chips, tan mastic (ignore wood)	1988 era, Closet 143. At hatch to crawl space. Photo R2052, 2062	None Detected both layers
WMC920-A104 7072865	CB-3, Gray 4" cove base with cream mastic.	1988 era, Exam Rm 151. Photo R2090	None Detected both layers
WMC920-A105 7072866	Yellow carpet mastic	1988 era, Hallway outside Restroom 142. Photo R2091	None Detected
WMC920-A106 7072867	Yellow carpet mastic & gray leveling compound	1988 Era, Waiting Area 81, by vestibules. Photo B260	None Detected both layers



EHS ALASKA
INCORPORATED

EHS Alaska, Inc.

11901 Business Blvd., Suite 208, Eagle River, AK 99577

(907) 694-1383 • (907) 694-1382 fax

e-mail • ehsak@ehs-alaska.com

PROJECT NO: 7795-03	PROJECT NAME: Wrangell Medical Center	FACILITY: Wrangell Medical Center	COLLECTION DATE: 09-17-2020
-------------------------------	---	---	---------------------------------------

FIELD SURVEY DATA

EHS SAMPLE NO. LAB ID NO	SAMPLE DESCRIPTION. (COLOR, MATERIAL TYPE, LAYERS, FRIABILITY)	LOCATION/COMMENTS (INCLUDING PHOTO/REF)	RESULTS FOR EHS-ALASKA USE ONLY
WMC920-A107 7072868	Joint compound	1988 Era, Waiting Area 81, by corner near Admin 79. Photo B261	None Detected
WMC920-A108 7072869	Gypsum wall board <i>and Joint Compound</i>	1988 Era, Waiting Area 81, by corner near Admin 79. Photo B262	None Detected <i>Both layers</i>
WMC920-A109 7072870	Exterior stucco of EFIS at added walls around Dining/Activity 69 <i>w/white foam</i>	Unknown date, reportedly within the past 10 years. Photo B263	None Detected <i>both layers</i>
WMC920-A110 7072871	Exterior stucco, red sealant of EFIS at added walls around Dining/Activity 69	Unknown date, reportedly within the past 10 years. Photo R2251	None Detected
WMC920-A111 7072872	Black rubber stair tread with brown mastic	1974 era. Base of stairs. Photo R2262	None Detected <i>both layers</i>
WMC920-A112 7072873	Black rubber stair stringer with brown mastic	1974 era. Base of stairs. Photo R2263	<i>10% Chrysotile in Stringer ND in Mastic</i>
WMC920-A113 7072874	Black Sink undercoating	1974 era. Break Rm. 9 Stainless steel sink. Photo R2272	<i>2.6% Chrysotile</i>
WMC920-A114 7072875	"Marlite" and brown mastic	1974 era. Restroom 12. At cleanout. Photo R2277	<i>ND in Marlite Trace chrys. in Mastic</i>
WMC920-A115 7072876	White, chalky fire door insulation	1974 era. Door between back hallway and Laundry 15. UL listed 1.5 hour rating. Photo R2279	<i>60% Chrysotile</i>
WMC920-A116 7072877	Red duct sealant	1974 era. Mech/fan Rm. 3 on Mixing side of plenum wall. Photo R2289	<i>5.2% Chrysotile</i>
WMC920-A117 7072878	Red duct sealant	1974 era. Mech/fan Rm. 3 at bare steel flange. Photo B264	<i>5.0% Chrysotile</i>
WMC920-A118 7072879	Gray sealant at Fan sections	1974 era. Mech/fan Rm. 3. Fan 10013. Photo R2290	None Detected
WMC920-A119 7072880	"Ventglas" Black neoprene duct flexible connector	1974 era. Mech/fan Rm. 3. Outlet side of Squirrel fan. Photo R2291	None Detected
WMC920-A120 7072881	Gray ceramic tile grout	1974 era. Restroom 12. Loose grout in crack in base by door Photo R2278	None Detected

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated
11901 Business Blvd., Ste 208
Eagle River AK 99577

Report Date: 10/7/2020
Report No.: 620590 - PLM
Project: Wrangell Medical Center
Project No.: 7795-02

Client: EHS511

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072792	Analyst Observation: Tan Mastic	Location: Attic Near 1974 Era, Loose Store
Client No.: WMC920-A31	Client Description: Gray-Green Mastic Of Stainless Corner Guard	Corner Guard
<u>Percent Asbestos:</u>	<u>Percent Non-Asbestos Fibrous Material:</u>	<u>Percent Non-Fibrous Material:</u>
<i>None Detected</i>	None Detected	100

Lab No.: 7072793	Analyst Observation: Black Roof Material	Location: Attic Of 1974 Era, Under Loose
Client No.: WMC920-A32	Client Description: Built-Up Roofing Of 1974 Era Flat Roof W/Brown Perlite Board Insulation	Fiberglass At Exhaust Duct Penetration Through Old Roof Into Attic
<u>Percent Asbestos:</u>	<u>Percent Non-Asbestos Fibrous Material:</u>	<u>Percent Non-Fibrous Material:</u>
<i>20 Chrysotile</i>	10 Cellulose	70

Lab No.: 7072793(L2)	Analyst Observation: Brown Roof Material	Location: Attic Of 1974 Era, Under Loose
Client No.: WMC920-A32	Client Description: Built-Up Roofing Of 1974 Era Flat Roof W/Brown Perlite Board Insulation	Fiberglass At Exhaust Duct Penetration Through Old Roof Into Attic
<u>Percent Asbestos:</u>	<u>Percent Non-Asbestos Fibrous Material:</u>	<u>Percent Non-Fibrous Material:</u>
<i>None Detected</i>	25 Cellulose 10 Fibrous Glass	65

Lab No.: 7072794	Analyst Observation: Black Tar	Location: Attic Of 1974 Era, Bottom Of
Client No.: WMC920-A33	Client Description: Tarry Vapor Barrier And Tar And Fesco Board	Roof Assembly At Exhaust Duct Penetration Through Old Roof Into Attic
<u>Percent Asbestos:</u>	<u>Percent Non-Asbestos Fibrous Material:</u>	<u>Percent Non-Fibrous Material:</u>
<i>None Detected</i>	None Detected	100

Lab No.: 7072794(L2)	Analyst Observation: Brown Roof Material	Location: Attic Of 1974 Era, Bottom Of
Client No.: WMC920-A33	Client Description: Tarry Vapor Barrier And Tar And Fesco Board	Roof Assembly At Exhaust Duct Penetration Through Old Roof Into Attic
<u>Percent Asbestos:</u>	<u>Percent Non-Asbestos Fibrous Material:</u>	<u>Percent Non-Fibrous Material:</u>
<i>None Detected</i>	30 Cellulose	70

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/06/2020
Signature:
Analyst: Sarah Lipiecki

Approved By:
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 10/7/2020 Report No.: 620590 - PLM Project: Wrangell Medical Center Project No.: 7795-02
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072795 Client No.: WMC920-A34	Analyst Observation: Black Tar Client Description: Probably Hot Mop And Fesco Board	Location: Attic Of 1974 Era, Middle Layer Of Fesco Board Insulation At Exhaust Duct Penetration Through Old Ro
--	--	---

<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
--	--	---

Lab No.: 7072795(L2) Client No.: WMC920-A34	Analyst Observation: Brown Insulation Client Description: Probably Hot Mop And Fesco Board	Location: Attic Of 1974 Era, Middle Layer Of Fesco Board Insulation At Exhaust Duct Penetration Through Old Ro
--	---	---

<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 30 Cellulose	<u>Percent Non-Fibrous Material:</u> 70
--	---	--

Lab No.: 7072796 Client No.: WMC920-A35	Analyst Observation: Black Roof Material Client Description: Built-Up Roofing Of 1974 Era Flat Roof W/Brown Perlite Board Insulation	Location: Attic Of 1974 Era, Under Loose Fiberglass At Supply Duct Penetration Through Old Roof Into Attic
--	---	---

<u>Percent Asbestos:</u> <i>20 Chrysotile</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 10 Cellulose	<u>Percent Non-Fibrous Material:</u> 70
--	---	--


Lab No.: 7072796(L2) Client No.: WMC920-A35	Analyst Observation: Black Roof Material Client Description: Built-Up Roofing Of 1974 Era Flat Roof W/Brown Perlite Board Insulation	Location: Attic Of 1974 Era, Under Loose Fiberglass At Supply Duct Penetration Through Old Roof Into Attic
--	---	---


<u>Percent Asbestos:</u> <i>20 Chrysotile</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 10 Cellulose	<u>Percent Non-Fibrous Material:</u> 70
--	---	--

Lab No.: 7072796(L3) Client No.: WMC920-A35	Analyst Observation: Black Roof Material Client Description: Built-Up Roofing Of 1974 Era Flat Roof W/Brown Perlite Board Insulation	Location: Attic Of 1974 Era, Under Loose Fiberglass At Supply Duct Penetration Through Old Roof Into Attic
--	---	---

<u>Percent Asbestos:</u> <i>20 Chrysotile</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 10 Cellulose	<u>Percent Non-Fibrous Material:</u> 70
--	---	--

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/06/2020
Signature: 
Analyst: Sarah Lipiecki

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director


CERTIFICATE OF ANALYSIS


Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 10/7/2020 Report No.: 620590 - PLM Project: Wrangell Medical Center Project No.: 7795-02
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072796(L4) Client No.: WMC920-A35	Analyst Observation: Brown Roof Material Client Description: Built-Up Roofing Of 1974 Era Flat Roof W/Brown Perlite Board Insulation	Location: Attic Of 1974 Era, Under Loose Fiberglass At Supply Duct Penetration Through Old Roof Into Attic Facility: Percent Non-Fibrous Material: 70
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 30 Cellulose	
Lab No.: 7072797 Client No.: WMC920-A36	Analyst Observation: Black Roof Material Client Description: Tarry Vapor Barrier And Tar And Fesco Board	Location: Attic Of 1974 Era, Bottom Of Roof Assembly At Supply Duct Penetration Through Old Roof Into Attic Facility: Percent Non-Fibrous Material: 70
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 30 Cellulose	
Lab No.: 7072798 Client No.: WMC920-A37	Analyst Observation: Black Tar Client Description: ATCO Roof Patch Tar	Location: Attic Near 1974 Era, Loose 5 Gal Can Of Part #1823 Facility: Percent Non-Fibrous Material: 91.8
<u>Percent Asbestos:</u> <i>PC 6.2 Chrysotile</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 2 Fibrous Glass	
Lab No.: 7072799 Client No.: WMC920-A38	Analyst Observation: Grey Tar Paper Client Description: Tar Paper Under T And G Siding	Location: Attic At Exterior Side Of Original 1967 Fan Rm Facility: Percent Non-Fibrous Material: 75
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 25 Cellulose	
Lab No.: 7072800 Client No.: WMC920-A39	Analyst Observation: Grey Tar Paper Client Description: Tar Paper And GWB Sheathing Under T And G Siding	Location: Attic At Exterior Side Of Original 1967 Fan Rm Facility: Percent Non-Fibrous Material: 75
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 25 Cellulose	

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/06/2020
Signature: 
Analyst: Sarah Lipiecki

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated
11901 Business Blvd., Ste 208
Eagle River AK 99577

Report Date: 10/7/2020
Report No.: 620590 - PLM
Project: Wrangell Medical Center
Project No.: 7795-02

Client: EHS511

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072800(L2) **Analyst Observation:** Black Tar **Location:** Attic At Exterior Side Of Original
Client No.: WMC920-A39 **Client Description:** Tar Paper And GWB Sheathing Under T 1967 Fan Rm
And G Siding **Facility:**
Percent Asbestos: Percent Non-Asbestos Fibrous Material: Percent Non-Fibrous Material:
None Detected None Detected 100

Lab No.: 7072800(L3) **Analyst Observation:** Tan Drywall **Location:** Attic At Exterior Side Of Original
Client No.: WMC920-A39 **Client Description:** Tar Paper And GWB Sheathing Under T 1967 Fan Rm
And G Siding **Facility:**
Percent Asbestos: Percent Non-Asbestos Fibrous Material: Percent Non-Fibrous Material:
None Detected 10 Cellulose 90


Lab No.: 7072801 **Analyst Observation:** White Sealant **Location:** Metal Roof Under Valley
Client No.: WMC920-A40 **Client Description:** White Silicone Sealant At Roofing Flashing Canopy Near Main Entrance
Facility:
Percent Asbestos: Percent Non-Asbestos Fibrous Material: Percent Non-Fibrous Material:
None Detected None Detected 100


Lab No.: 7072802 **Analyst Observation:** Grey Sealant **Location:** Metal Roof Sealant Under Edge
Client No.: WMC920-A41 **Client Description:** Gray Rubbery Roof Sealant Flashing, Near Main Entrance
Facility:
Percent Asbestos: Percent Non-Asbestos Fibrous Material: Percent Non-Fibrous Material:
None Detected None Detected 100

Lab No.: 7072803 **Analyst Observation:** Clear Sealant **Location:** Metal Roof At Lap Joint Of
Client No.: WMC920-A42 **Client Description:** Clear Silicone Sealant At Fascia Of Metal Drip Ledge Over EFIS
Roofing **Facility:**
Percent Asbestos: Percent Non-Asbestos Fibrous Material: Percent Non-Fibrous Material:
None Detected None Detected 100

Lab No.: 7072804 **Analyst Observation:** Yellow Sealant **Location:** Metal Roof, Sealant Between
Client No.: WMC920-A43 **Client Description:** Clear Yellow Sealant At Roofing Roofing And Metal Angle Edge Flashing
Into Gutter
Facility:
Percent Asbestos: Percent Non-Asbestos Fibrous Material: Percent Non-Fibrous Material:
None Detected None Detected 100

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/06/2020
Signature: 
Analyst: Sarah Lipiecki

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated
11901 Business Blvd., Ste 208
Eagle River AK 99577

Report Date: 10/7/2020
Report No.: 620590 - PLM
Project: Wrangell Medical Center
Project No.: 7795-02

Client: EHS511

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072805 **Analyst Observation:** Black Tar Paper **Location:** Metal Roof, Under Main Roof, Over Decking
Client No.: WMC920-A44 **Client Description:** Tar Paper Under Metal Roofing **Facility:**
Percent Asbestos: Percent Non-Asbestos Fibrous Material: Percent Non-Fibrous Material:
None Detected 20 Cellulose 80

Lab No.: 7072806 **Analyst Observation:** Grey Foam **Location:** Metal Roof, At Edge Box Of Roofing
Client No.: WMC920-A45 **Client Description:** Foam Robber Filler At Roofing **Facility:**
Percent Asbestos: Percent Non-Asbestos Fibrous Material: Percent Non-Fibrous Material:
None Detected None Detected 100


Lab No.: 7072807 **Analyst Observation:** Grey Sealant **Location:** Under Metal Roof, At Edge Flashing
Client No.: WMC920-A46 **Client Description:** Gray Sticky Putty Sealant At Roofing **Facility:**
Percent Asbestos: Percent Non-Asbestos Fibrous Material: Percent Non-Fibrous Material:
None Detected None Detected 100


Lab No.: 7072808 **Analyst Observation:** Grey Sealant **Location:** At Column Of Main Entrance Drive-Through
Client No.: WMC920-A47 **Client Description:** EFIS Stucco And Sealant **Facility:**
Percent Asbestos: Percent Non-Asbestos Fibrous Material: Percent Non-Fibrous Material:
None Detected None Detected 100

Lab No.: 7072808(L2) **Analyst Observation:** Tan Stucco **Location:** At Column Of Main Entrance Drive-Through
Client No.: WMC920-A47 **Client Description:** EFIS Stucco And Sealant **Facility:**
Percent Asbestos: Percent Non-Asbestos Fibrous Material: Percent Non-Fibrous Material:
None Detected 10 Fibrous Glass 90

Lab No.: 7072809 **Analyst Observation:** White Drywall **Location:** At Water Damaged At Underside Of Soffit At Main Entrance Drive-Through
Client No.: WMC920-A48 **Client Description:** GWB Of Soffit **Facility:**
Percent Asbestos: Percent Non-Asbestos Fibrous Material: Percent Non-Fibrous Material:
None Detected 2 Cellulose 90
8 Fibrous Glass

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/06/2020
Signature: 
Analyst: Sarah Lipiecki

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated
11901 Business Blvd., Ste 208
Eagle River AK 99577

Report Date: 10/7/2020
Report No.: 620590 - PLM
Project: Wrangell Medical Center
Project No.: 7795-02

Client: EHS511

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072810 **Analyst Observation:** White Joint Compound
Client No.: WMC920-A49 **Client Description:** Joint Compound Of Soffit
Location: At Water Damaged At Underside Of Soffit At Main Entrance Drive-Through
Facility:
Percent Asbestos: Percent Non-Asbestos Fibrous Material: Percent Non-Fibrous Material:
None Detected None Detected 100

Lab No.: 7072811 **Analyst Observation:** Grey Concrete
Client No.: WMC920-A50 **Client Description:** Concrete Sacking
Location: Exterior Foundation Wall Of 1974 Addition, At Snap-Tie Hole
Facility:
Percent Asbestos: Percent Non-Asbestos Fibrous Material: Percent Non-Fibrous Material:
None Detected None Detected 100


Lab No.: 7072812 **Analyst Observation:** White Joint Compound
Client No.: WMC920-A51 **Client Description:** Gypsum Wallboard/Joint Compound/Tape
Location: Ceiling Of Exterior Soffit Of Walkway Going To Morgue Door
Facility:
Percent Asbestos: Percent Non-Asbestos Fibrous Material: Percent Non-Fibrous Material:
None Detected None Detected 100


Lab No.: 7072812(L2) **Analyst Observation:** White Tape
Client No.: WMC920-A51 **Client Description:** Gypsum Wallboard/Joint Compound/Tape
Location: Ceiling Of Exterior Soffit Of Walkway Going To Morgue Door
Facility:
Percent Asbestos: Percent Non-Asbestos Fibrous Material: Percent Non-Fibrous Material:
None Detected 75 Cellulose 25

Lab No.: 7072813 **Analyst Observation:** Grey Sealant
Client No.: WMC920-A52 **Client Description:** Gray Sticky Sealant
Location: Between Door Frame And Concrete Of Morgue Door To 1974 To Era
Facility:
Percent Asbestos: Percent Non-Asbestos Fibrous Material: Percent Non-Fibrous Material:
None Detected 2 Cellulose 98

Lab No.: 7072813(L2) **Analyst Observation:** Black Foam
Client No.: WMC920-A52 **Client Description:** Gray Sticky Sealant
Location: Between Door Frame And Concrete Of Morgue Door To 1974 To Era
Facility:
Percent Asbestos: Percent Non-Asbestos Fibrous Material: Percent Non-Fibrous Material:
None Detected None Detected 100

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/06/2020
Signature: 
Analyst: Sarah Lipiecki

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director


CERTIFICATE OF ANALYSIS


Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 10/7/2020 Report No.: 620590 - PLM Project: Wrangell Medical Center Project No.: 7795-02
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072814 Client No.: WMC920-A53	Analyst Observation: White Sealant Client Description: White Window Frame Sealant	Location: Between Window Frame And EFIS Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
Lab No.: 7072815 Client No.: WMC920-A54	Analyst Observation: Cream Sealant Client Description: Harder Cream Sealant	Location: Sealant At Plywood Of Boarded Up Window Around Air Conditioning Unit Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
Lab No.: 7072816 Client No.: WMC920-A55	Analyst Observation: Black Sealant Client Description: Black Tarry Waterproofing At Foundation	Location: In Crawl Space, At Former Exterior Wall Of 1974 Addition Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
Lab No.: 7072817 Client No.: WMC920-A56	Analyst Observation: Grey Cement Product Client Description: Cement Asbestos Pipe	Location: In Crawl Space, At Capped Pipe Coming Out Of Soil Facility:
<u>Percent Asbestos:</u> 10 Chrysotile 10 Crocidolite	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 80
Lab No.: 7072818 Client No.: WMC920-A57	Analyst Observation: Grey Cement Product Client Description: Cement Asbestos Pipe	Location: In Crawl Space, At Active Sewer Pipe Facility:
<u>Percent Asbestos:</u> 12 Chrysotile PC 8 Crocidolite	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 80

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/06/2020
Signature: 
Analyst: Sarah Lipiecki

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 10/7/2020 Report No.: 620590 - PLM Project: Wrangell Medical Center Project No.: 7795-02
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072819 Client No.: WMC920-A58	Analyst Observation: White Insulation Client Description: Hard Fitting Insulation	Location: In Crawl Space, Probably On A Hot Water Pipe Facility: Percent Non-Fibrous Material: 73.3
<u>Percent Asbestos:</u> PC 0.5 Chrysotile PC 1.2 Crocidolite	<u>Percent Non-Asbestos Fibrous Material:</u> 25 Fibrous Glass	


Lab No.: 7072819(L2) Client No.: WMC920-A58	Analyst Observation: Yellow Insulation Client Description: Hard Fitting Insulation	Location: In Crawl Space, Probably On A Hot Water Pipe Facility: Percent Non-Fibrous Material: 10
<u>Percent Asbestos:</u> None Detected	<u>Percent Non-Asbestos Fibrous Material:</u> 90 Fibrous Glass	


Lab No.: 7072820 Client No.: WMC920-A59	Analyst Observation: White Insulation Client Description: Hard Fitting Insulation	Location: In Crawl Space, On Ground Facility: Percent Non-Fibrous Material: 65.5
<u>Percent Asbestos:</u> 20 Chrysotile PC 1.5 Crocidolite	<u>Percent Non-Asbestos Fibrous Material:</u> 3 Cellulose 10 Fibrous Glass	

Lab No.: 7072821 Client No.: WMC920-A60	Analyst Observation: Black Sealant Client Description: Black Tarry Waterproofing At Foundation	Location: At Exterior Wall Of 1974 Addition Facility: Percent Non-Fibrous Material: 100
<u>Percent Asbestos:</u> None Detected	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	

Lab No.: 7072822 Client No.: WMC920-A61	Analyst Observation: Cream Sealant Client Description: Sticky Cream Sealant At EFIS	Location: At EFIS Over 1974 Addition, Between Metal Frame Of Louver And EFIS Facility: Percent Non-Fibrous Material: 100
<u>Percent Asbestos:</u> None Detected	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/06/2020
Signature: 
Analyst: Sarah Lipiecki

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated
11901 Business Blvd., Ste 208
Eagle River AK 99577


Report Date: 10/7/2020
Report No.: 620590 - PLM
Project: Wrangell Medical Center
Project No.: 7795-02


Client: EHS511

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072823 Client No.: WMC920-A62	Analyst Observation: Clear Sealant Client Description: Sticky Cream Sealant At EFIS	Location: At EFIS Over 1988 Addition, Between Metal Frame Of Window And EFIS Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
Lab No.: 7072824 Client No.: WMC920-A63	Analyst Observation: Black Glazing Client Description: Black Rubbery Glazing At Alum Windows	Location: Aluminum Framed Window Of 1988 Addition Facility:
<u>Percent Asbestos:</u> <i>PC 4.5 Chrysotile</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 95.5
Lab No.: 7072825 Client No.: WMC920-A64	Analyst Observation: Cream Sealant Client Description: Sticky Cream Sealant At EFIS	Location: At EFIS Over 1988 Addition, Between GWB Soffit And EFIS Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 3 Talc	<u>Percent Non-Fibrous Material:</u> 97
Lab No.: 7072826 Client No.: WMC920-A65	Analyst Observation: White Sealant Client Description: Whiter Caulking At EFIS	Location: At EFIS Over 1988 Addition, Between Metal Generator Louver And EFIS Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
Lab No.: 7072827 Client No.: WMC920-A66	Analyst Observation: Pink Caulk Client Description: Pinkish Caulking	Location: At 1988 Addition, Between Metal Generator Louver And Louver Frame Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
Lab No.: 7072828 Client No.: WMC920-A67	Analyst Observation: Tan/Grey Stucco Client Description: EFIS Stucco And Fiberglass Mesh	Location: At 1988 Addition, At Drip Edge Of EFIS Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 2 Cellulose 10 Fibrous Glass	<u>Percent Non-Fibrous Material:</u> 88

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/06/2020
Signature: 
Analyst: Sarah Lipiecki

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director


CERTIFICATE OF ANALYSIS


Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 10/7/2020 Report No.: 620590 - PLM Project: Wrangell Medical Center Project No.: 7795-02
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072829 Client No.: WMC920-A68	Analyst Observation: Clear Sealant Client Description: Clear Sealant At Window	Location: At 1992 Addition, At Wood Frame To Plastic Window Joint Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
Lab No.: 7072830 Client No.: WMC920-A69	Analyst Observation: White Sealant Client Description: White Sealant At Siding	Location: At 1992 Addition, At Vent Pipe Penetration Of Metal Siding Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
Lab No.: 7072831 Client No.: WMC920-A70	Analyst Observation: White Sealant Client Description: White Sealant At Soffit Fascia	Location: At 1992 Addition, At Lap Joint Of Lower Soffit Flashing Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/06/2020
Signature: 
Analyst: Sarah Lipiecki

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 10/7/2020 Report No.: 620590 - PLM Project: Wrangell Medical Center Project No.: 7795-02
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072832 Client No.: WMC920-A71	Analyst Observation: White Sealant Client Description: White Sealant At Standing Seam Roof	Location: At 1992 Addition, At Folded Top Seam Of Rib Joints Facility: Percent Non-Fibrous Material: 100
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	

Lab No.: 7072833 Client No.: WMC920-A72	Analyst Observation: Black Tar Paper Client Description: Tar Paper Under Metal Roofing	Location: At 1992 Addition, Under Main Metal Roofing Facility: Percent Non-Fibrous Material: 35
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 65 Cellulose	

Lab No.: 7072834 Client No.: WMC920-A73	Analyst Observation: Grey Sealant Client Description: Gray Sealant At Metal Roofing	Location: At 1992 Addition, At Flashing Between Metal Siding And Transition Flashing Over Vestibule Roof Facility: Percent Non-Fibrous Material: 100
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	

Lab No.: 7072835 Client No.: WMC920-A74	Analyst Observation: Off-White Sealant Client Description: Sticky Cream Sealant At EFIS	Location: At EFIS Over 1988 Addition, At Fire Dept Connection Facility: Percent Non-Fibrous Material: 100
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	

Lab No.: 7072836 Client No.: WMC920-A75	Analyst Observation: Off-White Sealant Client Description: Sticky Cream Sealant At EFIS	Location: AT EFIS Over 1967 Orig, Between GWB Soffit And EFIS Facility: Percent Non-Fibrous Material: 100
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/07/2020
Signature:
Analyst: Rebecca Hargrove

Approved By:
Frank E. Ehrenfeld, III
Laboratory Director


CERTIFICATE OF ANALYSIS


Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 10/7/2020 Report No.: 620590 - PLM Project: Wrangell Medical Center Project No.: 7795-02
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072837 Client No.: WMC920-A76	Analyst Observation: Pink/Tan Drywall Client Description: Gypsum Board And Joint Compound	Location: 1992 Addition, Corner Of Rm 25, Bulk Storage Facility: Percent Non-Fibrous Material: 65
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 35 Cellulose Trace Fibrous Glass	
Lab No.: 7072837(L2) Client No.: WMC920-A76	Analyst Observation: Off-White Joint Compound Client Description: Gypsum Board And Joint Compound	Location: 1992 Addition, Corner Of Rm 25, Bulk Storage Facility: Percent Non-Fibrous Material: 100
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	
Lab No.: 7072837(L3) Client No.: WMC920-A76	Analyst Observation: Composite Client Description: Gypsum Board And Joint Compound	Location: 1992 Addition, Corner Of Rm 25, Bulk Storage Facility: Percent Non-Fibrous Material: 68
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 32 Cellulose Trace Fibrous Glass	
Lab No.: 7072838 Client No.: WMC920-A77	Analyst Observation: Pink/Tan Drywall Client Description: CB-1-4" Gray Cove Base With Cream Mastic/Joint Compound And Gypsum Wallboard	Location: 1992 Addition, Corner Of Rm 29, Vestibule Facility: Percent Non-Fibrous Material: 63
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 35 Cellulose 2 Fibrous Glass	
Lab No.: 7072838(L2) Client No.: WMC920-A77	Analyst Observation: Off-White Joint Compound Client Description: CB-1-4" Gray Cove Base With Cream Mastic/Joint Compound And Gypsum Wallboard	Location: 1992 Addition, Corner Of Rm 29, Vestibule Facility: Percent Non-Fibrous Material: 100
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/07/2020
Signature: 
Analyst: Rebecca Hargrove

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 10/7/2020 Report No.: 620590 - PLM Project: Wrangell Medical Center Project No.: 7795-02
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072838(L3) Client No.: WMC920-A77	Analyst Observation: Composite Client Description: CB-1-4" Gray Cove Base With Cream Mastic/Joint Compound And Gypsum Wallboard	Location: 1992 Addition, Corner Of Rm 29, Vestibule Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 30 Cellulose 2 Fibrous Glass	<u>Percent Non-Fibrous Material:</u> 68
Lab No.: 7072838(L4) Client No.: WMC920-A77	Analyst Observation: Grey Cove Base Client Description: CB-1-4" Gray Cove Base With Cream Mastic/Joint Compound And Gypsum Wallboard	Location: 1992 Addition, Corner Of Rm 29, Vestibule Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
Lab No.: 7072838(L5) Client No.: WMC920-A77	Analyst Observation: Tan Mastic Client Description: CB-1-4" Gray Cove Base With Cream Mastic/Joint Compound And Gypsum Wallboard	Location: 1992 Addition, Corner Of Rm 29, Vestibule Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
Lab No.: 7072839 Client No.: WMC920-A78	Analyst Observation: White/Tan Drywall Client Description: Gypsum Wallboard And Joint Compound	Location: 1967 Era, Sprinkler Rm 30, But Wall Supposedly Built With 1988 Addition Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 20 Cellulose 2 Fibrous Glass	<u>Percent Non-Fibrous Material:</u> 78
Lab No.: 7072839(L2) Client No.: WMC920-A78	Analyst Observation: Off-White Joint Compound Client Description: Gypsum Wallboard And Joint Compound	Location: 1967 Era, Sprinkler Rm 30, But Wall Supposedly Built With 1988 Addition Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/07/2020
Signature:
Analyst: Rebecca Hargrove

Approved By:
Frank E. Ehrenfeld, III
Laboratory Director


CERTIFICATE OF ANALYSIS


Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 10/7/2020 Report No.: 620590 - PLM Project: Wrangell Medical Center Project No.: 7795-02
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072839(L3) Client No.: WMC920-A78	Analyst Observation: Composite Client Description: Gypsum Wallboard And Joint Compound	Location: 1967 Era, Sprinkler Rm 30, But Wall Supposedly Built With 1988 Addition Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 20 Cellulose 2 Fibrous Glass	<u>Percent Non-Fibrous Material:</u> 78
Lab No.: 7072840 Client No.: WMC920-A79	Analyst Observation: White/Tan Drywall Client Description: Gypsum Wallboard And Joint Compound	Location: 1967 Era, Sprinkler Rm 30, 1967 Exterior Wall Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 25 Cellulose	<u>Percent Non-Fibrous Material:</u> 75
Lab No.: 7072840(L2) Client No.: WMC920-A79	Analyst Observation: White Joint Compound Client Description: Gypsum Wallboard And Joint Compound	Location: 1967 Era, Sprinkler Rm 30, 1967 Exterior Wall Facility:
<u>Percent Asbestos:</u> PC 2.8 Chrysotile	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 97.2
Lab No.: 7072840(L3) Client No.: WMC920-A79	Analyst Observation: Composite Client Description: Gypsum Wallboard And Joint Compound	Location: 1967 Era, Sprinkler Rm 30, 1967 Exterior Wall Facility:
<u>Percent Asbestos:</u> PC 0.25 Chrysotile	<u>Percent Non-Asbestos Fibrous Material:</u> 23 Cellulose	<u>Percent Non-Fibrous Material:</u> 76.75
Lab No.: 7072841 Client No.: WMC920-A80	Analyst Observation: Green Cove Base Client Description: CB-2, 4" Green Painted Cove Base With Dark Brown Mastic	Location: 1967 Era, Sprinkler Rm 30, 1967 Exterior Wall Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
Lab No.: 7072841(L2) Client No.: WMC920-A80	Analyst Observation: Brown Mastic Client Description: CB-2, 4" Green Painted Cove Base With Dark Brown Mastic	Location: 1967 Era, Sprinkler Rm 30, 1967 Exterior Wall Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/07/2020
Signature: 
Analyst: Rebecca Hargrove

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 10/7/2020 Report No.: 620590 - PLM Project: Wrangell Medical Center Project No.: 7795-02
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072842 Client No.: WMC920-A81	Analyst Observation: Tan Insulation Client Description: Hard Fitting Insulation	Location: 1967 Era, Boiler Rm 108, On Yellow Boiler Supply Pipe Facility: Percent Non-Fibrous Material:
Percent Asbestos: <i>10 Chrysotile</i>	Percent Non-Asbestos Fibrous Material: 40 Fibrous Glass	Percent Non-Fibrous Material: 50


Lab No.: 7072843 Client No.: WMC920-A82	Analyst Observation: Tan Insulation Client Description: Hard Fitting Insulation	Location: 1967 Era, Boiler Rm 108, On Yellow Boiler Supply Pipe Facility: Percent Non-Fibrous Material:
Percent Asbestos: <i>10 Chrysotile</i> <i>PC Trace Amosite</i>	Percent Non-Asbestos Fibrous Material: 40 Fibrous Glass	Percent Non-Fibrous Material: 50


Lab No.: 7072844 Client No.: WMC920-A83	Analyst Observation: Off-White Insulation Client Description: Hard Fitting Insulation	Location: 1967 Era, Boiler Rm 108, On Blue Cold Water Supply Facility: Percent Non-Fibrous Material:
Percent Asbestos: <i>10 Chrysotile</i> <i>PC Trace Amosite</i>	Percent Non-Asbestos Fibrous Material: 20 Fibrous Glass 20 Cellulose	Percent Non-Fibrous Material: 50

Lab No.: 7072845 Client No.: WMC920-A84	Analyst Observation: Black Coating Client Description: Black Tarry Coating Inside Ceiling Speaker Box	Location: 1988 Era, Staff Lounge, Inside Red Speaker Box Facility: Percent Non-Fibrous Material:
Percent Asbestos: <i>None Detected</i>	Percent Non-Asbestos Fibrous Material: None Detected	Percent Non-Fibrous Material: 100

Lab No.: 7072846 Client No.: WMC920-A85	Analyst Observation: Grey/White Ceiling Tile Client Description: LCT-2, 2x4 Galaxy Pattern Suspended Ceiling Tile, Random Small Fisures	Location: 1988 Era, Staff Lounge 115, Main Tile In Rm Facility: Percent Non-Fibrous Material:
Percent Asbestos: <i>None Detected</i>	Percent Non-Asbestos Fibrous Material: 45 Fibrous Glass 40 Cellulose	Percent Non-Fibrous Material: 15

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/07/2020
Signature: 
Analyst: Rebecca Hargrove

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated
11901 Business Blvd., Ste 208
Eagle River AK 99577


Report Date: 10/7/2020
Report No.: 620590 - PLM
Project: Wrangell Medical Center
Project No.: 7795-02


Client: EHS511

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072847 Client No.: WMC920-A86	Analyst Observation: Green Cove Base Client Description: CB-2, 4" Green Painted Cove Base With Dark Brown Mastic And Old On Back Of CB Newer Jo On Face Of CB	Location: 1967 Era, Elec Rm 34, Possible 1988 Wall, But Appears Original Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
Lab No.: 7072847(L2) Client No.: WMC920-A86	Analyst Observation: Brown Mastic Client Description: CB-2, 4" Green Painted Cove Base With Dark Brown Mastic And Old On Back Of CB Newer Jo On Face Of CB	Location: 1967 Era, Elec Rm 34, Possible 1988 Wall, But Appears Original Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
Lab No.: 7072847(L3) Client No.: WMC920-A86	Analyst Observation: White Joint Compound Client Description: CB-2, 4" Green Painted Cove Base With Dark Brown Mastic And Old On Back Of CB Newer Jo On Face Of CB	Location: 1967 Era, Elec Rm 34, Possible 1988 Wall, But Appears Original Facility:
<u>Percent Asbestos:</u> <i>PC 2.6 Chrysotile</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 97.4
Lab No.: 7072847(L4) Client No.: WMC920-A86	Analyst Observation: White Joint Compound Client Description: CB-2, 4" Green Painted Cove Base With Dark Brown Mastic And Old On Back Of CB Newer Jo On Face Of CB	Location: 1967 Era, Elec Rm 34, Possible 1988 Wall, But Appears Original Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
Lab No.: 7072848 Client No.: WMC920-A87	Analyst Observation: Grey/White Ceiling Tile Client Description: LCT-1, 2x4 Shallow Directional Fissures 1/16" And 1/8" Holes	Location: 1967 Era, But Newer Tile, Hallway To 1992 Addition Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 50 Fibrous Glass 30 Cellulose	<u>Percent Non-Fibrous Material:</u> 20

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/07/2020
Signature: 
Analyst: Rebecca Hargrove

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated
11901 Business Blvd., Ste 208
Eagle River AK 99577


Report Date: 10/7/2020
Report No.: 620590 - PLM
Project: Wrangell Medical Center
Project No.: 7795-02


Client: EHS511

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072849 Client No.: WMC920-A88 <u>Percent Asbestos:</u> <i>None Detected</i>	Analyst Observation: Off-White Vinyl Sheet Flooring Client Description: SV-1, Cream Sheet Vinyl With White Shading And Tiny Brown Specks <u>Percent Non-Asbestos Fibrous Material:</u> 5 Fibrous Glass	Location: 1967 Era, But Newer Flooring, Hallway To 1992 Addition Facility: <u>Percent Non-Fibrous Material:</u> 95
Lab No.: 7072849(L2) Client No.: WMC920-A88 <u>Percent Asbestos:</u> <i>None Detected</i>	Analyst Observation: Tan Mastic Client Description: SV-1, Cream Sheet Vinyl With White Shading And Tiny Brown Specks <u>Percent Non-Asbestos Fibrous Material:</u> None Detected	Location: 1967 Era, But Newer Flooring, Hallway To 1992 Addition Facility: <u>Percent Non-Fibrous Material:</u> 100
Lab No.: 7072850 Client No.: WMC920-A89 <u>Percent Asbestos:</u> <i>None Detected</i>	Analyst Observation: Grey Cove Base Client Description: CB-3, Gray 4" Cove Base With Light Tan Mastic <u>Percent Non-Asbestos Fibrous Material:</u> None Detected	Location: 1988 Addition, Janitor Closet 109 Facility: <u>Percent Non-Fibrous Material:</u> 100
Lab No.: 7072850(L2) Client No.: WMC920-A89 <u>Percent Asbestos:</u> <i>None Detected</i>	Analyst Observation: Tan Mastic Client Description: CB-3, Gray 4" Cove Base With Light Tan Mastic <u>Percent Non-Asbestos Fibrous Material:</u> None Detected	Location: 1988 Addition, Janitor Closet 109 Facility: <u>Percent Non-Fibrous Material:</u> 100
Lab No.: 7072851 Client No.: WMC920-A90 <u>Percent Asbestos:</u> <i>None Detected</i>	Analyst Observation: Off-White Vinyl Sheet Flooring Client Description: SV-2, Cream With Small 3/8" And Smaller Light Tan And Gray Chips, Tan Mastic <u>Percent Non-Asbestos Fibrous Material:</u> None Detected	Location: 1988 Addition, Janitor Closet 109 Facility: <u>Percent Non-Fibrous Material:</u> 100
Lab No.: 7072851(L2) Client No.: WMC920-A90 <u>Percent Asbestos:</u> <i>None Detected</i>	Analyst Observation: Tan Mastic Client Description: SV-2, Cream With Small 3/8" And Smaller Light Tan And Gray Chips, Tan Mastic <u>Percent Non-Asbestos Fibrous Material:</u> None Detected	Location: 1988 Addition, Janitor Closet 109 Facility: <u>Percent Non-Fibrous Material:</u> 100

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/07/2020
Signature: 
Analyst: Rebecca Hargrove

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director


CERTIFICATE OF ANALYSIS


Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 10/7/2020 Report No.: 620590 - PLM Project: Wrangell Medical Center Project No.: 7795-02
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072852 Client No.: WMC920-A91	Analyst Observation: Black Connector Client Description: Ventglas Black Neoprene Duct Flexible Connector	Location: 1967 Penthouse Fan Rm, At Exhaust Fan #10019 Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 40 Fibrous Glass	<u>Percent Non-Fibrous Material:</u> 60
Lab No.: 7072853 Client No.: WMC920-A92	Analyst Observation: Black Connector Client Description: Ventglas Black Neoprene Duct Flexible Connector	Location: 1967 Penthouse Fan Rm, At Central AHU Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 40 Fibrous Glass	<u>Percent Non-Fibrous Material:</u> 60
Lab No.: 7072854 Client No.: WMC920-A93	Analyst Observation: Off-White Vinyl Sheet Flooring Client Description: SV-1, Cream Sheet Vinyl With White Shading And Tiny Brown Specks, Brown Mastic	Location: 1967 Era, But Newer Flooring, Store Rm 102 Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 10 Fibrous Glass	<u>Percent Non-Fibrous Material:</u> 90
Lab No.: 7072854(L2) Client No.: WMC920-A93	Analyst Observation: Brown Mastic Client Description: SV-1, Cream Sheet Vinyl With White Shading And Tiny Brown Specks, Brown Mastic	Location: 1967 Era, But Newer Flooring, Store Rm 102 Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
Lab No.: 7072855 Client No.: WMC920-A94	Analyst Observation: Grey Leveling Compound Client Description: Leveling Compound Or Float Over Concrete	Location: 1967 Era, Store Rm 102, Appears To Be 1/2" Thick Over Painted Concrete Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
Lab No.: 7072856 Client No.: WMC920-A95	Analyst Observation: Black Tar Paper Client Description: Tar Paper Between Layers Of Plywood Ignore Wood	Location: 1967 Era, At Hatch In Janitor Closet 38, Appears To Be Original Slipsheet Between Plywood Subfloor A Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 50 Cellulose	<u>Percent Non-Fibrous Material:</u> 50

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/07/2020
Signature: 
Analyst: Rebecca Hargrove

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 10/7/2020 Report No.: 620590 - PLM Project: Wrangell Medical Center Project No.: 7795-02
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072857	Analyst Observation: Black Mastic	Location: 1967 Era, At Hatch In Janitor Closet 38, Appears To Be Original Black Mastic Under Particle Board Un
Client No.: WMC920-A96	Client Description: Tar Mastic Under Particle Board Ignore Wood	Facility:

<u>Percent Asbestos:</u> <i>PC 4.1 Chrysotile</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 95.9
--	--	--


Lab No.: 7072858	Analyst Observation: Tan Vinyl Sheet Flooring	Location: 1967 Era, At Hatch In Janitor Closet 38, Top Layer Over Particle Board
Client No.: WMC920-A97	Client Description: SV-1, Cream Sheet Vinyl With Whit Shading And Tiny Brown Specks, Brown Mastic, Particle Board Ignore	Facility:


<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 5 Fibrous Glass	<u>Percent Non-Fibrous Material:</u> 95
--	--	--

Lab No.: 7072858(L2)	Analyst Observation: Brown Mastic	Location: 1967 Era, At Hatch In Janitor Closet 38, Top Layer Over Particle Board
Client No.: WMC920-A97	Client Description: SV-1, Cream Sheet Vinyl With Whit Shading And Tiny Brown Specks, Brown Mastic, Particle Board Ignore	Facility:

<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
--	--	---

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/07/2020
Signature: 
Analyst: Rebecca Hargrove

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated
11901 Business Blvd., Ste 208
Eagle River AK 99577

Report Date: 10/7/2020
Report No.: 620590 - PLM
Project: Wrangell Medical Center
Project No.: 7795-02

Client: EHS511

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072859	Analyst Observation: Brown Vinyl Sheet Flooring	Location: 1988 Era, Pt Rm 132, At In-Floor Duct Grille By Entrance
Client No.: WMC920-A98	Client Description: SV-3, Fake Wood Sheet Flooring, White Leveling Compound, Sticky Brown Contact Cement	Facility:
<u>Percent Asbestos:</u>	<u>Percent Non-Asbestos Fibrous Material:</u>	<u>Percent Non-Fibrous Material:</u>
<i>None Detected</i>	None Detected	100

Lab No.: 7072859(L2)	Analyst Observation: Clear/Yellow Mastic	Location: 1988 Era, Pt Rm 132, At In-Floor Duct Grille By Entrance
Client No.: WMC920-A98	Client Description: SV-3, Fake Wood Sheet Flooring, White Leveling Compound, Sticky Brown Contact Cement	Facility:
<u>Percent Asbestos:</u>	<u>Percent Non-Asbestos Fibrous Material:</u>	<u>Percent Non-Fibrous Material:</u>
<i>None Detected</i>	None Detected	100


Lab No.: 7072859(L3)	Analyst Observation: Grey/White Leveling Compound	Location: 1988 Era, Pt Rm 132, At In-Floor Duct Grille By Entrance
Client No.: WMC920-A98	Client Description: SV-3, Fake Wood Sheet Flooring, White Leveling Compound, Sticky Brown Contact Cement	Facility:
<u>Percent Asbestos:</u>	<u>Percent Non-Asbestos Fibrous Material:</u>	<u>Percent Non-Fibrous Material:</u>
<i>None Detected</i>	2 Cellulose	98


Lab No.: 7072860	Analyst Observation: Grey/White Leveling Compound	Location: 1988 Era, PT Rm 132, At In-Floor Duct Grille By Entrance
Client No.: WMC920-A99	Client Description: White Leveling Compound, Brown Mastic	Facility:
<u>Percent Asbestos:</u>	<u>Percent Non-Asbestos Fibrous Material:</u>	<u>Percent Non-Fibrous Material:</u>
<i>None Detected</i>	None Detected	100

Lab No.: 7072860(L2)	Analyst Observation: Yellow/Brown Mastic	Location: 1988 Era, PT Rm 132, At In-Floor Duct Grille By Entrance
Client No.: WMC920-A99	Client Description: White Leveling Compound, Brown Mastic	Facility:
<u>Percent Asbestos:</u>	<u>Percent Non-Asbestos Fibrous Material:</u>	<u>Percent Non-Fibrous Material:</u>
<i>None Detected</i>	None Detected	100

Lab No.: 7072861	Analyst Observation: Yellow/Brown Mastic	Location: 1988 Era, PT Rm 132, Probably Original Mastic, At In-Floor Duct Grille By Entrance
Client No.: WMC920-A100	Client Description: Brown Mastic On Side Of metal Duct	Facility:
<u>Percent Asbestos:</u>	<u>Percent Non-Asbestos Fibrous Material:</u>	<u>Percent Non-Fibrous Material:</u>
<i>None Detected</i>	2 Cellulose	98

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/07/2020
Signature: 
Analyst: Michael Moore

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director


CERTIFICATE OF ANALYSIS


Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 10/7/2020 Report No.: 620590 - PLM Project: Wrangell Medical Center Project No.: 7795-02
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072862 Client No.: WMC920-A101	Analyst Observation: White Sealant Client Description: White Seal At Ductwork	Location: 1988 Era, PT Rm 132, At Opposed Blade Damper In Relief Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 10 Talc	<u>Percent Non-Fibrous Material:</u> 90
Lab No.: 7072863 Client No.: WMC920-A102	Analyst Observation: White Drywall Client Description: Gypsum Wallboard And Joint Compound	Location: 1988 Era, PT Rm 132, At Wall Above Ceiling Grid Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 2 Cellulose 2 Fibrous Glass	<u>Percent Non-Fibrous Material:</u> 96
Lab No.: 7072863(L2) Client No.: WMC920-A102	Analyst Observation: White Joint Compound Client Description: Gypsum Wallboard And Joint Compound	Location: 1988 Era, PT Rm 132, At Wall Above Ceiling Grid Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
Lab No.: 7072864 Client No.: WMC920-A103	Analyst Observation: Cream Vinyl Sheet Flooring Client Description: SV-2, Cream With Small 3/8" And Smaller Light Tan And Gray Chips, Tan Mastic Ignore Wood	Location: 1988 Era, Closet 143, At Hatch To Crawl Space Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
Lab No.: 7072864(L2) Client No.: WMC920-A103	Analyst Observation: Yellow Mastic Client Description: SV-2, Cream With Small 3/8" And Smaller Light Tan And Gray Chips, Tan Mastic Ignore Wood	Location: 1988 Era, Closet 143, At Hatch To Crawl Space Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 3 Cellulose	<u>Percent Non-Fibrous Material:</u> 97
Lab No.: 7072865 Client No.: WMC920-A104	Analyst Observation: Grey Cove Base Client Description: CB-3, Gray 4" Cove Base With Cream Mastic	Location: 1988 Era, Exam Rm 151 Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/07/2020
Signature: 
Analyst: Michael Moore

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 10/7/2020 Report No.: 620590 - PLM Project: Wrangell Medical Center Project No.: 7795-02
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072865(L2) Client No.: WMC920-A104	Analyst Observation: Beige Mastic Client Description: CB-3, Gray 4" Cove Base With Cream Mastic	Location: 1988 Era, Exam Rm 151 Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100


Lab No.: 7072866 Client No.: WMC920-A105	Analyst Observation: Yellow Mastic Client Description: Yellow Carpet Mastic	Location: 1988 Era, Hallway Outside Restroom 142 Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 2 Cellulose Trace Synthetic	<u>Percent Non-Fibrous Material:</u> 98


Lab No.: 7072867 Client No.: WMC920-A106	Analyst Observation: Grey Leveling Compound Client Description: Yellow Carpet Mastic And Gray Leveling Compound	Location: 1988 Era, Waiting Area 81, By Vestibules Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 2 Cellulose	<u>Percent Non-Fibrous Material:</u> 98

Lab No.: 7072867(L2) Client No.: WMC920-A106	Analyst Observation: Clear/Yellow Mastic Client Description: Yellow Carpet Mastic And Gray Leveling Compound	Location: 1988 Era, Waiting Area 81, By Vestibules Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 2 Cellulose	<u>Percent Non-Fibrous Material:</u> 98

Lab No.: 7072868 Client No.: WMC920-A107	Analyst Observation: White Joint Compound Client Description: Joint Compound	Location: 1988 Era, Waiting Area 81, By Corner Near Admin 79 Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/07/2020
Signature: 
Analyst: Michael Moore

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 10/7/2020 Report No.: 620590 - PLM Project: Wrangell Medical Center Project No.: 7795-02
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072869 Client No.: WMC920-A108	Analyst Observation: White Drywall Client Description: Gypsum Wallboard	Location: 1988 Era, Waiting Area 81, By Corner Near Admin 79
---	--	--

<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 3 Cellulose 2 Fibrous Glass	<u>Percent Non-Fibrous Material:</u> 95
--	---	--

Lab No.: 7072869(L2) Client No.: WMC920-A108	Analyst Observation: White Joint Compound Client Description: Gypsum Wallboard	Location: 1988 Era, Waiting Area 81, By Corner Near Admin 79
---	---	--

<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
--	--	---

Lab No.: 7072870 Client No.: WMC920-A109	Analyst Observation: Grey/Tan Stucco Client Description: Exterior Stucco Of EFIS At Added Walls Around Dining/Activity 69	Location: Unknown Date, Reportedly Within The Past 10 Years
---	---	---

<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 5 Fibrous Glass	<u>Percent Non-Fibrous Material:</u> 95
--	--	--

Lab No.: 7072870(L2) Client No.: WMC920-A109	Analyst Observation: White Foam Client Description: Exterior Stucco Of EFIS At Added Walls Around Dining/Activity 69	Location: Unknown Date, Reportedly Within The Past 10 Years
---	--	---

<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
--	--	---


Lab No.: 7072871 Client No.: WMC920-A110	Analyst Observation: Brown/Grey Sealant Client Description: Exterior Stucco, Red Sealant Of EFIS At Added Walls Around Dining/Activity 69	Location: Unknown Date, Reportedly Within The Past 10 Years
---	---	---


<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 2 Fibrous Glass	<u>Percent Non-Fibrous Material:</u> 98
--	--	--

Lab No.: 7072872 Client No.: WMC920-A111	Analyst Observation: Black Stair Tread Client Description: Black Rubber Stair Tread With Brown Mastic	Location: 1974 Era, Base Of Stairs Facility:
---	---	---

<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100
--	--	---

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/07/2020
Signature: 
Analyst: Michael Moore

Approved By: 
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 10/7/2020 Report No.: 620590 - PLM Project: Wrangell Medical Center Project No.: 7795-02
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072872(L2)	Analyst Observation: Brown Mastic	Location: 1974 Era, Base Of Stairs
Client No.: WMC920-A111	Client Description: Black Rubber Stair Tread With Brown Mastic	Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 2 Cellulose	<u>Percent Non-Fibrous Material:</u> 98

Lab No.: 7072873	Analyst Observation: Black Stair Tread	Location: 1974 Era, Base Of Stairs
Client No.: WMC920-A112	Client Description: Black Rubber Stair Stringer With Brown Mastic	Facility:
<u>Percent Asbestos:</u> <i>PC 1 Chrysotile</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 99

Lab No.: 7072873(L2)	Analyst Observation: Brown Mastic	Location: 1974 Era, Base Of Stairs
Client No.: WMC920-A112	Client Description: Black Rubber Stair Stringer With Brown Mastic	Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 3 Talc	<u>Percent Non-Fibrous Material:</u> 97

Lab No.: 7072874	Analyst Observation: Black Undercoating	Location: 1974 Era, Break Rm 9, Stainless Steel Sink
Client No.: WMC920-A113	Client Description: Black Sink Undercoating	Facility:
<u>Percent Asbestos:</u> <i>PC 2.6 Chrysotile</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 97.4

Lab No.: 7072875	Analyst Observation: White/Brown Flooring	Location: 1974 Era, Restroom 12, At Cleanout
Client No.: WMC920-A114	Client Description: Marlite And Brown Mastic	Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 80 Cellulose	<u>Percent Non-Fibrous Material:</u> 20

Lab No.: 7072875(L2)	Analyst Observation: Brown Mastic	Location: 1974 Era, Restroom 12, At Cleanout
Client No.: WMC920-A114	Client Description: Marlite And Brown Mastic	Facility:
<u>Percent Asbestos:</u> <i>PC Trace Chrysotile</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	<u>Percent Non-Fibrous Material:</u> 100

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/07/2020
Signature:
Analyst: Michael Moore

Approved By:
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 10/7/2020 Report No.: 620590 - PLM Project: Wrangell Medical Center Project No.: 7795-02
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072876 Client No.: WMC920-A115	Analyst Observation: White Insulation Client Description: White, Chalky Fire Door Insulation	Location: 1974 Era, Door Between Back Hallway And Laundry 15, UL Listed 1.5 Hour Rating Facility: Percent Non-Fibrous Material: 40
<u>Percent Asbestos:</u> 60 Chrysotile	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	

Lab No.: 7072877 Client No.: WMC920-A116	Analyst Observation: Red Sealant Client Description: Red Duct Sealant	Location: 1974 Era, Mech/Fan Rm 3, On Mixing Side Of Plenum Wall Facility: Percent Non-Fibrous Material: 84.8
<u>Percent Asbestos:</u> PC 5.2 Chrysotile	<u>Percent Non-Asbestos Fibrous Material:</u> 10 Talc	

Lab No.: 7072878 Client No.: WMC920-A117	Analyst Observation: Red Sealant Client Description: Red Duct Sealant	Location: 1974 Era, Mech/Fan Rm 3, At Bar Steel Flange Facility: Percent Non-Fibrous Material: 85
<u>Percent Asbestos:</u> PC 5.0 Chrysotile	<u>Percent Non-Asbestos Fibrous Material:</u> 10 Talc	

Lab No.: 7072879 Client No.: WMC920-A118	Analyst Observation: Grey Sealant Client Description: Gray Sealant At Fan Sections	Location: 1974 Era, Mech/Fan Rm 3, Fan 10013 Facility: Percent Non-Fibrous Material: 100
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	

Lab No.: 7072880 Client No.: WMC920-A119	Analyst Observation: Black Duct Material Client Description: Ventglas Black Neoprene Duct Flexible Connector	Location: 1974 Era, Mech/Fan Rm 3, Outlet Side Of Squirrel Fan Facility: Percent Non-Fibrous Material: 85
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 15 Fibrous Glass	

Lab No.: 7072881 Client No.: WMC920-A120	Analyst Observation: Grey Grout Client Description: Gray Ceramic Tile Grout	Location: 1974 Era, Restroom 12, Loose Grout In Crack In Base By Door Facility: Percent Non-Fibrous Material: 100
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> None Detected	

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/07/2020
Signature:
Analyst: Michael Moore

Approved By:
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated 11901 Business Blvd., Ste 208 Eagle River AK 99577	Report Date: 10/7/2020 Report No.: 620590 - PLM Project: Wrangell Medical Center Project No.: 7795-02
Client: EHS511	

PLM BULK SAMPLE ANALYSIS SUMMARY

Lab No.: 7072882 Client No.: WMC920-A121	Analyst Observation: Tan Ceiling Tile Client Description: GCT-1, 12x12 Glued On Ceiling Tile, Groove For Concealed Grid, Directional Medium Fissures, 1/16" Ho	Location: 1974 Era, Hallway 6, At Speaker Box Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 50 Fibrous Glass 30 Cellulose	<u>Percent Non-Fibrous Material:</u> 20

Lab No.: 7072882(L2) Client No.: WMC920-A121	Analyst Observation: Brown Mastic Client Description: GCT-1, 12x12 Glued On Ceiling Tile, Groove For Concealed Grid, Directional Medium Fissures, 1/16" Ho	Location: 1974 Era, Hallway 6, At Speaker Box Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 2 Fibrous Glass	<u>Percent Non-Fibrous Material:</u> 98

Lab No.: 7072883 Client No.: WMC920-A122	Analyst Observation: Black/Red Lining Client Description: Black Tarry Lining Of Red Speaker Box	Location: 1974 Era, Hallway 6, At Speaker Box Facility:
<u>Percent Asbestos:</u> <i>None Detected</i>	<u>Percent Non-Asbestos Fibrous Material:</u> 30 Cellulose 15 Fibrous Glass	<u>Percent Non-Fibrous Material:</u> 55

Please refer to the Appendix of this report for further information regarding your analysis.

Date Received: 10/5/2020
Date Analyzed: 10/07/2020
Signature:
Analyst: Michael Moore

Approved By:
Frank E. Ehrenfeld, III
Laboratory Director

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated
11901 Business Blvd., Ste 208
Eagle River AK 99577

Report Date: 10/7/2020
Report No.: 620590 - PLM
Project: Wrangell Medical Center
Project No.: 7795-02

Client: EHS511

Appendix to Analytical Report

Customer Contact: Cali Swatowski

Method: 40 CFR Appendix E to Subpart E of Part 763, interim method for the Determination of Asbestos in Bulk Insulation Samples, and USEPA 600, R93-116 as needed.

This appendix seeks to promote greater understanding of any observations, exceptions, special instructions, or circumstances that the laboratory needs to communicate to the client concerning the above samples. The information below is used to help promote your ability to make the most informed decisions for you and your customers. Please note the following points of contact for any questions you may have.

iATL Customer Service: customerservice@iatl.com

iATL Office Manager: wchampion@iatl.com

iATL Account Representative: Semih Kocahasan

Sample Login Notes: See Batch Sheet Attached

Sample Matrix: Bulk Building Materials

Exceptions Noted: See Following Pages

General Terms, Warrants, Limits, Qualifiers:

General information about iATL capabilities and client/laboratory relationships and responsibilities are spelled out in iATL policies that are listed at www.iATL.com and in our Quality Assurance Manual per ISO 17025 standard requirements. The information therein is a representation of iATL definitions and policies for turnaround times, sample submittal, collection media, blank definitions, quantification issues and limit of detection, analytical methods and procedures, sub-contracting policies, results reporting options, fees, terms, and discounts, confidentiality, sample archival and disposal, and data interpretation.

iATL warrants the test results to be of a precision normal for the type and methodology employed for each sample submitted. iATL disclaims any other warrants, expressed or implied, including warranty of fitness for a particular purpose and warranty of merchantability. iATL accepts no legal responsibility for the purpose for which the client uses test results. Any analytical work performed must be governed by our Standard Terms and Conditions. Prices, methods and detection limits may be changed without notification. Please contact your Customer Service Representative for the most current information.

This confidential report relates only to those item(s) tested and does not represent an endorsement by NIST-NVLAP, AIHA LAP LLC, or any agency of local, state or province governments nor of any agency of the U.S. government.

This report shall not be reproduced except in full, without written approval of the laboratory.

Information Pertinent to this Report:

Analysis by US EPA 600 93-116: Determination of Asbestos in Bulk Building Materials by Polarized Light Microscopy (PLM).

Certifications:

- NIST-NVLAP No. 101165-0
- NYSDOH-ELAP No. 11021
- AIHA-LAP, LLC No. 100188

Quantification at <0.25% by volume is possible with this method. (PC) Indicates Stratified Point Count Method performed. (PC-Trace) means that asbestos was detected but is not quantifiable under the Point Counting regimen. PC Trace represents a <0.25% amount. Analysis includes all distinct separable layers in accordance with EPA 600 Method. If not reported or otherwise noted, layer is either not present or the client has specifically requested that it not be analyzed (ex. analyze until positive instructions). Small asbestos fibers may be missed by PLM due to resolution limitations of the optical microscope. Therefore, PLM is not consistently reliable in detecting asbestos in non-friable organically bound (NOB) materials. Quantitative transmission electron microscopy (TEM) is currently the only method that can pronounce materials as non-asbestos containing.

Analytical Methodology Alternatives: Your initial request for analysis may not have accounted for recent advances in regulatory requirements or advances in technology that are routinely used in similar situations for other qualified projects. You may have the option to explore additional analysis for further information. Below are a few options, listed as the matrix followed by the appropriate methodology. Also included are links to more information on our website.

Bulk Building Materials that are Non-Friable Organically Bound (NOB) by Gravimetric Reduction techniques employing PLM and TEM: ELAP 198.6 (PLM-NOB), ELAP 198.4 (TEM-NOB)

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated
11901 Business Blvd., Ste 208
Eagle River AK 99577

Report Date: 10/7/2020
Report No.: 620590 - PLM
Project: Wrangell Medical Center
Project No.: 7795-02

Client: EHS511

Loose Fill Vermiculite Insulation, Attic Insulation, Zonolite (copyright), etc.: US EPA 600 R-4/004 (multi-tiered analytical process)
Sprayed On Insulation/Fireproofing with Vermiculite (SOF-V): ELAP 198.8 (PLM-SOF-V)

Soil, sludge, sediment, aggregate, and like materials analyzed for asbestos or other elongated mineral particles (ex. erionite, etc.): ASTM D7521, CARB 435, and other options available

Asbestos in Surface Dust according to one of ASTM's Methods (very dependent on sampling collection technique – by TEM): ASTM D 5755, D5756, or D6480

Various other asbestos matrices (air, water, etc.) and analytical methods are available.

Disclaimers / Qualifiers:

There may be some samples in this project that have a "NOTE:" associated with a sample result. We use added disclaimers or qualifiers to inform the client about something that requires further explanation. Here is a list with highlighted disclaimers that may be pertinent to this project. For a full explanation of these and other disclaimers, please inquire at customerservice@iatl.com.

- 1) Note: No mastic provided for analysis.
- 2) Note: Insufficient mastic provided for analysis.
- 3) Note: Insufficient material provided for analysis.
- 4) Note: Insufficient sample provided for QC reanalysis.
- 5) Note: Different material than indicated on Sample Log / Description.
- 6) Note: Sample not submitted.
- 7) Note: Attached to asbestos containing material.
- 8) Note: Received wet.
- 9) Note: Possible surface contamination.
- 10) Note: Not building material. 1% threshold may not apply.
- 11) Note: Recommend TEM-NOB analysis as per EPA recommendations.
- 12) Note: Asbestos detected but not quantifiable.
- 13) Note: Multiple identical samples submitted, only one analyzed.
- 14) Note: Analyzed by EPA 600/R-93/116. Point Counting detection limit at 0.080%.
- 15) Note: Analyzed by EPA 600/R-93/116. Point Counting detection limit at 0.125%.
- 16) Note: This sample contains >10% vermiculite mineral. See Appendix for Recommendations for Vermiculite Analysis.

Recommendations for Vermiculite Analysis:

Several analytical protocols exist for the analysis of asbestos in vermiculite. These analytical approaches vary depending upon the nature of the vermiculite mineral being tested (e.g. un-processed gange, homogeneous exfoliated books of mica, or mixed mineral composites). Please contact your client representative for pricing and turnaround time options available.

iATL recommends initial testing using the EPA 600/R-93/116 method. This method is specifically designed for the analysis of asbestos in bulk building materials. It provides an acceptable starting point for primary screening of vermiculite for possible asbestos.

Results from this testing may be inconclusive. EPA suggests proceeding to a multi-tiered analysis involving wet separation techniques in conjunction with PLM and TEM gravimetric analysis (EPA 600/R-04/004).

For New York State customers, NYSDOH requires disclaimers and qualifiers for various vermiculite containing samples that direct analysis via ELAP198.6 and ELAP198.8 for samples that contain >10% vermiculite mineral where ELAP198.6 may be used to evaluate the asbestos content of the material. However, any test result using ELAP198.6 will be reported with the following disclaimer: "ELAP198.6 method does not remove vermiculite and may underestimate the level of asbestos present in a sample containing >10% vermiculite."

Further information on this method and other vermiculite and asbestos issues can be found at the following: Agency for Toxic Substances and Disease Registry (ATSDR) www.atsdr.cdc.gov, United States Geological Survey (USGS) www.minerals.usgs.gov/minerals/, US EPA www.epa.gov/asbestos. The USEPA also has an informative brochure "Current Best Practices for Vermiculite Attic Insulation" EPA 747F03001 May 2003, that may assist the health and remediation professional. NYS customers please follow current NYSDOH ELAP requirements per policy on subject of surfacing and vermiculite, May 6, 2016, Testing Requirements for Surfacing Material Containing Vermiculite (https://www.wadsworth.org/sites/default/files/WebDoc/I198_8_02_2.pdf)

The following is a summary of the analytical process outlines in the EPA 600/R-04/004 Method:

- 1) **Analytical Step/Method:** Initial Screening by PLM, EPA 600R-93/116
Requirements/Comments: Minimum of 0.1 g of sample. ~0.25% for most samples.

CERTIFICATE OF ANALYSIS

Client: EHS Alaska Incorporated
11901 Business Blvd., Ste 208
Eagle River AK 99577

Client: EHS511

Report Date: 10/7/2020
Report No.: 620590 - PLM
Project: Wrangell Medical Center
Project No.: 7795-02

2)**Analytical Step/Method:** Wet Separation by PLM Gravimetric Technique, EPA R-04/004
Requirements/Comments: Minimum 50g** of dry sample. Analysis of "Sinks" only.

3)**Analytical Step/Method:** Wet Separation by PLM Gravimetric Technique, EPA R-04/004
Requirements/Comments: Minimum 50g** of dry sample. Analysis of "Floats" only.

4)**Analytical Step/Method:** Wet Separation by TEM Gravimetric Technique, EPA R-04/004
Requirements/Comments: Minimum 50g** of dry sample. Analysis of "Sinks" only.

5)**Analytical Step/Method:** Wet Separation by TEM Gravimetric Technique, EPA R-04/004
Requirements/Comments: Minimum 50g** of dry sample. Analysis of "Suspension" only.
*With advance notice and confirmation by the laboratory.

**Approximately 1 Liter of sample in double-bagged container (~9x6 inch bag of sample).

APPENDIX B

Lead Analyzer Test Results

LEAD ANALYZER TEST RESULTS

Heuresis Pb200i, Serial No. 1770

NO.	SITE	INSPECTOR	FLOOR	ROOM	COMPONENT	SUBSTRATE	CONDITION	COLOR	DURATION	TIME	RESULTS		
											LBP	mg/cm ²	+/- ERROR
READINGS PRIOR TO 216 ARE FROM A DIFFERENT FACILITY AND NOT INCLUDED HERE													
216	WRANGELL MEDICAL CENTER	FRENCH	-	-	CALIBRATION	-	-	GREEN	5	9/17/20 19:14:50	POSITIVE	1	0.1
217	WRANGELL MEDICAL CENTER	FRENCH	-	-	CALIBRATION	-	-	GREEN	5	9/17/20 19:15:22	POSITIVE	1	0.1
218	WRANGELL MEDICAL CENTER	FRENCH	-	-	CALIBRATION	-	-	GREEN	5	9/17/20 19:15:35	POSITIVE	1	0.1
219	WRANGELL MEDICAL CENTER	FRENCH	FIRST	EXTERIOR	DOOR FRAME	METAL	INTACT	BROWN	5.73	9/17/20 19:23:27	NEGATIVE	0.16	0.12
220	WRANGELL MEDICAL CENTER	FRENCH	FIRST	EXTERIOR	DOOR	WOOD	INTACT	BROWN	5.85	9/17/20 19:26:51	NEGATIVE	0.05	0.12
221	WRANGELL MEDICAL CENTER	FRENCH	FIRST	EXTERIOR	WINDOW CASING	WOOD	INTACT	BROWN	1.57	9/17/20 19:29:17	NEGATIVE	0.35	0.24
222	WRANGELL MEDICAL CENTER	FRENCH	FIRST	EXTERIOR	TANK	METAL	INTACT	RED	2.81	9/17/20 19:31:42	NEGATIVE	0.24	0.18
223	WRANGELL MEDICAL CENTER	FRENCH	FIRST	EXTERIOR	BOLLARD	METAL	INTACT	YELLOW	5.94	9/17/20 19:32:56	NEGATIVE	0.09	0.12
224	WRANGELL MEDICAL CENTER	FRENCH	FIRST	EXTERIOR	WALL	METAL	INTACT	RED	5.84	9/17/20 19:34:30	NEGATIVE	0.15	0.12
225	WRANGELL MEDICAL CENTER	FRENCH	FIRST	EXTERIOR	DOOR	METAL	INTACT	BROWN	4.33	9/17/20 19:37:28	NEGATIVE	0.03	0.14
226	WRANGELL MEDICAL CENTER	FRENCH	FIRST	EXTERIOR	EQUIPMENT	METAL	INTACT	BEIGE	4.79	9/17/20 19:38:37	NEGATIVE	0.1	0.14
227	WRANGELL MEDICAL CENTER	FRENCH	FIRST	EXTERIOR	BOLLARD	METAL	INTACT	RED	4.95	9/17/20 19:41:09	NEGATIVE	0.06	0.13
228	WRANGELL MEDICAL CENTER	FRENCH	FIRST	EXTERIOR	WALL	METAL	INTACT	RED	6.44	9/17/20 19:43:11	NEGATIVE	-0.19	0.12
229	WRANGELL MEDICAL CENTER	FRENCH	FIRST	EXTERIOR	EQUIPMENT	METAL	INTACT	WHITE	5.63	9/17/20 19:45:17	NEGATIVE	0.08	0.13
230	WRANGELL MEDICAL CENTER	FRENCH	FIRST	EXTERIOR	WALL	EFIS	INTACT	DK BROWN	5.96	9/17/20 19:47:35	NEGATIVE	0.11	0.12
231	WRANGELL MEDICAL CENTER	FRENCH	FIRST	EXTERIOR	WALL	EFIS	INTACT	DK BROWN	5.68	9/17/20 19:49:02	NEGATIVE	0.11	0.13
232	WRANGELL MEDICAL CENTER	FRENCH	FIRST	EXTERIOR	DOOR	WOOD	INTACT	DK BROWN	5.95	9/17/20 19:50:06	NEGATIVE	0.12	0.12
233	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	EXTERIOR	WALL	EFIS	INTACT	BEIGE	5.16	9/17/20 19:51:36	NEGATIVE	0.14	0.13
234	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	EXTERIOR	WALL	CONCRETE	INTACT	BEIGE	5.43	9/17/20 19:53:02	NEGATIVE	0.11	0.13
235	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	EXTERIOR	BEAM	WOOD	INTACT	BROWN	6.13	9/17/20 19:55:20	NEGATIVE	0.07	0.12
236	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	EXTERIOR	COLUMN	EFIS	INTACT	BEIGE	5.65	9/17/20 19:58:05	NEGATIVE	0.05	0.13
237	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	EXTERIOR	PIPE	METAL	INTACT	RED	6.01	9/17/20 20:00:56	NEGATIVE	0.09	0.12
238	WRANGELL MEDICAL CENTER	FRENCH	FIRST	95	DOOR FRAME	WOOD	INTACT	VARNISH	5.91	9/17/20 20:03:48	NEGATIVE	0.04	0.12
239	WRANGELL MEDICAL CENTER	FRENCH	FIRST	EXTERIOR	WINDOW CASING	METAL	INTACT	BROWN	5.65	9/17/20 20:05:14	NEGATIVE	0.43	0.13
240	WRANGELL MEDICAL CENTER	FRENCH	FIRST	EXTERIOR	COLUMN	EFIS	INTACT	BEIGE	5.88	9/17/20 20:07:17	NEGATIVE	0.17	0.12
241	WRANGELL MEDICAL CENTER	FRENCH	FIRST	EXTERIOR	DOOR	WOOD	INTACT	BROWN	5.92	9/17/20 20:09:34	NEGATIVE	0.02	0.12
242	WRANGELL MEDICAL CENTER	FRENCH	FIRST	EXTERIOR	FASCIA	EFIS	INTACT	BLACK	2.89	9/17/20 20:57:37	NEGATIVE	0.11	0.18
243	WRANGELL MEDICAL CENTER	FRENCH	FIRST	EXTERIOR	FASCIA	WOOD	INTACT	BEIGE	6.74	9/17/20 20:59:41	NEGATIVE	0.15	0.12
244	WRANGELL MEDICAL CENTER	FRENCH	FIRST	EXTERIOR	FASCIA	DRYWALL	INTACT	BEIGE	5.86	9/17/20 21:00:46	NEGATIVE	0.13	0.12
245	WRANGELL MEDICAL CENTER	FRENCH	-	-	CALIBRATION	-	-	GREEN	5	9/17/20 21:04:51	POSITIVE	1	0.1
246	WRANGELL MEDICAL CENTER	FRENCH	-	-	CALIBRATION	-	-	GREEN	5	9/17/20 21:05:03	POSITIVE	1	0.1
247	WRANGELL MEDICAL CENTER	FRENCH	-	-	CALIBRATION	-	-	GREEN	5	9/17/20 21:05:16	POSITIVE	1	0.1
READINGS 248 THRU 280 ARE FROM A DIFFERENT FACILITY AND NOT INCLUDED HERE													
281	WRANGELL MEDICAL CENTER	FRENCH	-	-	CALIBRATION	-	-	GREEN	5	9/18/20 12:41:39	POSITIVE	1	0.1
282	WRANGELL MEDICAL CENTER	FRENCH	-	-	CALIBRATION	-	-	GREEN	5	9/18/20 12:41:51	POSITIVE	1	0.1
283	WRANGELL MEDICAL CENTER	FRENCH	-	-	CALIBRATION	-	-	GREEN	5	9/18/20 12:42:03	POSITIVE	1	0.1
284	WRANGELL MEDICAL CENTER	FRENCH	FIRST	22	WALL	DRYWALL	INTACT	WHITE	2	9/18/20 12:43:22	NEGATIVE	0.2	0.3
285	WRANGELL MEDICAL CENTER	FRENCH	FIRST	22	CABINET	FORMICA	INTACT	BEIGE	5.49	9/18/20 12:44:22	NEGATIVE	0.13	0.13
286	WRANGELL MEDICAL CENTER	FRENCH	FIRST	22	DOOR FRAME	METAL	INTACT	BEIGE	5.27	9/18/20 12:45:54	NEGATIVE	0.09	0.13
287	WRANGELL MEDICAL CENTER	FRENCH	FIRST	27	DOOR FRAME	METAL	INTACT	GRAY	4.77	9/18/20 12:47:45	NEGATIVE	0.5	0.14
288	WRANGELL MEDICAL CENTER	FRENCH	FIRST	27	DOOR	WOOD	INTACT	VARNISH	5.49	9/18/20 12:48:57	NEGATIVE	0.03	0.13
289	WRANGELL MEDICAL CENTER	FRENCH	FIRST	26	LOCKER	METAL	INTACT	BLUE	5.64	9/18/20 12:51:43	NEGATIVE	0.09	0.13
290	WRANGELL MEDICAL CENTER	FRENCH	FIRST	26	WALL	DRYWALL	INTACT	WHITE	5.82	9/18/20 12:53:12	NEGATIVE	0.22	0.12
291	WRANGELL MEDICAL CENTER	FRENCH	FIRST	23	DOOR	METAL	INTACT	BROWN	6.6	9/18/20 12:55:42	NEGATIVE	0.11	0.12
292	WRANGELL MEDICAL CENTER	FRENCH	FIRST	23	DOOR FRAME	WOOD	INTACT	WHITE	6.02	9/18/20 12:56:12	NEGATIVE	0.1	0.12
293	WRANGELL MEDICAL CENTER	FRENCH	FIRST	24	WALL	DRYWALL	INTACT	WHITE	5.51	9/18/20 12:58:02	NEGATIVE	0.11	0.13
294	WRANGELL MEDICAL CENTER	FRENCH	FIRST	24	FLOOR	CONCRETE	INTACT	GRAY	5.6	9/18/20 12:59:09	NEGATIVE	0.21	0.13
295	WRANGELL MEDICAL CENTER	FRENCH	FIRST	25	DOOR	WOOD	INTACT	YELLOW	3.72	9/18/20 13:01:30	NEGATIVE	0.09	0.16
296	WRANGELL MEDICAL CENTER	FRENCH	FIRST	25	HAND RAIL	WOOD	INTACT	WHITE	6.18	9/18/20 13:03:23	NEGATIVE	0.07	0.12
297	WRANGELL MEDICAL CENTER	FRENCH	FIRST	25	BEAM	METAL	INTACT	WHITE	5.51	9/18/20 13:05:01	NEGATIVE	0.14	0.13
298	WRANGELL MEDICAL CENTER	FRENCH	SECOND	25	WALL	DRYWALL	INTACT	WHITE	5.45	9/18/20 13:06:26	NEGATIVE	0.09	0.13
299	WRANGELL MEDICAL CENTER	FRENCH	SECOND	25	WALL	DRYWALL	INTACT	WHITE	5.48	9/18/20 13:08:20	NEGATIVE	0.13	0.13

LEAD ANALYZER TEST RESULTS

NO.	SITE	INSPECTOR	FLOOR	ROOM	COMPONENT	SUBSTRATE	CONDITION	COLOR	DURATION	TIME	RESULTS		
											LBP	mg/cm ²	+/- ERROR
300	WRANGELL MEDICAL CENTER	FRENCH	SECOND	29	COUNTERTOP	WOOD	INTACT	GRAY	6.45	9/18/20 13:12:38	NEGATIVE	0.12	0.12
301	WRANGELL MEDICAL CENTER	FRENCH	FIRST	29	DOOR	METAL	INTACT	BLACK	5.3	9/18/20 13:13:53	NEGATIVE	0.36	0.13
302	WRANGELL MEDICAL CENTER	FRENCH	FIRST	29	WALL	DRYWALL	INTACT	WHITE	5.61	9/18/20 13:21:20	NEGATIVE	0.11	0.13
303	WRANGELL MEDICAL CENTER	FRENCH	FIRST	30 (IN HALLWAY)	WALL	DRYWALL	INTACT	WHITE	5.26	9/18/20 13:25:18	NEGATIVE	0.14	0.13
304	WRANGELL MEDICAL CENTER	FRENCH	FIRST	30	WALL	DRYWALL	INTACT	WHITE	6	9/18/20 13:26:52	NEGATIVE	0.16	0.12
305	WRANGELL MEDICAL CENTER	FRENCH	FIRST	30	PIPE	METAL	INTACT	GREEN	5.23	9/18/20 13:27:58	NEGATIVE	0.09	0.13
306	WRANGELL MEDICAL CENTER	FRENCH	FIRST	30	PIPE	METAL	INTACT	BLUE	4.08	9/18/20 13:28:55	NEGATIVE	0.1	0.15
307	WRANGELL MEDICAL CENTER	FRENCH	FIRST	30	PIPE	METAL	INTACT	RED	4.81	9/18/20 13:29:54	NEGATIVE	0.16	0.14
308	WRANGELL MEDICAL CENTER	FRENCH	FIRST	34 (IN HALLWAY)	WALL	DRYWALL	INTACT	GREEN	1.93	9/18/20 13:32:01	NEGATIVE	0.09	0.22
309	WRANGELL MEDICAL CENTER	FRENCH	FIRST	31 (IN HALLWAY)	WALL	DRYWALL	INTACT	WHITE	5.58	9/18/20 13:33:34	NEGATIVE	0.17	0.13
310	WRANGELL MEDICAL CENTER	FRENCH	FIRST	115	RADIATOR	METAL	INTACT	WHITE	5.91	9/18/20 13:35:29	NEGATIVE	0.13	0.12
311	WRANGELL MEDICAL CENTER	FRENCH	FIRST	115	WINDOW CASING	WOOD	INTACT	VARNISH	5.65	9/18/20 13:36:47	NEGATIVE	0	0.13
312	WRANGELL MEDICAL CENTER	FRENCH	FIRST	115	COUNTERTOP	FORMICA	INTACT	BEIGE	5.78	9/18/20 13:37:54	NEGATIVE	0.16	0.12
313	WRANGELL MEDICAL CENTER	FRENCH	FIRST	108	FLOOR	CONCRETE	INTACT	GRAY	5.55	9/18/20 13:41:18	NEGATIVE	0.21	0.13
314	WRANGELL MEDICAL CENTER	FRENCH	FIRST	108	ELECTRICAL PANEL	METAL	INTACT	GRAY	5.55	9/18/20 13:42:07	NEGATIVE	0.14	0.13
315	WRANGELL MEDICAL CENTER	FRENCH	FIRST	109	SINK	CERAMIC	INTACT	WHITE	5.62	9/18/20 13:49:27	POSITIVE	21.34	0.13
316	WRANGELL MEDICAL CENTER	FRENCH	FIRST	109	DOOR	WOOD	INTACT	VARNISH	6.16	9/18/20 13:50:24	NEGATIVE	0.08	0.12
317	WRANGELL MEDICAL CENTER	FRENCH	FIRST	114	WALL	VINYL	INTACT	BEIGE	5.75	9/18/20 14:05:19	NEGATIVE	0.1	0.12
318	WRANGELL MEDICAL CENTER	FRENCH	FIRST	114	COUNTERTOP	FORMICA	INTACT	BEIGE	5.5	9/18/20 14:07:37	NEGATIVE	0.23	0.13
319	WRANGELL MEDICAL CENTER	FRENCH	FIRST	35	COUNTERTOP	FORMICA	INTACT	BEIGE	5.75	9/18/20 14:10:06	NEGATIVE	0.06	0.12
320	WRANGELL MEDICAL CENTER	FRENCH	FIRST	35	WALL	DRYWALL	INTACT	BEIGE	5.7	9/18/2020 14:11	NEGATIVE	0.3	0.13
321	WRANGELL MEDICAL CENTER	FRENCH	FIRST	35	CABINET	FORMICA	INTACT	OFF-WHITE	5.64	9/18/20 14:12:53	NEGATIVE	0.18	0.13
322	WRANGELL MEDICAL CENTER	FRENCH	FIRST	37	WALL	FRP	INTACT	WHITE	5.62	9/18/20 14:15:13	NEGATIVE	0.13	0.13
323	WRANGELL MEDICAL CENTER	FRENCH	FIRST	38	DOOR FRAME	METAL	INTACT	WHITE	5.58	9/18/20 14:16:55	NEGATIVE	0.09	0.13
324	WRANGELL MEDICAL CENTER	FRENCH	FIRST	35 (IN HALLWAY)	LADDER	METAL	INTACT	WHITE	5.57	9/18/20 14:18:25	NEGATIVE	0.21	0.13
325	WRANGELL MEDICAL CENTER	FRENCH	FIRST	38 (IN HALLWAY)	DOOR FRAME	METAL	INTACT	BEIGE	5.71	9/18/20 14:19:51	NEGATIVE	0.11	0.13
326	WRANGELL MEDICAL CENTER	FRENCH	FIRST	103	WALL	METAL	INTACT	WHITE	5.44	9/18/20 14:21:34	NEGATIVE	0.14	0.13
327	WRANGELL MEDICAL CENTER	FRENCH	FIRST	132	WALL	DRYWALL	INTACT	RED	3.3	9/18/20 14:34:18	NEGATIVE	0.3	0.16
328	WRANGELL MEDICAL CENTER	FRENCH	FIRST	125	WALL	DRYWALL	INTACT	BLUE	5.36	9/18/20 14:35:15	NEGATIVE	0.11	0.13
329	WRANGELL MEDICAL CENTER	FRENCH	FIRST	125	DOOR	METAL	INTACT	BLACK	5.63	9/18/20 14:36:10	NEGATIVE	0.07	0.13
330	WRANGELL MEDICAL CENTER	FRENCH	FIRST	136 (IN HALLWAY)	CABINET	FORMICA	INTACT	BEIGE	6.58	9/18/20 14:41:13	NEGATIVE	0.18	0.12
331	WRANGELL MEDICAL CENTER	FRENCH	FIRST	136	WALL	VINYL	INTACT	OFF-WHITE	4.26	9/18/20 14:42:34	NEGATIVE	0.2	0.14
332	WRANGELL MEDICAL CENTER	FRENCH	FIRST	137	RADIATOR	METAL	INTACT	TAN	5.47	9/18/20 14:43:24	NEGATIVE	0.11	0.13
333	WRANGELL MEDICAL CENTER	FRENCH	FIRST	139 (IN HALLWAY)	DOOR	WOOD	INTACT	VARNISH	6.25	9/18/20 14:44:54	NEGATIVE	0.11	0.12
334	WRANGELL MEDICAL CENTER	FRENCH	FIRST	140	SINK	CERAMIC	INTACT	WHITE	5.25	9/18/20 14:46:36	NEGATIVE	0	0.13
335	WRANGELL MEDICAL CENTER	FRENCH	FIRST	135	DOOR FRAME	METAL	INTACT	PINK	4.9	9/18/20 14:48:08	NEGATIVE	0.22	0.14
336	WRANGELL MEDICAL CENTER	FRENCH	FIRST	135	WALL	FORMICA	INTACT	BEIGE	5.69	9/18/20 14:49:45	NEGATIVE	0.12	0.13
337	WRANGELL MEDICAL CENTER	FRENCH	FIRST	131	SINK	CERAMIC	INTACT	WHITE	3.83	9/18/20 14:52:10	POSITIVE	19.26	0.15
338	WRANGELL MEDICAL CENTER	FRENCH	FIRST	128	WALL	VINYL	INTACT	ORANGE	4.43	9/18/20 14:54:50	NEGATIVE	0.09	0.14
339	WRANGELL MEDICAL CENTER	FRENCH	FIRST	143	WALL	DRYWALL	INTACT	WHITE	5.45	9/18/20 14:58:09	NEGATIVE	0.11	0.13
340	WRANGELL MEDICAL CENTER	FRENCH	FIRST	144	WALL	DRYWALL	INTACT	GRAY	5.7	9/18/20 14:59:01	NEGATIVE	0.15	0.13
341	WRANGELL MEDICAL CENTER	FRENCH	FIRST	147	WALL	DRYWALL	INTACT	OFF-WHITE	4.14	9/18/20 15:02:36	NEGATIVE	0.15	0.15
342	WRANGELL MEDICAL CENTER	FRENCH	FIRST	147	DOOR	WOOD	INTACT	VARNISH	5.82	9/18/20 15:03:43	NEGATIVE	0.02	0.12
343	WRANGELL MEDICAL CENTER	FRENCH	FIRST	151	DOOR	METAL	INTACT	BLACK	5.67	9/18/20 15:05:12	NEGATIVE	0.09	0.13
344	WRANGELL MEDICAL CENTER	FRENCH	FIRST	141	CABINET	FORMICA	INTACT	PINK	5.68	9/18/20 15:06:30	NEGATIVE	0.25	0.13
345	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	21 (IN HALLWAY)	DOOR	METAL	INTACT	BEIGE	5.38	9/18/20 15:27:22	NEGATIVE	0.12	0.13
346	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	21	FLOOR	CONCRETE	INTACT	GRAY	5.81	9/18/20 15:41:48	NEGATIVE	0.19	0.12
347	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	1 (IN HALLWAY)	WALL	DRYWALL	INTACT	OFF-WHITE	5.16	9/18/20 15:43:04	NEGATIVE	0.25	0.13
348	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	20 (IN HALLWAY)	DOOR FRAME	METAL	INTACT	WHITE	5.47	9/18/20 15:43:54	NEGATIVE	0.5	0.13
349	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	2	COUNTERTOP	FORMICA	INTACT	BROWN	5.65	9/18/20 15:44:58	NEGATIVE	0.25	0.13
350	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	2	CABINET	FORMICA	INTACT	WHITE	5.47	9/18/20 15:45:34	NEGATIVE	0.18	0.13
351	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	2	WALL	DRYWALL	INTACT	PINK	6.34	9/18/20 15:46:27	NEGATIVE	0.36	0.12
352	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	1	WALL	DRYWALL	INTACT	PINK	6.03	9/18/20 15:48:22	NEGATIVE	0.15	0.12
353	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	167	WALL	MARLITE	INTACT	GREEN	5.97	9/18/20 15:49:44	NEGATIVE	0.19	0.12

LEAD ANALYZER TEST RESULTS

NO.	SITE	INSPECTOR	FLOOR	ROOM	COMPONENT	SUBSTRATE	CONDITION	COLOR	DURATION	TIME	RESULTS		
											LBP	mg/cm ²	+/- ERROR
354	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	167	FLOOR	CONCRETE	INTACT	GRAY	5.62	9/18/20 15:50:50	NEGATIVE	0.26	0.13
355	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	3	DUCT	METAL	INTACT	PINK	5.44	9/18/20 15:53:42	NEGATIVE	0.11	0.13
356	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	3	DUCT	METAL	INTACT	GRAY	5.42	9/18/20 15:54:16	NEGATIVE	0.06	0.13
357	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	3	PIPE	METAL	INTACT	YELLOW	4.43	9/18/20 15:55:14	NEGATIVE	0.18	0.14
358	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	4	DOOR	METAL	INTACT	GRAY	5.5	9/18/20 15:57:48	NEGATIVE	0.06	0.13
359	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	4	WALL	DRYWALL	INTACT	OFF-WHITE	6.14	9/18/20 15:58:40	NEGATIVE	0.05	0.12
360	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	164	DOOR	WOOD	INTACT	VARNISH	5.85	9/18/20 16:00:28	NEGATIVE	0.04	0.12
361	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	165	WALL	DRYWALL	INTACT	TAN	5.64	9/18/20 16:02:58	NEGATIVE	0.2	0.13
362	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	164	WALL	WOOD	INTACT	OFF-WHITE	5.58	9/18/20 16:04:04	NEGATIVE	0.19	0.13
363	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	5	DOOR FRAME	METAL	INTACT	WHITE	2.68	9/18/20 16:05:26	NEGATIVE	0.13	0.18
364	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	5	WALL	DRYWALL	INTACT	RED	5.21	9/18/20 16:06:45	NEGATIVE	0.15	0.13
365	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	6	WALL	DRYWALL	INTACT	BLUE	3.23	9/18/20 16:08:46	NEGATIVE	0.17	0.17
366	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	7	WALL	DRYWALL	INTACT	BLUE	5.51	9/18/20 16:11:06	NEGATIVE	0.12	0.13
367	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	9	CABINET	FORMICA	INTACT	RED	6.14	9/18/20 16:12:51	NEGATIVE	0.43	0.12
368	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	14	CABINET	FORMICA	INTACT	RED	7.52	9/18/20 16:16:16	NEGATIVE	0.5	0.11
369	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	14	COUNTERTOP	FORMICA	INTACT	BROWN	5.74	9/18/20 16:17:29	NEGATIVE	0.15	0.12
370	WRANGELL MEDICAL CENTER	FRENCH	BASEMENT	37	COUNTERTOP	FORMICA	INTACT	WHITE	4.84	9/18/20 16:18:27	NEGATIVE	0.14	0.14

Table Heading Descriptions:

Duration: This is the nominal time in "source" seconds that each sample was analyzed.

LBP: Results are shown as positive (POS \geq 1.0 mg/cm²) or negative (NEG < 1.0 mg/cm²). Positive results are shown in bold print.


mg/cm²: This is the testing results produced by the Heuresis Pb200i instrument in milligrams of lead per square centimeter (mg/cm²). The EPA defines lead based paint as paint containing lead at 1.0 mg/cm² or greater. A negative number is a result of an internal computation made by the instrument and should be interpreted as zero. Even though paint may be termed negative (less than 1.0 mg/cm²) by EPA definition, disturbance of the paint may still be regulated by OSHA under 29 CFR 1926.62. Where lead is present at any level, appropriate engineering controls, work practices and personal protective equipment should be used until a negative exposure assessment can be determined. <LOD indicates that the lead present was less than the limits of detection of the instrument (very little or no lead present).

VOID: This indicates that the test was intentionally terminated by the operator due to operator error (e.g. - operator moved analyzer while testing).

Substrate: Where ceramic is shown as a substrate, lead content is typically from the glazing on the tile unless the tile is painted.

APPENDIX C

Drawings of Sample Locations



1
C-1

1967 ATTIC & FAN RM
NTS



LEGEND

- — AXX ASBESTOS TEST LOCATION
- — [AXX] LAB TEST RESULTS POSITIVE FOR ASBESTOS


REFER TO TESTING SUMMARY IN REPORT FOR DETAILS. SAMPLES A01-A30 HAVE WMS0920- PREFIX. SAMPLES A31-A122 HAVE WMC920-PREFIX

WRANGELL
CAPITAL FACILITIES
DEPARTMENT

WRANGELL MEDICAL CENTER
WRANGELL, ALASKA
ASBESTOS SAMPLE LOCATIONS



DRAWN: CTO	DATE: 09/14/2020
CHECK: RAF	
FILE #:	DWG.NO:
7795-03-SL	C-1



1
C-2

ROOF & ATTIC
NTS




WRANGELL
CAPITAL FACILITIES
DEPARTMENT

WRANGELL MEDICAL CENTER
WRANGELL, ALASKA
ASBESTOS SAMPLE LOCATIONS



DRAWN: CTO	DATE: 09/14/2020
CHECK: RAF	DWG.NO: C-2
FILE #:	
7795-03-SL	



1
C-3

1974 ERA BASEMENT
NTS



LEGEND


- — AXX ASBESTOS TEST LOCATION
- — AXX LAB TEST RESULTS POSITIVE FOR ASBESTOS
REFER TO TESTING SUMMARY IN REPORT FOR DETAILS. SAMPLES
A01-A30 HAVE WMS0920- PREFIX. SAMPLES A31-A122 HAVE
WMC920-PREFIX

WRANGELL
CAPITAL FACILITIES
DEPARTMENT

WRANGELL MEDICAL CENTER
WRANGELL, ALASKA
ASBESTOS SAMPLE LOCATIONS



DRAWN: CTO	DATE: 09/14/2020
CHECK: RAF	DWG.NO: C-3
FILE #:	
7795-03-SL	



1
C-4

1992 ADDITION
NTS



LEGEND


- — AXX ASBESTOS TEST LOCATION
- — AXX LAB TEST RESULTS POSITIVE FOR ASBESTOS
REFER TO TESTING SUMMARY IN REPORT FOR DETAILS. SAMPLES
A01-A30 HAVE WMS0920- PREFIX. SAMPLES A31-A122 HAVE
WMC920-PREFIX

WRANGELL
CAPITAL FACILITIES
DEPARTMENT

WRANGELL MEDICAL CENTER
WRANGELL, ALASKA
ASBESTOS SAMPLE LOCATIONS



DRAWN: CTO	DATE: 09/14/2020
CHECK: RAF	
FILE #:	DWG.NO:
7795-03-SL	C-4



1
C-5

FIRST FLOOR NORTH



LEGEND


- — AXX ASBESTOS TEST LOCATION
 - — [AXX] LAB TEST RESULTS POSITIVE FOR ASBESTOS
- REFER TO TESTING SUMMARY IN REPORT FOR DETAILS. SAMPLES A01-A30 HAVE WMS0920- PREFIX. SAMPLES A31-A122 HAVE WMC920-PREFIX

WRANGELL
CAPITAL FACILITIES
DEPARTMENT

WRANGELL MEDICAL CENTER
WRANGELL, ALASKA
ASBESTOS SAMPLE LOCATIONS



DRAWN: CTO	DATE: 09/14/2020
CHECK: RAF	DWG.NO: C-5
FILE #:	
7795-03-SL	



1
C-6

FIRST FLOOR WEST
NTS



LEGEND


- — AXX ASBESTOS TEST LOCATION
- — [AXX] LAB TEST RESULTS POSITIVE FOR ASBESTOS
REFER TO TESTING SUMMARY IN REPORT FOR DETAILS. SAMPLES
A01–A30 HAVE WMS0920– PREFIX. SAMPLES A31–A122 HAVE
WMC920–PREFIX

WRANGELL
CAPITAL FACILITIES
DEPARTMENT

WRANGELL MEDICAL CENTER
WRANGELL, ALASKA
ASBESTOS SAMPLE LOCATIONS



DRAWN: CTO	DATE: 09/14/2020
CHECK: RAF	DWG.NO: C-6
FILE #:	
7795-03-SL	



1
C-7

FIRST FLOOR SOUTH
NTS



LEGEND


- — AXX ASBESTOS TEST LOCATION
- — [AXX] LAB TEST RESULTS POSITIVE FOR ASBESTOS
REFER TO TESTING SUMMARY IN REPORT FOR DETAILS. SAMPLES
A01-A30 HAVE WMS0920- PREFIX. SAMPLES A31-A122 HAVE
WMC920-PREFIX

WRANGELL
CAPITAL FACILITIES
DEPARTMENT

WRANGELL MEDICAL CENTER
WRANGELL, ALASKA
ASBESTOS SAMPLE LOCATIONS



DRAWN: CTO	DATE: 09/14/2020
CHECK: RAF	
FILE #:	DWG.NO:
7795-03-SL	C-7



1
C-8

1992 ADDITION
NTS



LEGEND


- LXX LEAD TEST LOCATION
 - LXX LEAD TEST CLASSIFIED AS LEAD BASED PAINT
- REFER TO TESTING SUMMARY IN REPORT FOR FULL DETAILS.

WRANGELL
CAPITAL FACILITIES
DEPARTMENT

WRANGELL MEDICAL CENTER
WRANGELL, ALASKA
LEAD SAMPLE LOCATIONS



DRAWN: CTO	DATE: 09/14/2020
CHECK: RAF	
FILE #:	DWG.NO:
7795-03-SL	C-8



1
C-9

FIRST FLOOR NORTH



LEGEND

- LXX LEAD TEST LOCATION
- LXX LEAD TEST CLASSIFIED AS LEAD BASED PAINT


REFER TO TESTING SUMMARY IN REPORT FOR FULL DETAILS.

**WRANGELL
CAPITAL FACILITIES
DEPARTMENT**

**WRANGELL MEDICAL CENTER
WRANGELL, ALASKA
LEAD SAMPLE LOCATIONS**



DRAWN: CTO	DATE: 09/14/2020
CHECK: RAF	DWG.NO: C-9
FILE #:	
7795-03-SL	



1
C-10

FIRST FLOOR WEST
NTS



LEGEND


- LXX LEAD TEST LOCATION
 - LXX LEAD TEST CLASSIFIED AS LEAD BASED PAINT
- REFER TO TESTING SUMMARY IN REPORT FOR FULL DETAILS.

WRANGELL
CAPITAL FACILITIES
DEPARTMENT

WRANGELL MEDICAL CENTER
WRANGELL, ALASKA
LEAD SAMPLE LOCATIONS



DRAWN: CTO	DATE: 09/14/2020
CHECK: RAF	DWG.NO: C-10
FILE #:	
7795-03-SL	



1
C-11

FIRST FLOOR SOUTH
NTS



LEGEND


- LXX LEAD TEST LOCATION
 - LXX LEAD TEST CLASSIFIED AS LEAD BASED PAINT
- REFER TO TESTING SUMMARY IN REPORT FOR FULL DETAILS.

WRANGELL
CAPITAL FACILITIES
DEPARTMENT

WRANGELL MEDICAL CENTER
WRANGELL, ALASKA
LEAD SAMPLE LOCATIONS



DRAWN: CTO	DATE: 09/14/2020
CHECK: RAF	
FILE #: 7795-03-SL	DWG.NO: C-11



1
C-12

1974 ERA BASEMENT
NTS



LEGEND

- LXX LEAD TEST LOCATION
 - LXX LEAD TEST CLASSIFIED AS LEAD BASED PAINT
- REFER TO TESTING SUMMARY IN REPORT FOR FULL DETAILS.

WRANGELL
CAPITAL FACILITIES
DEPARTMENT

WRANGELL MEDICAL CENTER
WRANGELL, ALASKA
LEAD SAMPLE LOCATIONS



DRAWN: CTO	DATE: 09/14/2020
CHECK: RAF	
FILE #:	DWG.NO:
7795-03-SL	C-12