

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-06		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 WRANGELL, AK 99929							
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
				B. Transporter 1 Phone 907-258-1558			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID			
				F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No.	Type		
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1	CM	41000	P
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
1) 128731OR LEAD CONTAMINTED SOILS				D19814 WMTC 6190			
15. Special Handling Instructions and Additional Information							
Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature <i>[Signature]</i>		Date Month 10 Day 5 Year 18	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date			
Printed/Typed Name Shane O'Neill				Signature <i>[Signature]</i>		Month 10 Day 5 Year 18	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date			
Printed/Typed Name H Standow				Signature <i>[Signature]</i>		Month 10 Day 6 Year 18	
19. Discrepancy Indication Space profile 122948 OR							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames				Signature <i>[Signature]</i>		Date Month 11 Day 13 Year 18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY


DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

EPA Form 8700-22A (Rev. 3-05) Previous editions are obsolete. **DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)**

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-07		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 56.4227 N & 132.3563 W WRANGELL, AK 99929							
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
				B. Transporter 1 Phone 907-258-1558			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID			
				F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION HM a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				Containers		13. Total Quantity	
				No.	Type		
				1	CM	409 60	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 un+0 62 62			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature 		Date Month 10 Day 5 Year 18	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature 		Date Month 10 Day 9 Year 18	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature 		Date Month 10 Day 6 Year 18	
19. Discrepancy Indication Space profile 122948OR							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Signature 		Date Month 12 Day 12 Year 18	
Printed/Typed Name Toni Ames							

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY


GENERATOR

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474	22. Page 3	23. Manifest Tracking Number 115885-07		
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929						
25. Transporter _____ Company Name 5 COLUMBIA RIDGE RECY. & LNDFL.				U.S. EPA ID Number ORD987173457		
26. Transporter _____ Company Name 6				U.S. EPA ID Number		
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
32. Special Handling Instructions and Additional Information						
TRANSPORTER	33. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year					
	34. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year					
DESIGNATED FACILITY	35. Discrepancy					
	36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)					

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000208474		Manifest Document No. 115885-08		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 56.4227 N & 132.3563 W WRANGELL, AK 99929 56.4227 N & 132.3563 W WRANGELL, AK 99929							
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
				B. Transporter 1 Phone 907-258-1558			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID			
				F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No.	Type		
HM a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1	CM	40790	P
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 WXXV 6249			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature 		Date Month 10 Day 5 Year 18	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature 		Date Month 10 Day 5 Year 18	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature 		Date Month 10 Day 6 Year 18	
19. Discrepancy Indication Space profile 1229480R							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Signature 		Date Month 12 Day 12 Year 18	
Printed/Typed Name Tom Ames							

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-10		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR P.O. BOX 531 WRANGELL, AK 99929				CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929			
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID		B. Transporter 1 Phone 907-258-1558	
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470539		C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID		F. Facility's Phone (541) 454-2030	
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1 CM		40680 P	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 WMTU 6410			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Reilly				Signature [Signature]		Date 10/5/18	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature [Signature]		Date 10/5/18	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature [Signature]		Date 10/6/18	
19. Discrepancy Indication Space profile 1229480R							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Signature [Signature]		Date 11/28/18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474	22. Page 2	23. Manifest Tracking Number 115885-10			
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929							
25. Transporter Company Name 3 NRC ENVIRONMENTAL SERVICES				U.S. EPA ID Number CAR000030114			
26. Transporter Company Name 4 UNION PACIFIC				U.S. EPA ID Number NED001792910			
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes	
		No.	Type				
32. Special Handling Instructions and Additional Information							
33. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name: Dana M. Mc... Signature: [Signature] Month: 11 Day: 16 Year: 18							
34. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name: Michael Emuel Signature: [Signature] Month: 11 Day: 16 Year: 18							
35. Discrepancy							
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							

GENERATOR

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-14		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 56.4227 N & 132.3563 W WRANGELL, AK 99929 WRANGELL, AK 99929							
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		B. Transporter 1 Phone 907-258-1558			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		C. State Transporter's ID			
				D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1 CM		40850 P	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINTED SOILS				H. Handling Codes for Wastes Listed Above D19814 WM+L 6309			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date Month Day Year 10 5 18	
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date Month Day Year 10 9 18	
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name H. Standow				Signature [Signature]		Date Month Day Year 10 6 18	
19. Discrepancy Indication Space profile 1229480R							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames				Signature [Signature]		Date Month Day Year 12 12 18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY



DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-18		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 WRANGELL, AK 99929							
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
				B. Transporter 1 Phone 907-258-1558			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID			
				F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No.	Type		
HM a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1	CM	40780	P
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 WMXU 6423			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature 		Date Month 10 Day 5 Year 18	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature 		Date Month 10 Day 5 Year 18	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature 		Date Month 10 Day 6 Year 18	
19. Discrepancy Indication Space profile 1229480R							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Signature 		Date Month 11 Day 29 Year 18	
Printed/Typed Name Toni Ames							

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-20		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR P.O. BOX 531 WRANGELL, AK 99929				CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929			
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
				B. Transporter 1 Phone		907-258-1558	
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID			
				F. Facility's Phone		(541) 454-2030	
11. WASTE DESCRIPTION HM a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				Containers		13. Total Quantity	
				No.	Type		
				1	CM	40630	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 WMXU 6125			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Reilly				Signature [Signature]		Date 10/5/18	
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name Shane O'Reilly				Signature [Signature]		Date 10/5/18	
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name #1 Standow				Signature [Signature]		Date 10/6/18	
19. Discrepancy Indication Space profile 1229480R							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames				Signature [Signature]		Date 11/13/18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

DESIGNATED FACILITY	TRANSPORTER	GENERATOR

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474	22. Page	23. Manifest Tracking Number 3 115885-20		
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929						
25. Transporter Company Name 5 COLUMBIARIDGE RECY. & LNDFL.			U.S. EPA ID Number ORD987173457			
26. Transporter Company Name 6			U.S. EPA ID Number			
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
32. Special Handling Instructions and Additional Information						
33. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year						
34. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year						
35. Discrepancy						
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)


NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000208474		Manifest Document No. 115885-21		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 56.4227 N & 132.3563 W WRANGELL, AK 99929 WRANGELL, AK 99929							
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		B. Transporter 1 Phone 907-258-1558			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		C. State Transporter's ID			
				D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1		CM 40960	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 wmtv 6349			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date 10/5/18	
17. Transporter 1 Acknowledgement of Receipt of Materials						Date	
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date 10/5/18	
18. Transporter 2 Acknowledgement of Receipt of Materials						Date	
Printed/Typed Name H. L. Stender				Signature [Signature]		Date 10/6/18	
19. Discrepancy Indication Space profile 122948OR							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames				Signature [Signature]		Date 11/29/18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474	22. Page 2	23. Manifest Tracking Number 115885- 2 /			
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929							
25. Transporter _____ Company Name 3 NRC ENVIRONMENTAL SERVICES				U.S. EPA ID Number CAR000030114			
26. Transporter _____ Company Name 4 UNION PACIFIC				U.S. EPA ID Number NED001792910			
GENERATOR	27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
32. Special Handling Instructions and Additional Information							
TRANSPORTER	33. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name DANIEL McMillan		Signature 		Month 11	Day 7	Year 18
	34. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name James Ruppert		Signature 		Month 11	Day 7	Year 18
DESIGNATED FACILITY	35. Discrepancy						
	36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

3

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000208474		Manifest Document No. 115885-22		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 56.4227 N & 132.3563 W WRANGELL, AK 99929 WRANGELL, AK 99929							
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
				B. Transporter 1 Phone 907-258-1558			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID			
				F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1 CM		40 840 P	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINTED SOILS				H. Handling Codes for Wastes Listed Above D19814 WMTU G 174			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date 10/5/18	
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date 10/5/18	
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name H.L. Standow				Signature [Signature]		Date 10/6/18	
19. Discrepancy Indication Space profile 1229480R							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames				Signature [Signature]		Date 11/14/18	

NON-HAZARDOUS WASTE

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474	22. Page 3	23. Manifest Tracking Number 115885-22		
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929						
25. Transporter _____ Company Name 5 COLUMBIARIDGE RECY. & LNDFL.			U.S. EPA ID Number ORD987173457			
26. Transporter _____ Company Name 6			U.S. EPA ID Number			
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
32. Special Handling Instructions and Additional Information						
33. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year						
34. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year						
35. Discrepancy						
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885- 23		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 56.4227 N & 132.3563 W WRANGELL, AK 99929 WRANGELL, AK 99929							
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		B. Transporter 1 Phone 907-258-1558			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		C. State Transporter's ID			
				D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1		CM 40 500 P	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 WMXV 6375			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane C. Zell				Signature [Signature]		Date Month Day Year 10 5 15	
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name Shane C. Zell				Signature [Signature]		Date Month Day Year 10 5 15	
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name H. Standow				Signature [Signature]		Date Month Day Year 10 6 15	
19. Discrepancy Indication Space profile 122948OR							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames				Signature [Signature]		Date Month Day Year 11 14 18	



NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY


GENERATOR

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474	22. Page 3	23. Manifest Tracking Number 115885-23		
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929						
25. Transporter _____ Company Name 5 COLUMBIA RIDGE RECY. & LNDFL.			U.S. EPA ID Number ORD987173457			
26. Transporter _____ Company Name 6			U.S. EPA ID Number			
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
32. Special Handling Instructions and Additional Information						
33. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name _____ Signature _____ Month _____ Day _____ Year _____						
34. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name _____ Signature _____ Month _____ Day _____ Year _____						
35. Discrepancy						
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-24		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR P.O. BOX 531 WRANGELL, AK 99929				CITY AND BOROUGH OF WRANGELL 58.4227 N & 132.3563 W WRANGELL, AK 99929			
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
				B. Transporter 1 Phone 907-258-1558			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID			
				F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No.	Type		
HM a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1	CM	40910	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 WMX6 G197			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Reilly				Signature 		Date Month 10 Day 5 Year 18	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature 		Date Month 10 Day 5 Year 18	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature 		Date Month 10 Day 6 Year 18	
19. Discrepancy Indication Space profile 1229480R							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Signature 		Date Month 11 Day 14 Year 18	
Printed/Typed Name Toni Ames							

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

GENERATOR

DESIGNATED FACILITY TO GENERATOR

NON-HAZARDOUS WASTE MANIFEST


115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-26		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 56.4227 N & 132.3583 W WRANGELL, AK 99929 WRANGELL, AK 99929							
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
				B. Transporter 1 Phone		907-258-1558	
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID			
				F. Facility's Phone		(541) 454-2030	
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1		CM 40700 P	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
1) 128731OR LEAD CONTAMINATED SOILS				D19814 WMXU 6215			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name				Signature		Date	
Shane O'Reilly				[Signature]		Month Day Year 10 5 18	
17. Transporter 1 Acknowledgement of Receipt of Materials						Date	
Printed/Typed Name				Signature		Month Day Year	
Shane O'Reilly				[Signature]		10 5 18	
18. Transporter 2 Acknowledgement of Receipt of Materials						Date	
Printed/Typed Name				Signature		Month Day Year	
H. Standow				[Signature]		10 6 18	
19. Discrepancy Indication Space profile 122948 OR							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name				Signature		Date	
Toni Ames				[Signature]		Month Day Year 11 14 18	

NON-HAZARDOUS WASTE



UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474	22. Page 2	23. Manifest Tracking Number 115885-26				
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929								
25. Transporter Company Name 3 NRC ENVIRONMENTAL SERVICES			U.S. EPA ID Number CAR000030114					
26. Transporter Company Name 4 UNION PACIFIC			U.S. EPA ID Number NED001792910					
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes		
		No.	Type					
32. Special Handling Instructions and Additional Information								
33. Transporter Acknowledgment of Receipt of Materials								
Printed/Typed Name Michael Emahiser		Signature 		Month 11		Day 17		Year 18
34. Transporter Acknowledgment of Receipt of Materials								
Printed/Typed Name Kobby Gideon NRCG		Signature 		Month 11		Day 7		Year 18
35. Discrepancy								
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474	22. Page	23. Manifest Tracking Number 3 115885-26				
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929								
25. Transporter Company Name 5 COLUMBIA RIDGE RECY. & LNDFL.			U.S. EPA ID Number ORD987173457					
26. Transporter Company Name 6			U.S. EPA ID Number					
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes		
		No.	Type					
32. Special Handling Instructions and Additional Information								
33. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year								
34. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year								
35. Discrepancy								
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-28		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR P.O. BOX 531 WRANGELL, AK 99929				4. Generator's Phone ()			
5. Transporter 1 Company Name NRC ALASKA LLC				6. US EPA ID Number AKR000004184		A. State Transporter's ID	
7. Transporter 2 Company Name HEKO SERVICES INC				8. US EPA ID Number WAD988470589		B. Transporter 1 Phone 907-258-1558	
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812				10. US EPA ID Number ORD987173457		C. State Transporter's ID	
						D. Transporter 2 Phone	
						E. State Facility's ID	
						F. Facility's Phone (541) 454-2030	
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
HM a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1		CM 40 860 P	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINTED SOILS				H. Handling Codes for Wastes Listed Above D19814 WMXU 6351			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature 		Date Month Day Year 10 5 18	
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name Shane O'Neill				Signature 		Date Month Day Year 10 5 18	
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name HL Stankov				Signature 		Date Month Day Year 10 6 18	
19. Discrepancy Indication Space profile 122948OR							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames				Signature 		Date Month Day Year 11 29 18	

NON-HAZARDOUS WASTE

TRANSPORTER FACILITY

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-29		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR P.O. BOX 531 WRANGELL, AK 99929				4. Generator's Phone ()			
5. Transporter 1 Company Name NRC ALASKA LLC				6. US EPA ID Number AKR000004184		A. State Transporter's ID	
7. Transporter 2 Company Name HEKO SERVICES INC				8. US EPA ID Number WAD988470589		B. Transporter 1 Phone 907-258-1558	
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812				10. US EPA ID Number ORD987173457		C. State Transporter's ID	
						D. Transporter 2 Phone	
						E. State Facility's ID	
						F. Facility's Phone (541) 454-2030	
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1 CM		40120	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 WMTL 6308			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill						Signature [Signature]	
						Date 10/5/18	
17. Transporter 1 Acknowledgement of Receipt of Materials						Date	
Printed/Typed Name Shane O'Neill						Signature [Signature]	
						Date 10/5/18	
18. Transporter 2 Acknowledgement of Receipt of Materials						Date	
Printed/Typed Name HL Standow						Signature [Signature]	
						Date 10/6/18	
19. Discrepancy Indication Space profile 122948OR							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames						Signature [Signature]	
						Date 11/13/18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

EPA Form 8700-22A (Rev. 3-05) Previous editions are obsolete.

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474	22. Page 3	23. Manifest Tracking Number 115885-29		
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929						
25. Transporter Company Name 5 COLUMBIARIDGE RECY. & LNDFL.			U.S. EPA ID Number ORD987173457			
26. Transporter Company Name 6			U.S. EPA ID Number			
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
32. Special Handling Instructions and Additional Information						
33. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year						
34. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year						
35. Discrepancy						
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type

(Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-30		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 56.4227 N & 132.3563 W WRANGELL, AK 99929 WRANGELL, AK 99929							
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		B. Transporter 1 Phone 907-258-1558			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		C. State Transporter's ID			
				D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No.	Type		
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1	CM	40780	P
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 wnto 5070			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date 10/5/18	
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date 10/5/18	
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name [Signature]				Signature [Signature]		Date 10/5/18	
19. Discrepancy Indication Space profile 1229480R							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames				Signature [Signature]		Date 12/12/18	



NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

EPA Form 8700-22A (Rev. 3-05) Previous editions are obsolete.

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474	22. Page 3	23. Manifest Tracking Number 115885-30		
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929						
25. Transporter _____ Company Name 5 COLUMBIA RIDGE RECY. & LNDFL.			U.S. EPA ID Number ORD987173457			
26. Transporter _____ Company Name 6			U.S. EPA ID Number			
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
32. Special Handling Instructions and Additional Information						
33. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year						
34. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year						
35. Discrepancy						
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-31		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 56,4227 N & 132,3563 W WRANGELL, AK 99929 56,4227 N & 132,3563 W WRANGELL, AK 99929							
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
				B. Transporter 1 Phone 907-258-1558			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID			
				F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1 CM		410990 P	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 WMXU 6029			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date 10/5/18	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date			
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date 10/5/18	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date			
Printed/Typed Name H L Standow				Signature [Signature]		Date 10/6/18	
19. Discrepancy Indication Space profile 1229480R							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Tom Ames				Signature [Signature]		Date 11/14/18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

EPA Form 8700-22A (Rev. 3-05) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR STATE (IF REQUIRED)

GENERATOR

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885- 32		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 58.4227 N & 132.3563 W WRANGELL, AK 99929 WRANGELL, AK 99929							
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
				B. Transporter 1 Phone 907-258-1558			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID			
				F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No.	Type		
a. ☒ RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1	CM	410 280	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 wmxu 0289			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill						Signature [Signature]	
						Date 10/5/18	
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name Shane O'Neill						Signature [Signature]	
						Date 10/5/18	
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name HL Standow						Signature [Signature]	
						Date 10/6/18	
19. Discrepancy Indication Space profile 1229480R							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames						Signature [Signature]	
						Date 11/14/18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number	22. Page	23. Manifest Tracking Number		
		AKR000206474	2	115885-32		
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929						
25. Transporter Company Name 3 NRC ENVIRONMENTAL SERVICES				U.S. EPA ID Number CAR000030114		
26. Transporter Company Name 4 UNION PACIFIC				U.S. EPA ID Number NED001792910		
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
		No.	Type			
32. Special Handling Instructions and Additional Information						
33. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name: James Ruppert Signature: [Signature] Month: 11 Day: 8 Year: 18						
34. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name: [Signature] NRC Signature: [Signature] Month: 11 Day: 8 Year: 18						
35. Discrepancy						
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000205474	22. Page	23. Manifest Tracking Number 3 115885-32				
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929								
25. Transporter Company Name 5 COLUMBIARIDGE RECY. & LNDFL			U.S. EPA ID Number ORD987173457					
26. Transporter Company Name 6			U.S. EPA ID Number 1					
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes		
		No.	Type					
32. Special Handling Instructions and Additional Information								
TRANSPORTER	33. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year							
	34. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year							
	35. Discrepancy							
DESIGNATED FACILITY	36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-33		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR P.O. BOX 531 WRANGELL, AK 99929 4. Generator's Phone ()				CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929			
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID		B. Transporter 1 Phone 907-258-1558	
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID		F. Facility's Phone (541) 454-2030	
11. WASTE DESCRIPTION a. ☒ RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171 b. c. d.				Containers		13. Total Quantity	14. Unit Wt./Vol.
				No.	Type		
				1	CM		
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 WMLC 6422			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature 		Date Month 10 Day 5 Year 18	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Shane O'Neill				Signature 		Date Month 10 Day 5 Year 18	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name H.L. Standow				Signature 		Date Month 10 Day 6 Year 18	
19. Discrepancy Indication Space profile 1229480R							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames				Signature 		Date Month 11 Day 14 Year 18	

NON-HAZARDOUS WASTE

TRANSPORTER FACILITY



DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

DESIGNATED FACILITY TO GENERATOR STATE (IF REQUIRED)

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type

(Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-34		2. Page 1 of 3			
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR P.O. BOX 531 WRANGELL, AK 99929				CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929					
4. Generator's Phone ()									
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID					
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		B. Transporter 1 Phone 907-258-1558					
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		C. State Transporter's ID					
				D. Transporter 2 Phone					
				E. State Facility's ID					
				F. Facility's Phone (541) 454-2030					
11. WASTE DESCRIPTION HM a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171 b. c. d.				Containers		13. Total Quantity		14. Unit Wt./Vol.	
				No. Type					
				1 0M		40610		P	
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 WMXU 6277					
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation									
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.									
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date Month Day Year 10 5 18			
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name Shane O'Neill		Signature [Signature]		Date Month Day Year 10 9 18	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name H L Standow		Signature [Signature]		Date Month Day Year 10 6 18	
19. Discrepancy Indication Space profile 1229480R									
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.									
Printed/Typed Name Toni Ames				Signature [Signature]		Date Month Day Year 11 15 18			



NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

GENERATOR

GENERATOR

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000208474		Manifest Document No. 115885-30		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 58.4227 N & 132.3563 W WRANGELL, AK 99929 4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		B. Transporter 1 Phone 907-258-1558			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		C. State Transporter's ID			
				D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1 CM		40750 P	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 unrx 6030			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill						Signature [Signature] Date 10/5/18	
17. Transporter 1 Acknowledgement of Receipt of Materials						Date	
Printed/Typed Name Shane O'Neill						Signature [Signature] Date 10/9/18	
18. Transporter 2 Acknowledgement of Receipt of Materials						Date	
Printed/Typed Name H.L. Standow						Signature [Signature] Date 10/6/18	
19. Discrepancy Indication Space profile 1229480R							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames						Signature [Signature] Date 12/3/18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474	22. Page 3	23. Manifest Tracking Number 115885- 36		
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929						
25. Transporter _____ Company Name 5 COLUMBIA RIDGE RECY. & LNDFL.			U.S. EPA ID Number ORD987173457			
26. Transporter _____ Company Name 6			U.S. EPA ID Number			
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
32. Special Handling Instructions and Additional Information						
33. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year						
34. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year						
35. Discrepancy						
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885- 37		2. Page 1 of 3			
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR P.O. BOX 531 WRANGELL, AK 99929 4. Generator's Phone ()				CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929					
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID		B. Transporter 1 Phone 907-258-1558			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID		D. Transporter 2 Phone			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID		F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION a. ☒ RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171 b. c. d.				Containers		13. Total Quantity		14. Unit Wt./Vol.	
				No. Type					
				1 CM		40820		P	
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 wmtv 6391					
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation									
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.									
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date Month 10 Day 5 Year 18			
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Shane O'Neill				Signature [Signature]		Date Month 10 Day 5 Year 18			
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name H L Standow				Signature [Signature]		Date Month 10 Day 8 Year 18			
19. Discrepancy Indication Space profile 122948 OR									
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Date					
Printed/Typed Name Toni Ames				Signature [Signature]		Date Month 11 Day 14 Year 18			

NON-HAZARDOUS WASTE

GENERATOR
TRANSPORTER
FACILITY

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type

(Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-38		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR P.O. BOX 531 WRANGELL, AK 99929				4. Generator's Phone ()			
5. Transporter 1 Company Name NRC ALASKA LLC				6. US EPA ID Number AKR000004184		A. State Transporter's ID	
7. Transporter 2 Company Name HEKO SERVICES INC				8. US EPA ID Number WAD988470589		B. Transporter 1 Phone 907-258-1558	
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812				10. US EPA ID Number ORD987173457		C. State Transporter's ID	
						D. Transporter 2 Phone	
						E. State Facility's ID	
						F. Facility's Phone (541) 454-2030	
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1 CM		40750 P	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 WMXU 6418			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature [Signature]			
				Date Month Day Year 10 5 18			
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name Shane O'Neill				Signature [Signature]			
				Date Month Day Year 10 5 18			
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name HLS tance				Signature [Signature]			
				Date Month Day Year 10 8 18			
19. Discrepancy Indication Space profile 1229480R							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames				Signature [Signature]			
				Date Month Day Year 11 27 18			

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-39		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 56.4227 N & 132.3563 W WRANGELL, AK 99929 WRANGELL, AK 99929							
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		B. Transporter 1 Phone 907-258-1558			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		C. State Transporter's ID			
				D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
HM a. ☒ RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1		CM 40980	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
1) 128731OR LEAD CONTAMINATED SOILS				D19814wmxw 6073			
15. Special Handling Instructions and Additional Information							
Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill						Signature [Signature]	
						Date Month 10 Day 5 Year 18	
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name Shane O'Neill						Signature [Signature]	
						Date Month 10 Day 5 Year 18	
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name HL Standow						Signature [Signature]	
						Date Month 10 Day 6 Year 18	
19. Discrepancy Indication Space profile 12294802							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames						Signature [Signature]	
						Date Month 11 Day 13 Year 18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY