

EPA Form 8700-22A (Rev. 3-05) Previous editions are obsolete.

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

EPA Form 8700-22A (Rev. 3-05) Previous editions are obsolete.

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-40		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR P.O. BOX 531 WRANGELL, AK 99929				4. Generator's Phone ()			
5. Transporter 1 Company Name NRC ALASKA LLC				6. US EPA ID Number AKR000004184		A. State Transporter's ID	
7. Transporter 2 Company Name HEKO SERVICES INC				8. US EPA ID Number WAD988470589		B. Transporter 1 Phone 907-258-1558	
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812				10. US EPA ID Number ORD987173457		C. State Transporter's ID	
						D. Transporter 2 Phone	
						E. State Facility's ID	
						F. Facility's Phone (541) 454-2030	
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No.	Type		
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1	CM	40640	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 WMXV 6187			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature <i>[Signature]</i>		Date Month Day Year 10 5 18	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name Shane O'Neill		Signature <i>[Signature]</i>	
						Date Month Day Year 10 5 18	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name H L Standow		Signature <i>[Signature]</i>	
						Date Month Day Year 10 10 18	
19. Discrepancy Indication Space profile 122948 OR							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames				Signature <i>[Signature]</i>		Date Month Day Year 11 14 18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

GENERATOR

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474	22. Page 2	23. Manifest Tracking Number 115885-40			
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929							
25. Transporter Company Name 3 NRC ENVIRONMENTAL SERVICES				U.S. EPA ID Number CAR000030114			
26. Transporter Company Name 4 UNION PACIFIC				U.S. EPA ID Number NED001792910			
GENERATOR	27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
32. Special Handling Instructions and Additional Information							
TRANSPORTER	33. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name: Michael Emahiser Signature: <i>[Signature]</i> Month: 11 Day: 17 Year: 18						
	34. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name: Kelley Carden NRC Signature: <i>[Signature]</i> Month: 11 Day: 17 Year: 18						
	35. Discrepancy						
	36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
DESIGNATED FACILITY							

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-41		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 WRANGELL, AK 99929							
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		B. Transporter 1 Phone 907-258-1558			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		C. State Transporter's ID			
				D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No.	Type		
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1	CM	40960	P
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above				H. Handling Codes for Wastes Listed Above			
1) 128731OR LEAD CONTAMINATED SOILS				D19814 WMTL 6305			
15. Special Handling Instructions and Additional Information							
Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date Month 10 Day 5 Year 18	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name Shane O'Neill		Signature [Signature]	
						Date Month 10 Day 5 Year 18	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name H Standow		Signature [Signature]	
						Date Month 10 Day 0 Year 18	
19. Discrepancy Indication Space profile 1229480R							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames				Signature [Signature]		Date Month 11 Day 14 Year 18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

EPA Form 8700-22A (Rev. 3-05) Previous editions are obsolete.

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number	22. Page	23. Manifest Tracking Number		
		AKR000206474	3	115885- 41		
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929						
25. Transporter _____ Company Name 5 COLUMBIARIDGE RECY. & LNDFL.				U.S. EPA ID Number ORD987173457		
26. Transporter _____ Company Name 6				U.S. EPA ID Number		
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
		No.	Type			
32. Special Handling Instructions and Additional Information						
33. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name _____ Signature _____ Month _____ Day _____ Year _____						
34. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name _____ Signature _____ Month _____ Day _____ Year _____						
35. Discrepancy						
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type

(Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.

AKR000206474

Manifest Document No.

115885-43

2. Page 1

of 3

3. Generator's Name and Mailing Address

CITY AND BOROUGH OF WRANGELL - JUNKYAR
P.O. BOX 531
WRANGELL, AK 99929

CITY AND BOROUGH OF WRANGELL
56.4227 N & 132.3563 W
WRANGELL, AK 99929

4. Generator's Phone ()

5. Transporter 1 Company Name

NRC ALASKA LLC

6.

US EPA ID Number

AKR000004184

A. State Transporter's ID

B. Transporter 1 Phone 907-258-1558

7. Transporter 2 Company Name

HEKO SERVICES INC

8.

US EPA ID Number

WAD988470589

C. State Transporter's ID

D. Transporter 2 Phone

9. Designated Facility Name and Site Address

COLUMBIA RIDGE RECY. & LNDFL
18177 CEDAR SPRINGS LANE
ARLINGTON, OR 97812

10.

US EPA ID Number

ORD987173457

E. State Facility's ID

F. Facility's Phone (541) 454-2030

11. WASTE DESCRIPTION

Containers

No.

Type

13.
Total
Quantity

14.
Unit
Wt./Vol.

HM

a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S.
(LEAD), 9, PGIII, RQ=10 ERG#171

1

CM

40650

P

b.

c.

d.

G. Additional Descriptions for Materials Listed Above

1) 128731OR LEAD CONTAMINATED SOILS

H. Handling Codes for Wastes Listed Above

D19814

WMXU 6173

15. Special Handling Instructions and Additional Information

Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation

16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Date

Printed/Typed Name

Shane O'Neill

Signature

[Signature]

Month Day Year
10 5 18

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Shane O'Neill

Signature

[Signature]

Month Day Year
10 5 18

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

HL Stendow

Signature

[Signature]

Month Day Year
10 6 18

19. Discrepancy Indication Space

profile 122948 OR

20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.

Date

Printed/Typed Name

Toni Ames

Signature

[Signature]

Month Day Year
11 29 18

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number	22. Page	23. Manifest Tracking Number		
		AKR000206474		3	115885- 43	
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929						
25. Transporter _____ Company Name 5 COLUMBIARIDGE RECY. & LNDFL.				U.S. EPA ID Number ORD987173457		
26. Transporter _____ Company Name 6				U.S. EPA ID Number		
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
		No.	Type			
32. Special Handling Instructions and Additional Information						
TRANSPORTER	33. Transporter _____ Acknowledgment of Receipt of Materials					
	Printed/Typed Name		Signature		Month	Day Year
DESIGNATED FACILITY	34. Transporter _____ Acknowledgment of Receipt of Materials					
	Printed/Typed Name		Signature		Month	Day Year
35. Discrepancy						
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885- 47		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 WRANGELL, AK 99929				4. Generator's Phone ()			
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID		B. Transporter 1 Phone 907-258-1558	
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID		F. Facility's Phone (541) 454-2030	
11. WASTE DESCRIPTION HM a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171 b. c. d.				Containers No. Type		13. Total Quantity	
				1		CM 40990	
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 wnxlv 6020			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane C. Reill				Signature <i>[Signature]</i>		Date Month Day Year 10 5 18	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name Shane C. Reill		Signature <i>[Signature]</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name H. L. Stando		Signature <i>[Signature]</i>	
19. Discrepancy Indication Space profile 1229480R				Date Month Day Year 10 6 18			
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames				Signature <i>[Signature]</i>		Date Month Day Year 11 13 18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474	22. Page 3	23. Manifest Tracking Number 115885- 47		
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929						
25. Transporter Company Name 5 COLUMBIARIDGE RECY. & LNDFL.			U.S. EPA ID Number ORD987173457			
26. Transporter Company Name 6			U.S. EPA ID Number			
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
32. Special Handling Instructions and Additional Information						
33. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year						
34. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year						
35. Discrepancy						
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.

AKR000206474

Manifest Document No.

115885-5Z

2. Page 1

of 3

3. Generator's Name and Mailing Address

CITY AND BOROUGH OF WRANGELL - JUNKYAR
P.O. BOX 531
WRANGELL, AK 99929

CITY AND BOROUGH OF WRANGELL
58.4227 N & 132.3563 W
WRANGELL, AK 99929

4. Generator's Phone ()

5. Transporter 1 Company Name

NRC ALASKA LLC

6.

US EPA ID Number

AKR000004184

A. State Transporter's ID

B. Transporter 1 Phone 907-258-1558

7. Transporter 2 Company Name

HEKO SERVICES INC

8.

US EPA ID Number

WAD988470589

C. State Transporter's ID

D. Transporter 2 Phone

9. Designated Facility Name and Site Address

COLUMBIA RIDGE RECY. & LNDFL
18177 CEDAR SPRINGS LANE
ARLINGTON, OR 97812

10.

US EPA ID Number

ORD987173457

E. State Facility's ID

F. Facility's Phone (541) 454-2030

11. WASTE DESCRIPTION

HM
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S.
(LEAD), 9, PGIII, RQ=10 ERG#171

Containers

No.

Type

13.
Total
Quantity

14.
Unit
Wt./Vol.

1

CM 40820

P

b.

c.

d.

G. Additional Descriptions for Materials Listed Above

1) 128731OR LEAD CONTAMINATED SOILS

H. Handling Codes for Wastes Listed Above

D19814

WMXU 6072

15. Special Handling Instructions and Additional Information

Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation

16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name

Shane O'Neill

Signature

[Signature]

Date

Month Day Year
10 9 18

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Shane O'Neill

Signature

[Signature]

Date

Month Day Year
10 9 18

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

HL Standow

Signature

[Signature]

Date

Month Day Year
10 16 18

19. Discrepancy Indication Space

profile 122948 OR

20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.

Printed/Typed Name

Toni Ames

Signature

[Signature]

Date

Month Day Year
11 13 18




NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number	22. Page	23. Manifest Tracking Number		
		AKR000206474		2	115885-	SZ
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929						
25. Transporter Company Name 3 NRC ENVIRONMENTAL SERVICES				U.S. EPA ID Number CAR000030114		
26. Transporter Company Name 4 UNION PACIFIC				U.S. EPA ID Number NED001792910		
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
		No.	Type			
32. Special Handling Instructions and Additional Information						
TRANSPORTER	33. Transporter Acknowledgment of Receipt of Materials					
	Printed/Typed Name Michael Emehiser		Signature 		Month 11	Day 6
TRANSPORTER	34. Transporter Acknowledgment of Receipt of Materials					
	Printed/Typed Name Re Jonathan Harris		Signature 		Month 11	Day 5
DESIGNATED FACILITY	35. Discrepancy					
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type

(Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE	NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885- 53		2. Page 1 of 3	
	3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 56.4227 N & 132.3563 W WRANGELL, AK 99929 WRANGELL, AK 99929							
	4. Generator's Phone ()							
	5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
	7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		B. Transporter 1 Phone 907-258-1558			
					C. State Transporter's ID			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		D. Transporter 2 Phone				E. State Facility's ID
				F. Facility's Phone (541) 454-2030				
GENERATOR	11. WASTE DESCRIPTION			Containers		13. Total Quantity		14. Unit Wt./Vol.
	a. HM			No.	Type			
	X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171			1	CM	40610		P
	b.							
	c.							
	d.							
	G. Additional Descriptions for Materials Listed Above			H. Handling Codes for Wastes Listed Above				
	1) 128731OR LEAD CONTAMINATED SOILS			D19814 WMTU 5094				
	15. Special Handling Instructions and Additional Information							
	Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
TRANSPORTER	16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
	Printed/Typed Name Shane O'Neill				Signature [Signature]		Date 10/5/18	
	17. Transporter 1 Acknowledgement of Receipt of Materials							
	Printed/Typed Name Shane O'Neill				Signature [Signature]		Date 10/5/18	
	18. Transporter 2 Acknowledgement of Receipt of Materials							
	Printed/Typed Name H Standow				Signature [Signature]		Date 10/8/18	
	19. Discrepancy Indication Space							
	profile 122948 OR							
	20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
	FACILITY	Printed/Typed Name Toni Dimes				Signature [Signature]		Date 11/13/18



UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number	22. Page	23. Manifest Tracking Number		
		AKR000206474	2	115885- 53		
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929						
25. Transporter _____ Company Name 3 NRC ENVIRONMENTAL SERVICES				U.S. EPA ID Number CAR000030114		
26. Transporter _____ Company Name 4 UNION PACIFIC				U.S. EPA ID Number NED001792910		
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
32. Special Handling Instructions and Additional Information						
33. Transporter _____ Acknowledgment of Receipt of Materials						
Printed/Typed Name Michael Emchitz		Signature [Signature]		Month Day Year 11 5 18		
34. Transporter _____ Acknowledgment of Receipt of Materials						
Printed/Typed Name Amy Gordon Kelly		Signature [Signature]		Month Day Year 11 5 18		
35. Discrepancy						
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474	22. Page 3	23. Manifest Tracking Number 115885-53		
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929						
25. Transporter Company Name 5 COLUMBIARIDGE RECY. & LNDFL.			U.S. EPA ID Number ORD987173457			
26. Transporter Company Name 6			U.S. EPA ID Number			
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
32. Special Handling Instructions and Additional Information						
33. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year						
34. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year						
35. Discrepancy						
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-56		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 56.4227 N & 132.3563 W WRANGELL, AK 99929 WRANGELL, AK 99929							
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		B. Transporter 1 Phone 907-258-1558			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		C. State Transporter's ID			
				D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No.	Type		
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1	CM	40550	P
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 UN3077 6118			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date Month Day Year 10 9 18	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name Shane O'Neill		Signature [Signature]	
						Date Month Day Year 10 9 18	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name H L Standow		Signature [Signature]	
						Date Month Day Year 10 8 18	
19. Discrepancy Indication Space profile 1229480R							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames				Signature [Signature]		Date Month Day Year 11 13 18	



NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

EPA Form 8700-22A (Rev. 3-05) Previous editions are obsolete.

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number	22. Page	23. Manifest Tracking Number		
		AKR000206474		3	115885-56	
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929						
25. Transporter _____ Company Name 5 COLUMBIARIDGE RECY. & LNDFL.				U.S. EPA ID Number ORD987173457		
26. Transporter _____ Company Name 6				U.S. EPA ID Number		
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
32. Special Handling Instructions and Additional Information						
33. Transporter _____ Acknowledgment of Receipt of Materials						
Printed/Typed Name				Signature		Month Day Year
34. Transporter _____ Acknowledgment of Receipt of Materials						
Printed/Typed Name				Signature		Month Day Year
35. Discrepancy						
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-60		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR P.O. BOX 531 WRANGELL, AK 99929				CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929			
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		B. Transporter 1 Phone 907-258-1558			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		C. State Transporter's ID			
				D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION HM a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				Containers		13. Total Quantity	
				No.	Type		
				1	CM	40910	P
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 wm+V 6381			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature 		Date Month 10 Day 5 Year 18	
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name Shane O'Neill				Signature 		Date Month 10 Day 5 Year 18	
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name H L Stanton				Signature 		Date Month 10 Day 6 Year 18	
19. Discrepancy Indication Space profile 1229480R							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames				Signature 		Date Month 12 Day 4 Year 18	

NON-HAZARDOUS WASTE

TRANSPORTER

FACILITY



DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.

AKR000206474

Manifest Document No.

115885-61

2. Page 1

of 3

3. Generator's Name and Mailing Address

CITY AND BOROUGH OF WRANGELL - JUNKYAR
P.O. BOX 531
WRANGELL, AK 99929

CITY AND BOROUGH OF WRANGELL
58.4227 N & 132.3583 W
WRANGELL, AK 99929

4. Generator's Phone ()

5. Transporter 1 Company Name

NRC ALASKA LLC

6.

US EPA ID Number

AKR000004184

A. State Transporter's ID

B. Transporter 1 Phone 907-258-1558

7. Transporter 2 Company Name

HEKO SERVICES INC

8.

US EPA ID Number

WAD988470589

C. State Transporter's ID

D. Transporter 2 Phone

9. Designated Facility Name and Site Address

COLUMBIA RIDGE RECY. & LNDFL
18177 CEDAR SPRINGS LANE
ARLINGTON, OR 97812

10.

US EPA ID Number

ORD987173457

E. State Facility's ID

F. Facility's Phone (541) 454-2030

11. WASTE DESCRIPTION

Containers

No.

Type

13.
Total
Quantity

14.
Unit
Wt./Vol.

a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S.
(LEAD), 9, PGIII, RQ=10 ERG#171

1

CM 40840

P

b.

c.

d.

G. Additional Descriptions for Materials Listed Above

1) 128731OR LEAD CONTAMINATED SOILS

H. Handling Codes for Wastes Listed Above

D19814

WMTU 5169

15. Special Handling Instructions and Additional Information

Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation

16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.

Printed/Typed Name

Shane O'Neill

Signature

[Signature]

Date

Month Day Year
10 5 18

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Shane O'Neill

Signature

[Signature]

Date

Month Day Year
10 5 18

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

#1 Standow

Signature

[Signature]

Date

Month Day Year
10 6 18

19. Discrepancy Indication Space

profile 122948 OR

20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.

Printed/Typed Name

Toni Ames

Signature

[Signature]

Date

Month Day Year
11 27 18



NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-62		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 56.4227 N & 132.3563 W WRANGELL, AK 99929 WRANGELL, AK 99929							
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC				6. US EPA ID Number AKR000004184		A. State Transporter's ID	
7. Transporter 2 Company Name HEKO SERVICES INC				8. US EPA ID Number WAD988470589		B. Transporter 1 Phone 907-258-1558	
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812				10. US EPA ID Number ORD987173457		C. State Transporter's ID	
						D. Transporter 2 Phone	
						E. State Facility's ID	
11. WASTE DESCRIPTION HM a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				Containers No. Type		13. Total Quantity	
				1		CM 40970 41000	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 6108 wmxc 40970			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane C. Hill				Signature [Signature]		Date Month Day Year 10 5 18	
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name Shane C. Hill				Signature [Signature]		Date Month Day Year 10 5 18	
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name H. L. Standow				Signature [Signature]		Date Month Day Year 10 6 18	
19. Discrepancy Indication Space profile 1229480R							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Tom Ames				Signature [Signature]		Date Month Day Year 11 13 18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

EPA Form 8700-22A (Rev. 3-05) Previous editions are obsolete.

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

GENERATOR

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type

(Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885- 63		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR P.O. BOX 531 WRANGELL, AK 99929				CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929			
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID		B. Transporter 1 Phone 907-258-1558	
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID		F. Facility's Phone (541) 454-2030	
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
a. ☒ RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1		CM 40800 P	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 wmtv 6119			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date Month Day Year 10 3 18	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name Shane O'Neill		Signature [Signature]	
						Date Month Day Year 10 5 18	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name H L Standow		Signature [Signature]	
						Date Month Day Year 10 6 18	
19. Discrepancy Indication Space profile 122948OR							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames				Signature [Signature]		Date Month Day Year 11 16 18	



DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000208474	22. Page 3	23. Manifest Tracking Number 115885- 63		
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929						
25. Transporter _____ Company Name 5 COLUMBIARIDGE RECY. & LNDFL.			U.S. EPA ID Number ORD987173457			
26. Transporter _____ Company Name 6			U.S. EPA ID Number			
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
32. Special Handling Instructions and Additional Information						
33. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year						
34. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year						
35. Discrepancy						
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885- 64		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR P.O. BOX 531 WRANGELL, AK 99929				CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929			
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID		B. Transporter 1 Phone 907-258-1558	
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID		F. Facility's Phone (541) 454-2030	
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1		CM 40950 P	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 wnxv 6409			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date Month 10 Day 9 Year 18	
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date Month 10 Day 5 Year 18	
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name H.L. Standow				Signature [Signature]		Date Month 10 Day 6 Year 18	
19. Discrepancy Indication Space profile 122948 OR							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames				Signature [Signature]		Date Month 11 Day 30 Year 18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

EPA Form 8700-22A (Rev. 3-05) Previous editions are obsolete.

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

EPA Form 8700-22A (Rev. 3-05) Previous editions are obsolete.

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-65		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR P.O. BOX 531 WRANGELL, AK 99929				CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929			
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID		B. Transporter 1 Phone 907-258-1558	
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID		F. Facility's Phone (541) 454-2030	
11. WASTE DESCRIPTION HM a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				Containers No. Type		13. Total Quantity	
				1		CM 40980	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 WMTU 615Z			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature <i>[Signature]</i>		Date Month Day Year 10 5 18	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name Shane O'Neill		Signature <i>[Signature]</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name HL Standow		Signature <i>[Signature]</i>	
19. Discrepancy Indication Space profile 1229480R							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Printed/Typed Name Toni Ames		Signature <i>[Signature]</i>	
						Date Month Day Year 11 29 18	



UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474	22. Page	23. Manifest Tracking Number 2 115885-65				
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929								
25. Transporter Company Name 3 NRC ENVIRONMENTAL SERVICES			U.S. EPA ID Number CAR000030114					
26. Transporter Company Name 4 UNION PACIFIC			U.S. EPA ID Number NED001792910					
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes		
		No.	Type					
32. Special Handling Instructions and Additional Information								
33. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name: <u>Mrc Jonathan Harris</u> Signature: <u>[Signature]</u> Month: <u>11</u> Day: <u>5</u> Year: <u>18</u>								
34. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name: <u>Artemio Hernandez</u> Signature: <u>[Signature]</u> Month: <u>11</u> Day: <u>5</u> Year: <u>18</u>								
35. Discrepancy								
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474	22. Page	23. Manifest Tracking Number 3 115885- 65				
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929								
25. Transporter _____ Company Name 5 COLUMBIA RIDGE RECY. & LNDFL.			U.S. EPA ID Number ORD987173457					
26. Transporter _____ Company Name 6			U.S. EPA ID Number					
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes		
		No.	Type					
32. Special Handling Instructions and Additional Information								
TRANSPORTER	33. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year							
	34. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year							
DESIGNATED FACILITY	35. Discrepancy							
	36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000208474		Manifest Document No. 115885-60	2. Page 1 of 3
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 56.4227 N & 132.3563 W WRANGELL, AK 99929 WRANGELL, AK 99929					
4. Generator's Phone ()					
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID	
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		B. Transporter 1 Phone 907-258-1558	
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (541) 454-2030	
11. WASTE DESCRIPTION			Containers		13. Total Quantity
			No.	Type	14. Unit Wt./Vol.
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171			1	CM	40900 P
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS			H. Handling Codes for Wastes Listed Above D19814 WMTU 0353		
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name Shane O'Neill				Signature [Signature] Date 10/5/18	
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name Shane O'Neill				Signature [Signature] Date 10/5/18	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name H L Standow				Signature [Signature] Date 10/6/18	
19. Discrepancy Indication Space profile 122948OR					
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name Tom Ames				Signature [Signature] Date 11/13/18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

GENERATOR

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474	22. Page	23. Manifest Tracking Number 3 115885-60		
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929						
25. Transporter _____ Company Name 5 COLUMBIARIDGE RECY. & LNDFL.		U.S. EPA ID Number ORD987173457				
26. Transporter _____ Company Name 6		U.S. EPA ID Number				
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
32. Special Handling Instructions and Additional Information						
33. Transporter _____ Acknowledgment of Receipt of Materials						
Printed/Typed Name		Signature			Month	Day Year
34. Transporter _____ Acknowledgment of Receipt of Materials						
Printed/Typed Name		Signature			Month	Day Year
35. Discrepancy						
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-67		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR P.O. BOX 531 WRANGELL, AK 99929				4. Generator's Phone ()			
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID		B. Transporter 1 Phone 907-258-1558	
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID		F. Facility's Phone (541) 454-2030	
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1		CM 41000 P	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 wnxv 6009			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date Month Day Year 10 5 18	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name Shane O'Neill		Signature [Signature]	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name H L Stenow		Signature [Signature]	
19. Discrepancy Indication Space profile 1229480R						Date Month Day Year 10 6 18	
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Printed/Typed Name Toni Ames		Signature [Signature]	
						Date Month Day Year 12 11 18	



DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

DESIGNATED FACILITY TO GENERATOR STATE (IF REQUIRED)

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type

(Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-68		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR P.O. BOX 531 WRANGELL, AK 99929				CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929			
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID		B. Transporter 1 Phone 907-258-1558	
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID		F. Facility's Phone (541) 454-2030	
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1		CM 40970 P	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 wmtv 6189			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date 10/5/18	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name Shane O'Neill		Signature [Signature]	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name H L S Andrew		Signature [Signature]	
19. Discrepancy Indication Space profile 122948 OR							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Printed/Typed Name Toni Ames		Signature [Signature]	
						Date 11/13/18	



UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000208474	22. Page 2	23. Manifest Tracking Number 115885- 68		
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929						
25. Transporter _____ Company Name 3 NRC ENVIRONMENTAL SERVICES			U.S. EPA ID Number CAR000030114			
26. Transporter _____ Company Name 4 UNION PACIFIC			U.S. EPA ID Number NED001792910			
27a. HM	27b. U.S. DOT Description (Including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
		No.	Type			
32. Special Handling Instructions and Additional Information						
33. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name <i>Dana McMillian</i> Signature <i>[Signature]</i> Month <i>11</i> Day <i>12</i> Year <i>18</i>						
34. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name <i>Michael Encher</i> Signature <i>[Signature]</i> Month <i>11</i> Day <i>12</i> Year <i>18</i>						
35. Discrepancy						
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474	22. Page 3	23. Manifest Tracking Number 115885-68				
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929								
25. Transporter Company Name 5 COLUMBIARIDGE RECY. & LNDFL.			U.S. EPA ID Number ORD987173457					
26. Transporter Company Name 6			U.S. EPA ID Number					
GENERATOR	27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes	
32. Special Handling Instructions and Additional Information JANUARY 16/11/11. 11.00								
TRANSPORTER	33. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name		Signature		Month Day Year 11 2 11			
	34. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name		Signature		Month Day Year			
DESIGNATED FACILITY	35. Discrepancy							
	36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-73		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 56 4227 N & 132.3563 W WRANGELL, AK 99929 WRANGELL, AK 99929							
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
				B. Transporter 1 Phone 907-258-1558			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID			
				F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No.	Type		
HM a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1	CM	40890	P
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 wmtu 6341			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
						Date	
Printed/Typed Name Shane O'Neill				Signature [Signature]		Month 10 Day 5 Year 18	
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name Shane O'Neill				Signature [Signature]		Month 10 Day 5 Year 18	
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name H L Standow				Signature [Signature]		Month 10 Day 6 Year 18	
19. Discrepancy Indication Space profile 122948OR							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
						Date	
Printed/Typed Name Toni Ames				Signature [Signature]		Month 11 Day 13 Year 18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-74		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 56.4227 N & 132.3563 W WRANGELL, AK 99929 WRANGELL, AK 99929							
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		B. Transporter 1 Phone 907-258-1558			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		C. State Transporter's ID			
				D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No.	Type		
HM a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1	CM	40740	P
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 wmrv 6172			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date Month Day Year 10 5 18	
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date Month Day Year 10 5 18	
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name H L Standow				Signature [Signature]		Date Month Day Year 10 6 18	
19. Discrepancy Indication Space profile 122948OR							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames				Signature [Signature]		Date Month Day Year 11 27 18	

EPA Form 8700-22A (Rev. 3-05) Previous editions are obsolete.

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474	22. Page 3	23. Manifest Tracking Number 115885-74		
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929						
25. Transporter _____ Company Name 5 COLUMBIARIDGE RECY. & LNDFL.			U.S. EPA ID Number ORD987173457			
26. Transporter _____ Company Name 6			U.S. EPA ID Number			
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
32. Special Handling Instructions and Additional Information						
TRANSPORTER	33. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year					
	34. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year					
DESIGNATED FACILITY	35. Discrepancy					
	36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)					

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-75		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR P.O. BOX 531 WRANGELL, AK 99929				CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929			
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID		B. Transporter 1 Phone 907-258-1558	
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID		F. Facility's Phone (541) 454-2030	
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1 CM		409 80 P	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above 19814 wmtv 6115			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature		Date Month Day Year 10 5 18	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature		Date Month Day Year 10 9 18	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date Month Day Year 10 8 18	
19. Discrepancy Indication Space profile 122948 OR							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Signature		Date Month Day Year 11 29 18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474	22. Page 2	23. Manifest Tracking Number 115885- 75				
24. Generator's Name CITY AND BOROUGH OF WRANGELL 58.4227 N & 132.3563 W WRANGELL, AK 99929								
25. Transporter _____ Company Name 3 NRC ENVIRONMENTAL SERVICES			U.S. EPA ID Number CAR000030114					
26. Transporter _____ Company Name 4 UNION PACIFIC			U.S. EPA ID Number NED001792910					
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes		
		No.	Type					
32. Special Handling Instructions and Additional Information								
TRANSPORTER	33. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name <u>Golden Kelly</u> Signature <u>[Signature]</u> Month <u>11</u> Day <u>02</u> Year <u>18</u>							
	34. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name <u>Michael Ennahrner</u> Signature <u>[Signature]</u> Month <u>11</u> Day <u>02</u> Year <u>18</u>							
DESIGNATED FACILITY	35. Discrepancy							
	36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)


NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-77		2. Page 1 of 3			
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 WRANGELL, AK 99929				4. Generator's Phone ()					
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID		B. Transporter 1 Phone 907-258-1558			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID		D. Transporter 2 Phone			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID		F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171 b. c. d.				Containers		13. Total Quantity		14. Unit Wt./Vol.	
				No. Type					
				1 CM		40430		P	
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 wmxu 6155					
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation									
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.									
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date Month 10 Day 9 Year 18			
17. Transporter 1 Acknowledgement of Receipt of Materials				Date					
Printed/Typed Name Shane O'Neill				Signature [Signature]		Month 10 Day 9 Year 18			
18. Transporter 2 Acknowledgement of Receipt of Materials				Date					
Printed/Typed Name HL Standow				Signature [Signature]		Month 10 Day 16 Year 18			
19. Discrepancy Indication Space profile 1229480R									
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.									
Printed/Typed Name Toni Ames				Signature [Signature]		Date Month 12 Day 12 Year 18			

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number	22. Page	23. Manifest Tracking Number		
		AKR000206474		2	115885- 77	
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929						
25. Transporter _____ Company Name 3 NRC ENVIRONMENTAL SERVICES				U.S. EPA ID Number CAR000030114		
26. Transporter _____ Company Name 4 UNION PACIFIC				U.S. EPA ID Number NED001792910		
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
		No.	Type			
32. Special Handling Instructions and Additional Information						
TRANSPORTER	33. Transporter _____ Acknowledgment of Receipt of Materials					
	Printed/Typed Name NRC Jonathan Harris		Signature 		Month Day Year 11/02/18	
DESIGNATED FACILITY	34. Transporter _____ Acknowledgment of Receipt of Materials					
	Printed/Typed Name Michael Emahiser		Signature 		Month Day Year 11/02/18	
35. Discrepancy						
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474		22. Page 3	23. Manifest Tracking Number 115885- 77				
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929									
25. Transporter _____ Company Name 5 COLUMBIA RIDGE RECY. & LNDFL.				U.S. EPA ID Number ORD987173457					
26. Transporter _____ Company Name 6				U.S. EPA ID Number					
GENERATOR	27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))		28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes	
32. Special Handling Instructions and Additional Information									
TRANSPORTER	33. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name _____ Signature _____ Month _____ Day _____ Year _____								
	34. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name _____ Signature _____ Month _____ Day _____ Year _____								
DESIGNATED FACILITY	35. Discrepancy								
	36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-78		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR P.O. BOX 531 WRANGELL, AK 99929				4. Generator's Phone ()			
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID		B. Transporter 1 Phone 907-258-1558	
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID		D. Transporter 2 Phone	
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID		F. Facility's Phone (541) 454-2030	
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No. Type		14. Unit Wt./Vol.	
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1		CM 40970 P	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 mmxv 5420			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature		Date Month Day Year 10 5 18	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature		Date Month Day Year 10 5 18	
Printed/Typed Name Shane O'Neill				Signature		Date Month Day Year 10 5 18	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date Month Day Year 10 6 18	
Printed/Typed Name Henry Standow				Signature		Date Month Day Year 10 6 18	
19. Discrepancy Indication Space profile 1229480R							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames				Signature		Date Month Day Year 11 15 18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

GENERATOR

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885- 8/		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 56.4227 N & 132.3563 W WRANGELL, AK 99929 WRANGELL, AK 99929							
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
				B. Transporter 1 Phone 907-258-1558			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		C. State Transporter's ID			
				D. Transporter 2 Phone			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		E. State Facility's ID			
				F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No.	Type		
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1	CM	40720	P
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 wm+U 6377			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date 10/9/18	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature [Signature]		Date 10/9/18	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature [Signature]		Date 10/6/18	
19. Discrepancy Indication Space profile 1229480R							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.				Date			
Printed/Typed Name Toni Ames				Signature [Signature]		Date 11/14/18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474	22. Page	23. Manifest Tracking Number 3 115885- 81		
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929						
25. Transporter _____ Company Name 5 COLUMBIA RIDGE RECY. & LNDFL.			U.S. EPA ID Number ORD987173457			
26. Transporter _____ Company Name 6			U.S. EPA ID Number			
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
32. Special Handling Instructions and Additional Information						
TRANSPORTER	33. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name		Signature		Month	Day Year
TRANSPORTER	34. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name		Signature		Month	Day Year
DESIGNATED FACILITY	35. Discrepancy					
DESIGNATED FACILITY	36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)					

GENERATOR

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000206474		Manifest Document No. 115885-82		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 56.4227 N & 132.3563 W WRANGELL, AK 99929 56.4227 N & 132.3563 W WRANGELL, AK 99929							
4. Generator's Phone ()							
5. Transporter 1 Company Name NRC ALASKA LLC		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
7. Transporter 2 Company Name HEKO SERVICES INC		8. US EPA ID Number WAD988470589		B. Transporter 1 Phone 907-256-1556			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		C. State Transporter's ID			
				D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION HM a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				Containers No. Type		13. Total Quantity	
				14. Unit Wt./Vol.			
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 unxk 6220			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature <i>[Signature]</i>		Date Month Day Year 10 5 18	
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name Shane O'Neill				Signature <i>[Signature]</i>		Date Month Day Year 10 5 18	
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name Henry Standow				Signature <i>[Signature]</i>		Date Month Day Year 10 6 18	
19. Discrepancy Indication Space profile 122948OR							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Toni Ames				Signature <i>[Signature]</i>		Date Month Day Year 11 30 18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

GENERATOR

NON-HAZARDOUS WASTE MANIFEST

115885-6-3408DS

Please print or type (Form designed for use on elite (12 pica) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. AKR000208474		Manifest Document No. 115885-83		2. Page 1 of 3	
3. Generator's Name and Mailing Address CITY AND BOROUGH OF WRANGELL - JUNKYAR CITY AND BOROUGH OF WRANGELL P.O. BOX 531 WRANGELL, AK 99929							
4. Generator's Phone ()		6. US EPA ID Number AKR000004184		A. State Transporter's ID			
5. Transporter 1 Company Name NRC ALASKA LLC		7. Transporter 2 Company Name HEKO SERVICES INC		B. Transporter 1 Phone 907-258-1558			
9. Designated Facility Name and Site Address COLUMBIA RIDGE RECY. & LNDFL 18177 CEDAR SPRINGS LANE ARLINGTON, OR 97812		10. US EPA ID Number ORD987173457		C. State Transporter's ID			
				D. Transporter 2 Phone			
				E. State Facility's ID			
				F. Facility's Phone (541) 454-2030			
11. WASTE DESCRIPTION				Containers		13. Total Quantity	
				No. Type		Unit Wt./Vol.	
a. X RQ, UN3077, Environmentally Hazardous Substances, Solid, N.O.S. (LEAD), 9, PGIII, RQ=10 ERG#171				1 CM		40970	
b.							
c.							
d.							
G. Additional Descriptions for Materials Listed Above 1) 128731OR LEAD CONTAMINATED SOILS				H. Handling Codes for Wastes Listed Above D19814 wmxUGZ75			
15. Special Handling Instructions and Additional Information Shipper's Certification: This is to certify that the above-named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation							
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.							
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date Month 10 Day 5 Year 18	
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name Shane O'Neill				Signature [Signature]		Date Month 10 Day 5 Year 18	
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name HL Standow				Signature [Signature]		Date Month 10 Day 6 Year 18	
19. Discrepancy Indication Space profile 122948 OR							
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.							
Printed/Typed Name Tom Ames				Signature [Signature]		Date Month 11 Day 14 Year 18	

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number AKR000206474	22. Page 3	23. Manifest Tracking Number 115885-83		
24. Generator's Name CITY AND BOROUGH OF WRANGELL 56.4227 N & 132.3563 W WRANGELL, AK 99929						
25. Transporter <u>5</u> Company Name COLUMBIARIDGE RECY. & LNDFL.				U.S. EPA ID Number ORD987173457		
26. Transporter <u>6</u> Company Name				U.S. EPA ID Number		
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
32. Special Handling Instructions and Additional Information						
33. Transporter <u>6</u> Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year						
34. Transporter <u>6</u> Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year						
35. Discrepancy						
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						