



**Liberty Mutual Insurance**

Equipment Breakdown  
14900 Interurban Ave S Ste 142  
Tukwila, WA 98168-4666  
Phone: 253-719-1107  
[russell.bartlett@libertymutual.com](mailto:russell.bartlett@libertymutual.com)

02/14/2018

Amber Al-Haddad  
City of Wrangell  
PO Box 531  
Wrangell, AK 99929-0531  
[aal-haddad@wrangell.com](mailto:aal-haddad@wrangell.com)

RE: **Certificate Inspection - Confirmation**  
Public Safety Bldg  
431 Zimovia -Boiler Room  
Wrangell, AK 99929  
*Policy No. YB2L9L465929017*  
*JO Location No. 149299*

Dear Amber Al-Haddad:

Liberty Mutual performed a boiler and pressure vessel certificate inspection on February 14, 2018 at the above location. Enclosed you will find the report for the equipment inspected.

No code violations were discovered and no recommendations are being submitted as a result of this inspection. As required by the State of Alaska, a report of inspection has been submitted to them for each object inspected to allow the issuance of a certificate of inspection.

If you have any questions or comments regarding this inspection, please contact me at 253-719-1107 or via e-mail at [russell.bartlett@libertymutual.com](mailto:russell.bartlett@libertymutual.com).

Sincerely,

*Russell Bartlett*

Russell Bartlett  
Engineering Specialist

Information contained in this report is based on the conditions and practices observed at the time of the visit and/or information provided by personnel at that location. The inspection and/or any recommendations contained in this report are designed to assist the customer in the management of their own activities and should not be construed as legal advice. The report may not list all unsafe conditions and practices; others may exist. The customer is responsible for making changes in the operations, procedures, or for implementing any recommendations. By issuance of the report, neither the Insurance Company nor any of its employees makes any warranty, express or implied, concerning the contents of this report. Further, neither the Insurance Company nor any of its employees shall be liable in any manner (other than liability that may be expressed in any policy of insurance that may be issued by the Company) for personal injury or property damage or loss of any kind arising from or connected with this inspection or failure to inspect. This report does not amend, alter or otherwise affect, the provisions or coverage of any insurance policy. This report does not represent the status of coverage for any particular claim or loss under any such policy.



**CERTIFICATE INSPECTION REPORT**  
**For**

Public Safety Bldg  
431 Zimovia -Boiler Room  
Wrangell, AK 99929

**Date Visited:** February 14, 2018

**Inspected by:** Russell Bartlett  
Engineering Specialist

**Policy Number:** YB2L9L465929017

**JO Location** 149299  
**Number:**

**Scope of Inspection:**

A boiler and pressure vessel certificate inspection was performed at the above location on February 14, 2018, for the purpose of issuing the Certificates of Inspection as required by the State of Alaska. The following objects were inspected:

Manufacturer	Type of Object	Jurisdictional Number	NB Number	Type of Inspection (Internal or External)	Certificate Issued? (Yes or No)
Manchester	Air Tank	130518AK	1280701	External Cert	Yes
Precision	Elect Blr	120548AK	19170	External Cert	Yes

Information contained in this report is based on the conditions and practices observed at the time of the visit and/or information provided by personnel at that location. The inspection and/or any recommendations contained in this report are designed to assist the customer in the management of their own activities and should not be construed as legal advice. The report may not list all unsafe conditions and practices; others may exist. The customer is responsible for making changes in the operations, procedures, or for implementing any recommendations. By issuance of the report, neither the Insurance Company nor any of its employees makes any warranty, express or implied, concerning the contents of this report. Further, neither the Insurance Company nor any of its employees shall be liable in any manner (other than liability that may be expressed in any policy of insurance that may be issued by the Company) for personal injury or property damage or loss of any kind arising from or connected with this inspection or failure to inspect. This report does not amend, alter or otherwise affect, the provisions or coverage of any insurance policy. This report does not represent the status of coverage for any particular claim or loss under any such policy.